

HISTORIC AND DESIGN REVIEW COMMISSION

January 20, 2016

Agenda Item No: 24

HDRC CASE NO: 2016-016
ADDRESS: 304 E TRAVIS ST
LEGAL DESCRIPTION: NCB 415 BLK 18 LOT A-7, A- 8, A-9, P-100, P-101 & P-102
ZONING: D HE
CITY COUNCIL DIST.: 1
LANDMARK: St Anthony Hotel
APPLICANT: Brandon Raney
OWNER: BCL St. Anthony ML, LP
TYPE OF WORK: Tax Certification
REQUEST:

The applicant is requesting Historic Tax Certification for the property at 304 E Travis.

APPLICABLE CITATIONS:

UDC Section 35-618. Tax Exemption Qualifications:

(d) Certification.

(1)Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's documentation for recommendation of either approval or disapproval of the application for exemption.

FINDINGS:


- a. The scope of work consists of various rehabilitative measures to the exterior of the structure including the cleaning and repair of the masonry façade, maintenance and repair to roofing, gutters and downspouts, third floor alley window rehabilitation and replacement, garage ventilation, exterior fire escape repair, exterior painting and caulking, various street level entrance improvements and terrace improvements; all of which have been previously approved and completed.
- b. The applicant has met all of the requirements for Historic Tax Certification outlined in UDC Section 35-618 and has provided evidence to that effect to the Historic Preservation Officer including photos and invoices.

RECOMMENDATION:

Staff recommends approval as submitted based on findings a and b.

CASE MANAGER:

Edward Hall




Flex Viewer

Powered by ArcGIS Server

Printed: Jan 07, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.



December 9, 2015

**118 Broadway, Suite 519
San Antonio, Texas 78205**

**Ms. Shanon Miller, AICP
Director of the Office of Historic Preservation
Development and Business Services Center
1901 South Alamo Street
San Antonio, Texas 78204**

RE: St. Anthony Hotel Tax Certification Application

Dear Ms. Miller and OHP Staff Members,

Please find attached our Tax Certification Application and supporting material for the St. Anthony Hotel Historic Rehabilitation Project. As you may recall, the exterior rehabilitation work for the project was fairly limited, with the vast majority of the project scope contained within the hotel's interior. As a result, the project received administrative approval on January 22, 2013.

Project Schedule: Construction commenced in May of 2013 and was substantially completed on November 14, 2015. We appreciate all the assistance and guidance OHP provided to help make this a successful rehabilitation of a significant San Antonio landmark.

To assist you the Certification Application, we have provided the following attachments:

- (1) Tax Certification Form;
- (2) Scope Summary of the Exterior Rehabilitation;
- (3) The NPS Part 2 Description of Rehabilitation for more detailed information of rehabilitation of each significant item within the scope of the exterior and interior rehabilitation work;
- (4) Historic photographs of the hotel;
- (5) Photographs of the hotel taken just prior to commencement of the work;
- (6) Selective drawing sheets from the construction documents, including plans, elevations and significant details;
- (7) Contractor's Schedule of Values for cost of the rehabilitation work.
- (8) And a CD-ROM disk with electronic copies of the above listed materials.

Thank you in advance for your kind consideration of the project. Please feel free to contact me should you have any questions regarding the hotel rehabilitation project.

Best regards,

Scott Carpenter, Registered Architect, LEED AP [BD+C]
Principal, Seventh Generation Design, Inc.

CC: Project File

Attachments:

- Materials listed above.

St. Anthony Hotel
Scope Summary of Exterior Rehabilitation

January 22, 2013

The following summarizes the scope of exterior rehabilitation included in the accompanying architectural drawings (Permit Set, dated January 18, 2013), historic preservation specifications and photographs of existing conditions:

I. General Exterior Façade Rehabilitation, Maintenance and Repair

- A. Masonry cleaning and repair – coated and uncoated brick
- B. Roofing, gutters and downspout maintenance and repair
- C. Third floor alley window rehabilitation and replacement
- D. Garage window rehabilitation and replacement
- E. Garage ventilation at alley elevation through existing window openings
- F. Exterior fire escape repair and repainting
- G. General exterior painting, caulking, etc.

II. Travis Street Entrance

- A. Reconstitution of exterior loggia at Travis to re-establish relationship with park
- B. Removal of non-historic revolving door and replacement with new door

III. Navarro Street Entrance

- A. Replacement of non-historic storefront entrance with new storefront entrance
- B. Introduction of accessible entry and elevator within existing retail space

IV. Parking Garage Entry and Valet Area

- A. Modification of traffic management and guest arrival
- B. Introduction of removal bollards at Travis Street garage entry

V. Pool Terrace Rehabilitation & Modifications

- A. Replacement of perimeter fencing with glass guardrail system
- B. Rehabilitation of roof deck and waterproofing; new deck finish material
- C. New pool cabanas, shade structures, bar and event space

VI. Starlight Terrace Rehabilitation & Modifications


- A. Replacement of perimeter fencing with glass guardrail system
- B. Rehabilitation of roof deck and waterproofing; new deck finish material
- C. Removal of non-historic bar, restrooms and storage room
- D. New bar, event space and event support spaces
- E. Rehabilitation of existing wood windows

JEFFERSON STREET

NAVARRO STREET

ALLEY

TRAVIS STREET



ST. ANTHONY HOTEL RENOVATION
 PHOTO KEY PLAN - EXISTING 1ST FLOOR



003

004

005

006

009

010

008

019

016

015

018

017

014

013

011

012

002

001

034

031

033

035

029

027

030

032

036

037

038

040

044

042

041

145

149

146

151

158

161

159

162

171

172

170

173

178

189

181

182

183

184

190

191

192

195

194

193

199

200

202

196

197

198

308

307

318

317

294

140

291

293

292

293

298

297

299

295

296

300

157

160

175

168

173

174

176

179

164

163

165

166

167

188

187

096

106

105

197

198

104

103

331

329

332

138

130

131

124

123

117

118

119

110

102

101

310

309

315

137

132

122

129

128

126

121

339

108

099

097

352

316

311

136

340

127

135

134

133

350

098

095

099

351

354

353

313

314

039

SLOPE

039

DN

036

037

031

033

035

029

027

030

028

020

021

022

024

023

026


025

014

029


027

030




ST. ANTHONY HOTEL RENOVATION
 PHOTO KEY PLAN - EXISTING MEZZANINE LEVEL





ST. ANTHONY HOTEL RENOVATION
PHOTO KEY PLAN - EXISTING THIRD LEVEL





ST. ANTHONY HOTEL RENOVATION
PHOTO KEY PLAN - EXISTING SIXTH LEVEL





ST. ANTHONY HOTEL RENOVATION
PHOTO KEY PLAN - EXISTING TENTH FLOOR





Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Northeast corner near intersection of Travis & Jefferson Streets
Description: General exterior view of building
Date: September 2012

Photograph No.
SAH-001



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Northeast corner as viewed from one half block east on Travis Street
Description: General exterior view of building
Date: September 2012

Photograph No.
SAH-002



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Southeast corner viewed from one half block south on Jefferson Street
Description: General exterior view of building
Date: September 2012

Photograph No.

SAH-003



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Jefferson Street facade, looking northwest
Description: Damaged Jefferson Street canopy and deteriorated wood windows in garage
Date: September 2012

Photograph No.


SAH-004



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of garage from Jefferson Street looking northwest
Description: Exterior fire escape from sixth floor pool terrace and stained masonry
Date: September 2012

Photograph No.

SAH-005



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of Tower 3 from Jefferson Street looking northwest
Description: Exterior fire escape from Tower 3 to alley
Date: September 2012

Photograph No.


SAH-006



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of Tower 3 from Jefferson Street at alley, looking west
Description: Exterior fire escape, stained masonry, and deteriorated concrete loading dock
Date: September 2012

Photograph No.

SAH-007



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade between Tower 1 & 2 at alley, looking east-northeast
Description: Stained and dirty brick masonry, damaged downspouts, and mechanical piping
Date: September 2012

Photograph No.

SAH-008



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of Tower 3 at alley, looking west-northwest
Description: Deteriorated concrete loading dock and stairs & dirty and stained masonry
Date: September 2012

Photograph No.

SAH-009



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of Tower 2 at alley, looking north
Description: Dirty and stained masonry with damage due to dumpsters
Date: September 2012

Photograph No.

SAH-010



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Northwest corner as viewed from one half block west on Travis Street
Description: General exterior view of building
Date: September 2012

Photograph No.

SAH-011



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Northwest corner near intersection of Travis & Navarro Streets
Description: General exterior view of building
Date: September 2012

Photograph No.

SAH-012



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: West facade of Tower 1 looking south southeast on Navarro Street
Description: General exterior view of building, west arcade and terrace
Date: September 2012

Photograph No.

SAH-013



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: West facade of Tower 1 looking southeast on Navarro Street
Description: General exterior view of building, west arcade and terrace
Date: September 2012

Photograph No.

SAH-014



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Southwest corner and South facade viewed from Navarro Street
Description: General exterior view of building, west arcade, terrace & fire escapes
Date: September 2012

Photograph No.

SAH-015



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Southwest corner viewed from one half block south on Navarro Street
Description: General exterior view of building, west arcade, and terrace
Date: September 2012

Photograph No.

SAH-016



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: West facade at Navarro Street entrance, looking east
Description: Navarro Street arcade and terrace with non-historic glazing system
Date: September 2012

Photograph No.

SAH-017



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: West facade at restaurant street entrance, looking east
Description: Navarro Street arcade and terrace with non-historic glazing system
Date: September 2012

Photograph No.

SAH-018



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: South facade of west arcade and terrace at Navarro Street and alley
Description: Non-historic glazing system at terrace to be removed
Date: September 2012

Photograph No.

SAH-019



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: West facade of west arcade looking north
Description: Cast stone, brick masonry, and concrete requiring cleaning and repair
Date: September 2012

Photograph No.

SAH-020



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: East wall of west arcade, looking northeast
Description: Navarro Street entry door & arched transom to restaurant
Date: September 2012

Photograph No.


SAH-021



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: East wall of west arcade, looking south
Description: Arched restaurant windows, entry door and sconces
Date: September 2012


Photograph No.

SAH-022



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Navarro Street entrance, looking east
Description: Non-historic door and glazing system to be replaced
Date: September 2012

Photograph No.
SAH-023



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Navarro Street entrance, looking northeast
Description: Cast stone and brick masonry requiring general cleaning and repair
Date: September 2012

Photograph No.
SAH-024



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Navarro Street entrance and arcade, looking southeast
Description: Cast stone and brick masonry requiring general cleaning and repair
Date: September 2012

Photograph No.

SAH-025



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Navarro Street entrance, looking east
Description: Non-historic door and glazing system to be replaced
Date: September 2012

Photograph No.

SAH-026



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street entrance and canopy, looking south
Description: General view of building's primary entrance and loading zone
Date: September 2012

Photograph No.
SAH-027



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Travis Street entrance
Description: Vestibule vault, revolving door, historic handrail and carpet on steps
Date: September 2012

Photograph No.
SAH-028



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street entrance and canopy, looking southwest
Description: General view of building's primary entrance and loading zone
Date: September 2012

Photograph No.
SAH-029



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street entrance and canopy, looking southeast
Description: General view of building's primary entrance and loading zone
Date: September 2012

Photograph No.
SAH-030



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street garage entrance and canopy
Description: General view of vehicular entrance and guest arrival area
Date: September 2012

Photograph No.
SAH-031



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street garage entrance & canopy, looking west
Description: Vehicular entrance with canopy and existing streetscape elements
Date: September 2012

Photograph No.
SAH-032



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street garage entry & canopy, looking southeast
Description: Vehicular entrance and existing streetscape elements
Date: September 2012

Photograph No.
SAH-033



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street garage entry & canopy, looking southwest
Description: Vehicular entrance and existing streetscape elements
Date: September 2012

Photograph No.
SAH-034



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: North facade at Travis Street
Description: Fabric dome canopies, cast stone columns and wrought iron railings
Date: September 2012

Photograph No.

SAH-035



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Travis Street garage entry, looking southwest
Description: Guest arrival area and motor lobby entry
Date: September 2012

Photograph No.

SAH-036



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Travis Street garage entry, looking southeast
Description: Valet station and guest arrival area
Date: September 2012

Photograph No.
SAH-037



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking south
Description: Guest arrival area and valet queuing lanes
Date: September 2012

Photograph No.
SAH-038



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking east
Description: Fountain feature at valet station and waiting area
Date: September 2012

Photograph No.

SAH-039



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking northwest
Description: Fountain feature at valet station and waiting area
Date: September 2012

Photograph No.

SAH-040



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking east
Description: Looking up concrete spiral ramp
Date: September 2012

Photograph No.

SAH-041



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Second floor garage interior, looking west
Description: Looking down concrete spiral ramp
Date: September 2012

Photograph No.

SAH-042



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking north
Description: Guest arrival area and valet queuing lanes
Date: September 2012

Photograph No.
SAH-043



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor garage interior, looking east
Description: Jefferson Street vehicular entrance/exit
Date: September 2012

Photograph No.
SAH-044



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical interior view of parking garage
Description: Concrete & masonry cleaning, lighting upgrades, & ventilation required
Date: September 2012

Photograph No.


SAH-045



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical interior view of parking garage
Description: Concrete & masonry cleaning, lighting upgrades, & ventilation required
Date: September 2012

Photograph No.

SAH-046



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical interior view of parking garage
Description: Concrete & masonry cleaning, lighting upgrades, & ventilation required
Date: September 2012

Photograph No.

SAH-047



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical interior view of parking garage
Description: Concrete & masonry cleaning, window sash replacement required
Date: September 2012

Photograph No.

SAH-048



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace as seen from 8th floor, looking east-southeast
Description: General view of pool terrace, perimeter fencing and canopy structures
Date: September 2012

Photograph No.

SAH-049



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking east-southeast
Description: Cracked and spawling decking material & inappropriate fencing
Date: September 2012

Photograph No.

SAH-050



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking southeast toward Tower of the Am.
Description: Cracked and spawling decking material & inappropriate fencing
Date: September 2012

Photograph No.

SAH-051



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking south toward Casino Club Bldg.
Description: Cracked and spawling decking material & inappropriate fencing
Date: September 2012

Photograph No.


SAH-052



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking northeast toward Tower 4
Description: Cracked and spawling decking material & stained and dirty masonry
Date: September 2012

Photograph No.


SAH-053



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking southwest toward terrace corner
Description: Cracked and spawling decking material & inappropriate scaled fencing
Date: September 2012


Photograph No.

SAH-054





Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking west-northwest toward Tower 3
Description: Atmospheric and mineral stained masonry
Date: September 2012

Photograph No.
SAH-055



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking west toward Tower 3
Description: Atmospheric and mineral stained masonry; inappropriate fencing
Date: September 2012


Photograph No.
SAH-056



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking north-northwest toward Tower 4
Description: Atmospheric and mineral stained masonry; pool concession addition
Date: September 2012

Photograph No.


SAH-057



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking northwest toward Towers 3 & 4
Description: Atmospheric and mineral stained masonry; pool concession addition
Date: September 2012


Photograph No.

SAH-058



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking north at Tower 4 south facade
Description: Atmospheric and mineral stained masonry; pool concession addition
Date: September 2012

Photograph No.
SAH-059



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking south toward Maverick Bldg.
Description: Light fixtures & perimeter fencing with inappropriate scale & materials
Date: September 2012

Photograph No.
SAH-060



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking northwest at Tower 4 south facade
Description: Pool concession addition and canopy structure
Date: September 2012

Photograph No.
SAH-061



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking west toward Tower 3
Description: Pool concession addition and canopy structure
Date: September 2012


Photograph No.
SAH-062



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking northeast at Tower 4 south facade
Description: Pool concession serving window and pool terrace entry
Date: September 2012

Photograph No.

SAH-063



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking northwest at Tower 4 south facade
Description: Exterior showers with mineral stained tile & cracked pool terrace deck
Date: September 2012

Photograph No.

SAH-064



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking north at Tower 4 south facade
Description: Detail of stucco and tile finishes added to historic brick masonry
Date: September 2012

Photograph No.

SAH-065



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking southwest at terrace corner
Description: Detail of steel post and perimeter fencing
Date: September 2012

Photograph No.


SAH-066



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking north at Tower 4 south facade
Description: Mold and mineral stained masonry; cracked pool terrace
Date: September 2012

Photograph No.


SAH-067



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor pool terrace, looking west at Tower 3 east facade
Description: Cracked and spawling decking material & inappropriate scaled fencing
Date: September 2012


Photograph No.

SAH-068



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor men's pool changing room interior, looking west
Description: Lavatories in changing room
Date: September 2012

Photograph No.
SAH-069



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor men's pool changing room interior, looking northeast
Description: Toilet, urinals and showers in changing room
Date: September 2012

Photograph No.
SAH-070



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking northwest
Description: Proscenium and platform with non-historic restroom addition beyond
Date: September 2012

Photograph No.

SAH-071



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking north
Description: Proscenium and platform with non-historic restroom addition beyond
Date: September 2012

Photograph No.

SAH-072



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking northeast
Description: Tile roof and stucco colonnade with non-historic additions & infills
Date: September 2012

Photograph No.

SAH-073



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking east at west facade of Tower 3
Description: Non-historic bar and storage room additions
Date: September 2012

Photograph No.

SAH-074



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking southeast at parapet wall
Description: Inappropriately scaled, non-historic guardrail on historic parapet wall
Date: September 2012

Photograph No.

SAH-075



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking southeast at Tower 3 west facade
Description: Cracked and detaching masonry coating and stucco finish
Date: September 2012

Photograph No.

SAH-076



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking south
Description: Non-historic guardrail on historic parapet wall; tile roof & colonnade
Date: September 2012

Photograph No.

SAH-077



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking north
Description: Non-historic guardrail on historic parapet wall; tile roof & colonnade
Date: September 2012

Photograph No.

SAH-078



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking northwest
Description: Tile roof & colonnade with wood windows and transoms
Date: September 2012

Photograph No.

SAH-079



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking northwest
Description: Proscenium and platform with non-historic restroom addition beyond
Date: September 2012

Photograph No.


SAH-080



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking west
Description: South bay of west colonnade with tile roof and copper gutter
Date: September 2012

Photograph No.

SAH-081



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking southwest at window
Description: Wood window with painted transom arch; historic light fixtures
Date: September 2012

Photograph No.

SAH-082




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking southwest at west colonnade
Description: Tile roof & colonnade with wood windows and transoms
Date: September 2012

Photograph No.
SAH-083




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking northeast from west colonnade
Description: General view of terrace features
Date: September 2012

Photograph No.
SAH-084



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking south at west colonnade
Description: Stucco columns, wood windows with transoms, & historic fixtures
Date: September 2012

Photograph No.
SAH-085



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking north at west colonnade
Description: Stucco columns, wood windows with transoms, & historic fixtures
Date: September 2012

Photograph No.
SAH-086



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking west at west colonnade
Description: Tile parapet mural above tile roof and stucco colonnade
Date: September 2012

Photograph No.


SAH-087



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace, looking north at west colonnade
Description: Stucco columns, wood windows with transoms, & historic fixtures
Date: September 2012

Photograph No.


SAH-088



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace parapet and guardrail
Description: Detail view of inappropriately scaled guardrail & non-historic podium
Date: September 2012

Photograph No.

SAH-089



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Alley as seen from tenth floor Starlight Terrace, looking east
Description: Coated masonry with rust stains; Tower 2 fire escape
Date: September 2012

Photograph No.

SAH-090



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: East facade of Tower 1, as seen from tenth floor Starlight Terrace
Description: Starlight Terrace fire escape and crenelated brick parapet
Date: September 2012

Photograph No.

SAH-091



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Roof of Travis Room, as seen from tenth floor Starlight Terrace
Description: Coated masonry walls, terra-cotta sills, mechanical equipment & ducts
Date: September 2012

Photograph No.


SAH-092



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace storage room interior, looking west
Description: Non-historic infill addition at north colonnade to be demolished
Date: September 2012

Photograph No.


SAH-093



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Starlight Terrace restroom interior, looking north
Description: Non-historic infill addition behind stage to be demolished
Date: September 2012


Photograph No.

SAH-094



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking southwest
Description: General view of Grand Lobby's significant features
Date: September 2012

Photograph No.
SAH-095



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking north
Description: Non-historic serpentine stair to be demolished
Date: September 2012

Photograph No.
SAH-096



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking southeast
Description: General view of Grand Lobby's significant features
Date: September 2012

Photograph No.


SAH-097



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking south-southwest
Description: General view of Grand Lobby's significant features
Date: September 2012


Photograph No.

SAH-098



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking south
Description: General view of Grand Lobby's significant features
Date: September 2012

Photograph No.
SAH-099



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking northeast (portrait format)
Description: Travis Street entrance with brass revolving door & decorative surround
Date: September 2012

Photograph No.
SAH-100




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking southwest
Description: General view of Grand Lobby significant features
Date: September 2012

Photograph No.
SAH-101




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking west
Description: Plexiglas panels at mezzanine, brass canopy and historic door
Date: September 2012

Photograph No.
SAH-102



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking south
Description: Non-historic serpentine stair, historic column (left), faux column (right)
Date: September 2012

Photograph No.
SAH-103



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking at southwest corner
Description: Historic brass restaurant doors; non-historic plexiglass and railing
Date: September 2012

Photograph No.
SAH-104



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking east at stair
Description: Non-historic serpentine stair, plaster columns and cast stone arches
Date: September 2012

Photograph No.


SAH-105



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking northeast (landscape format)
Description: Travis Street entrance with brass revolving door & decorative surround
Date: September 2012

Photograph No.


SAH-106



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking east toward reception lobby
Description: Gypsum plaster columns and beam moldings; cast stone arches
Date: September 2012

Photograph No.


SAH-107



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Grand Lobby interior, looking east at reception desk
Description: Cast stone arch & non-historic reception desk
Date: September 2012


Photograph No.

SAH-108




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, looking west toward Grand Lobby
Description: Plaster groin vault ceiling & cast stone arch
Date: September 2012

Photograph No.
SAH-109




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, looking east toward Peacock Alley
Description: Plaster groin vault ceiling & reception desk
Date: September 2012

Photograph No.
SAH-110




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, looking east toward Peacock Alley
Description: Plaster groin vault ceiling & elevator lobby
Date: September 2012

Photograph No.
SAH-111



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor elevator lobby interior, looking southeast
Description: Non-historic, engraved brass elevator doors and call buttons
Date: September 2012


Photograph No.
SAH-112



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, looking east toward Peacock Alley
Description: Plaster groin vault ceiling & elevator lobby
Date: September 2012

Photograph No.


SAH-113



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor elevator lobby interior, looking southeast
Description: Non-historic, engraved brass elevator doors and call buttons
Date: September 2012


Photograph No.

SAH-114




Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, view above plaster groin vaults
Description: Mechanical equipment and remnants of original plaster ceiling
Date: September 2012

Photograph No.
SAH-115



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor reception lobby interior, view above plaster groin vaults
Description: Detail of remnants of original plaster ceiling molding and paint
Date: September 2012


Photograph No.
SAH-116



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking west toward reception lobby
Description: Cast stone arch, plaster column, & coffered ceiling with modillions
Date: September 2012

Photograph No.

SAH-117



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east
Description: Plaster columns, coffered ceiling with modillions, & chandeliers
Date: September 2012

Photograph No.

SAH-118



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east
Description: Plaster columns, coffered ceiling with modillions, & chandeliers
Date: September 2012

Photograph No.

SAH-119



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east
Description: Coffered ceiling with modillions, chandeliers & wood door surrounds
Date: September 2012

Photograph No.

SAH-120



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east
Description: Coffered ceiling with modillions, chandeliers & glass french doors
Date: September 2012

Photograph No.

SAH-121



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking southwest
Description: Plaster columns, coffered ceiling with modillions, & chandeliers
Date: September 2012

Photograph No.


SAH-122



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking south at fireplace
Description: Cast stone fireplace mantel with brass gallery, plaster pilasters & chandelier
Date: September 2012

Photograph No.


SAH-123



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking southwest at fireplace
Description: Cast stone fireplace mantel with brass gallery, plaster pilasters & chandelier
Date: September 2012

Photograph No.


SAH-124



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking south at fireplace
Description: Cast stone fireplace mantel with brass gallery & lion-headed andirons
Date: September 2012

Photograph No.

SAH-125



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking at northwest corner
Description: Cast stone arch with non-historic infill wall
Date: September 2012

Photograph No.


SAH-126



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east at bar
Description: Non-historic bar & loggia door with solid panels
Date: September 2012

Photograph No.


SAH-127



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking north at bar
Description: Non-historic bar & loggia door with solid panels
Date: September 2012

Photograph No.


SAH-128



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking northwest at bar
Description: Non-historic bar & loggia door with solid panels
Date: September 2012

Photograph No.


SAH-129



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking west
Description: Plaster columns, coffered ceiling with modillions, & chandeliers
Date: September 2012


Photograph No.

SAH-130



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east
Description: Non-historic infill wall panel at east wall of Peacock Alley
Date: September 2012

Photograph No.
SAH-131



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peacock Alley interior, looking east toward motor lobby
Description: Non-historic canterra stone arch
Date: September 2012


Photograph No.
SAH-132



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Loggia interior, looking east
Description: French doors with sidelights, quarry tile flooring, & historic fixtures
Date: September 2012

Photograph No.

SAH-133



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Loggia interior, looking east
Description: Steel arched windows, quarry tile flooring, & historic fixtures
Date: September 2012

Photograph No.

SAH-134



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Loggia interior, looking east
Description: Steel windows, french doors, quarry tile flooring, & historic fixtures
Date: September 2012

Photograph No.

SAH-135



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Loggia interior, looking west
Description: Steel windows, french doors, quarry tile flooring, & historic fixtures
Date: September 2012

Photograph No.

SAH-136



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Motor Lobby interior, looking southwest
Description: Non-historic steps, canterra stone arch, marble flooring and ceiling
Date: September 2012

Photograph No.

SAH-137



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Motor Lobby interior, looking northwest
Description: Non-historic steps, canterra stone arch, marble flooring and ceiling
Date: September 2012

Photograph No.

SAH-138



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Motor Lobby interior, looking southeast at elevator
Description: Non-historic vestibule doors, marble flooring and ceiling
Date: September 2012

Photograph No.

SAH-139



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho pre-function interior, looking north
Description: Non-historic vestibule finishes and doors
Date: September 2012

Photograph No.


SAH-140



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking southeast toward stage
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012

Photograph No.


SAH-141



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking south toward stage
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012

Photograph No.

SAH-142



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking southwest toward stage
Description: Coffered ceiling with plaster moldings, metal railings & chandeliers
Date: September 2012

Photograph No.


SAH-143



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking west toward mezzanine
Description: Coffered ceiling with plaster moldings, metal railings & chandeliers
Date: September 2012

Photograph No.


SAH-144



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking northwest toward entry
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012

Photograph No.


SAH-145



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking northeast toward entry
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012


Photograph No.

SAH-146



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, from stage looking north
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012

Photograph No.
SAH-147



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking south toward stage
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012


Photograph No.
SAH-148



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking northwest toward entry
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012

Photograph No.

SAH-149



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking south toward stage
Description: Coffered ceiling with plaster moldings, metal railings & chandelieres
Date: September 2012


Photograph No.

SAH-150



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking south at stage
Description: Stage proscenium of molded gypsum plaster
Date: September 2012

Photograph No.
SAH-151



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking west
Description: Corner detail of wrought iron railing with wood hand rail
Date: September 2012

Photograph No.
SAH-152



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking southwest
Description: Wrought iron railing with wood hand rail; mezzanine column
Date: September 2012

Photograph No.


SAH-153



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking south
Description: Wrought iron railing with wood hand rail; mezzanine column
Date: September 2012

Photograph No.


SAH-154



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior at top of east stair
Description: Wrought iron stair railing with wood hand rail
Date: September 2012

Photograph No.

SAH-155



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Anacacho Room interior, looking south
Description: Plaster finished structural steel columns at west side of mezzanine
Date: September 2012

Photograph No.

SAH-156



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peraus Room interior, looking southwest
Description: Coffered ceiling with plaster moldings, historic tapastry & chandeliers
Date: September 2012

Photograph No.

SAH-157



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Anacacho Room interior, looking northwest
Description: Coffered ceiling with plaster moldings, louvered doors & chandeliers
Date: September 2012

Photograph No.

SAH-158



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peraus Room interior, looking northeast
Description: Coffered ceiling with plaster moldings, louvered doors & chandeliers
Date: September 2012

Photograph No.

SAH-159



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peraus Room interior, looking southeast
Description: Coffered ceiling with plaster moldings, historic tapastry & chandeliers
Date: September 2012

Photograph No.

SAH-160



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peraux Room interior, looking north
Description: Coffered ceiling with plaster moldings, louvered doors & chandeliers
Date: September 2012

Photograph No.

SAH-161



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Peraux Room interior, looking south
Description: Historic tapastry in molded gypsum plaster frame and plexiglas
Date: September 2012

Photograph No.

SAH-162



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club Foyer interior, looking southeast
Description: Club entry doors and mezzanine stair
Date: September 2012

Photograph No.

SAH-163



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club Foyer interior, looking east
Description: Mezzanine stair and mirrored walls
Date: September 2012

Photograph No.

SAH-164



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club Foyer interior, looking west
Description: Georgian Room entry doors, Niche, wainscot, wood trim and crown molding
Date: September 2012

Photograph No.

SAH-165



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club Foyer interior, looking east
Description: Doors to Peacock Alley (left), niche, wainscot, wood trim and crown molding
Date: September 2012

Photograph No.

SAH-166



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking south
Description: Wood paneling, beams, columns, and sconce light fixtures
Date: September 2012

Photograph No.

SAH-167



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking southwest
Description: Wood paneling, beams, columns, sconce light fixtures, service doors to kitchen
Date: September 2012

Photograph No.

SAH-168



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking west
Description: Wood paneling, beams, columns, sconce light fixtures, & folding panels at bar
Date: September 2012

Photograph No.

SAH-169



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking northwest
Description: Wood paneling, beams, columns, sconce light fixtures, & folding panels at bar
Date: September 2012

Photograph No.

SAH-170



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking north
Description: Wood paneling, beams, columns, sconce light fixtures, and entry doors to foyer
Date: September 2012

Photograph No.

SAH-171



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking northeast
Description: Wood paneling, beams, columns, sconce light fixtures, and fireplace
Date: September 2012

Photograph No.

SAH-172



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking east
Description: Wood paneling, beams, columns, sconce light fixtures, and fireplace
Date: September 2012

Photograph No.

SAH-173



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking east-southeast
Description: Wood paneling, beams, columns, sconce light fixtures, and fireplace
Date: September 2012

Photograph No.

SAH-174



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club interior, looking west
Description: Folding panels at bar partially open revealing faux casks at back bar beyond
Date: September 2012

Photograph No.

SAH-175



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club bar interior, looking south
Description: Folding panels (left) and faux casks at back bar (right)
Date: September 2012

Photograph No.

SAH-176



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club bar interior, looking south
Description: Historic tile flooring with dirt and mineral stains
Date: September 2012

Photograph No.

SAH-177



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor St. Anthony Club bar interior, looking west
Description: Faux casks with heraldic crests at back bar
Date: September 2012

Photograph No.

SAH-178



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking southwest
Description: Wood wainscot, columns, beams, crown, wall fabric, & brass chandeliers
Date: September 2012

Photograph No.

SAH-179



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking west
Description: Wood wainscot, columns, beams, crown, wall fabric, & brass chandeliers
Date: September 2012

Photograph No.

SAH-180



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking northwest
Description: Wood wainscot, columns, beams, crown, wall fabric, & brass chandeliers
Date: September 2012

Photograph No.

SAH-181



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking north-northwest
Description: Wood wainscot, columns, beams, crown, wall fabric, exit door & faux window
Date: September 2012

Photograph No.


SAH-182



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking north
Description: Wood wainscot, columns, beams, crown, wall fabric, chandelier & faux window
Date: September 2012

Photograph No.

SAH-183



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking northeast
Description: Wood wainscot, columns, beams, crown, wall fabric, chandelier & faux window
Date: September 2012

Photograph No.

SAH-184



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking east
Description: Wood wainscot, columns, beams, crown, wall fabric, chandeliers & fireplace
Date: September 2012

Photograph No.

SAH-185



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking east
Description: Detail view of marble fireplace mantel with copper screen and gallery
Date: September 2012

Photograph No.

SAH-186



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking southeast
Description: Wood wainscot, columns, beams, crown, wall fabric, chandeliers & service
Date: September 2012

Photograph No.

SAH-187



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking south
Description: Wood wainscot, columns, beams, crown, wall fabric, & faux windows
Date: September 2012

Photograph No.

SAH-188



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking east
Description: Detail view of service door with ornate wood and plaster surround
Date: September 2012

Photograph No.

SAH-189



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Georgian Room interior, looking south
Description: Detail view of faux window with ornate wood and plaster surround
Date: September 2012

Photograph No.

SAH-190



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Jefferson Room interior, looking west-northwest
Description: Wood panelling, display cases, columns, beams, crown, and chandeliers
Date: September 2012

Photograph No.


SAH-191



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Jefferson Room interior, looking northeast
Description: Wood panelling, mirrors, columns, beams, crown, and chandeliers
Date: September 2012


Photograph No.

SAH-192



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Jefferson Room interior, looking southeast
Description: Wood panelling, display cases, mirrors, columns, beams, crown, & chandeliers
Date: September 2012

Photograph No.
SAH-193



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Jefferson Room interior, looking south-southeast
Description: Wood panelling, display cases, mirrors, columns, beams, crown, & chandeliers
Date: September 2012

Photograph No.
SAH-194



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Jefferson Room interior, looking north
Description: Entry door to vestibule and Grand Lobby beyond with shell niche at right
Date: September 2012

Photograph No.

SAH-195



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor service stair, looking north
Description: Service stair from Navarro Street entry lobby to basement
Date: September 2012

Photograph No.

SAH-196



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Navarro Street entry lobby interior, looking west
Description: Terrazzo and marble flooring and steps, and brass storefront entry doors
Date: September 2012

Photograph No.

SAH-197



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Navarro Street entry lobby interior, looking southwest
Description: Display case and basement service stairs left of Navarro Street entry doors
Date: September 2012

Photograph No.

SAH-198



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking southwest
Description: Plaster colmns, beams and moldings with central foundain/planter
Date: September 2012

Photograph No.

SAH-199



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking southeast
Description: Balcony and windows at Travis Room at mezzanine level
Date: September 2012

Photograph No.

SAH-200



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking east
Description: Plaster colms, beams and moldings with central foundain/planter
Date: September 2012

Photograph No.


SAH-201



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking south
Description: Curving metal stair leading to balcony & private dining room at mezzanine level
Date: September 2012

Photograph No.


SAH-202



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking south-southwest
Description: Curving metal stair leading to balcony & private dining room at mezzanine level
Date: September 2012

Photograph No.

SAH-203



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking northwest
Description: Curving metal stair, balcony, arched window and Navarro Street entrance
Date: September 2012

Photograph No.

SAH-204



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking northwest
Description: Buffet counter adjacent to central fountain/planter with curved stair beyond
Date: September 2012

Photograph No.

SAH-205



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First floor Madrid Room Restaurant interior, looking west-southwest
Description: Rear dining areas with wood lattice screens, panelled wainscot
Date: September 2012

Photograph No.

SAH-206



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Madrid Room Restaurant interior, looking northwest
Description: View from balcony of central columns with plaster capitals & dining room below
Date: September 2012

Photograph No.


SAH-207



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Madrid Room Restaurant interior, looking northeast
Description: Private dining room with door to mezzanine balcony (left) & Travis Room (right)
Date: September 2012

Photograph No.


SAH-208



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Madrid Room Restaurant interior, looking west
Description: Wood panelled wainscot, columns, with windows & doors to Navarro St. terrace
Date: September 2012

Photograph No.

SAH-209



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Madrid Room Restaurant interior, looking west-northwest
Description: Wood panelled wainscot, columns, with windows & doors to Navarro St. terrace
Date: September 2012

Photograph No.

SAH-210



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room pre-function area, looking southwest
Description: Entry door and windows to Travis Room; column, pilaster and plaster moldings
Date: September 2012

Photograph No.

SAH-211



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room pre-function area, looking northeast
Description: Grand Lobby columns and serpentine stair railing; plaster moldings and fixtures
Date: September 2012

Photograph No.


SAH-212



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room pre-function area, looking north
Description: Grand Lobby columns and serpentine stair railing; plaster moldings and beam
Date: September 2012

Photograph No.

SAH-213



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room pre-function area, looking north
Description: Detail view of plaster capital at faux column
Date: September 2012

Photograph No.

SAH-214



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking south
Description: Plaster elliptical barrel vault, steel columns, quarry tile flooring & tile wainscot
Date: September 2012

Photograph No.

SAH-215



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking southwest
Description: Plaster elliptical barrel vault, steel columns, quarry tile flooring & tile wainscot
Date: September 2012

Photograph No.

SAH-216



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking west
Description: Plaster elliptical barrel vault, steel columns, & windows overlooking Madrid Rm.
Date: September 2012

Photograph No.

SAH-217



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking northwest
Description: Plaster elliptical barrel vault, steel columns, entry door to pre-function area
Date: September 2012

Photograph No.

SAH-218



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking northwest
Description: Plaster elliptical barrel vault, steel columns, entry door to pre-function area
Date: September 2012

Photograph No.

SAH-219



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking northeast
Description: Plaster elliptical barrel vault, steel columns, entry door to pre-function area
Date: September 2012

Photograph No.

SAH-220



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking northeast
Description: Detail view of northeast corner columns and tile wainscot beyond
Date: September 2012

Photograph No.

SAH-221



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level Travis Room interior, looking west
Description: Detail view of casement window overlooking Madrid Room and wall tile
Date: September 2012

Photograph No.

SAH-222



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor east elevator lobby interior, looking south
Description: Typical east elevator lobby with chair rail, tile border and tile base
Date: September 2012

Photograph No.


SAH-223



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor corridor interior, looking east
Description: Typical guest level corridor with chair rail, tile border, tile base & room doors
Date: September 2012


Photograph No.

SAH-224



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor corridor interior, looking northwest (rooms 1074 & 1076)
Description: Typical recessed panel wood doors with wood transom panel
Date: September 2012

Photograph No.
SAH-225



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor corridor interior, looking east
Description: Entry door to fitness center with mirror sidelights and beveled glass door
Date: September 2012

Photograph No.
SAH-226



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor corridor tile border and base detail
Description: Example of inconsistent replacement tiles at border and base
Date: September 2012

Photograph No.


SAH-227



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor corridor tile border and base detail
Description: Example of inept Dutchman repair of damaged tiles at border and base
Date: September 2012

Photograph No.


SAH-228



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor corridor tile border and base detail
Description: Example of typical damage to tile base at projecting corners
Date: September 2012

Photograph No.

SAH-229



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor corridor tile border and base detail
Description: Detail view of typical damage to tile base at projecting corners
Date: September 2012

Photograph No.

SAH-230



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Fourth and fifth floor corridor tile border and base detail
Description: Example of dirt, abrasion, wear and chemical staining to tile at door thresholds
Date: September 2012

Photograph No.


SAH-231



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Fourth and fifth floor corridor tile border and base detail
Description: Example of deep pitting, scratches, abrasion, & wear to tile at door thresholds
Date: September 2012

Photograph No.

SAH-232



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor corridor tile border and base detail
Description: Example of typical damage to tile base at projecting corners & chipped border
Date: September 2012

Photograph No.

SAH-233



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth floor corridor tile border and base detail
Description: Example of dirt, abrasion and wear to tile border at door thresholds
Date: September 2012

Photograph No.


SAH-234



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Fourth and fifth floor corridor tile border and base detail
Description: Example of typical damage to tile base at projecting corners & pitted tile border
Date: September 2012

Photograph No.

SAH-235



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Seventh and tenth floor corridor tile border and base detail
Description: Typical damage to tile base at projecting corners & replacement border tile
Date: September 2012

Photograph No.


SAH-236



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Eighth and ninth floors corridor tile border and base detail
Description: Example of cracks, abrasion, & wear to tile at door thresholds
Date: September 2012

Photograph No.

SAH-237



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Eighth and ninth floors corridor tile border and base detail
Description: Example of typical damage to tile base at projecting corners & tile border
Date: September 2012

Photograph No.

SAH-238



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with single king-sized bed
Description: Small, wood crown molding, and simple base; 2-inch thick plaster walls
Date: September 2012

Photograph No.

SAH-239



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with single king-sized bed
Description: Simple crown & door trim and recessed door panels; exposed sprinkler piping
Date: September 2012

Photograph No.

SAH-240



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with single king-sized bed
Description: Mechanical furr down & exposed sprinkler piping; entry door w/ transom panel
Date: September 2012

Photograph No.

SAH-241



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room bathroom
Description: Panelled door, black and white tile wainscot, pedestal sink and toilet
Date: September 2012

Photograph No.

SAH-242



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room bathroom
Description: Black and white tile wainscot, pedestal sink, tub, toilet and chrome fittings
Date: September 2012

Photograph No.

SAH-243



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room bathroom
Description: Black and white tiled, cast iron tub with chrome fittings
Date: September 2012

Photograph No.

SAH-244



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with double full-sized beds
Description: Simple crown & door trim and recessed door panels; exposed sprinkler piping
Date: September 2012

Photograph No.

SAH-245



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with double full-sized beds
Description: Simple crown & door trim and recessed door panels; exposed sprinkler piping
Date: September 2012

Photograph No.

SAH-246



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with double full-sized beds
Description: Simple crown & door trim and recessed door panels; furr-downed mechanical
Date: September 2012

Photograph No.

SAH-247



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical guest room with double full-sized beds
Description: Small, wood crown molding, and simple base; 2-inch thick plaster walls
Date: September 2012

Photograph No.

SAH-248



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking northeast
Description: Living room with panelled wainscot, plaster and wood moldings, & light fixtures
Date: September 2012

Photograph No.

SAH-249



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking southeast
Description: Living room with panelled wainscot, plaster and wood moldings, & light fixtures
Date: September 2012

Photograph No.

SAH-250



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking southwest
Description: Living room with panelled wainscot, plaster and wood moldings, & mantel
Date: September 2012

Photograph No.

SAH-251



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking northwest
Description: Living room with panelled wainscot, plaster and wood moldings, & mantel
Date: September 2012

Photograph No.

SAH-252



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking west
Description: Detail view of carved marble fireplace mantel
Date: September 2012

Photograph No.

SAH-253



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking northeast
Description: Detailed view of cased opening to entry foyer
Date: September 2012

Photograph No.

SAH-254



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking southeast
Description: Detail view of plaster ornamentation and carved wood cornice
Date: September 2012

Photograph No.


SAH-255



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking south
Description: Detail view of plaster ornamentation and carved wood cornice
Date: September 2012


Photograph No.

SAH-256



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking south
Description: Detail view of carved wood cornice and casing at opening to entry foyer
Date: September 2012

Photograph No.
SAH-257



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking northeast
Description: Entry foyer with marble tile, wood cased openings and serving bar
Date: September 2012

Photograph No.
SAH-258



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking southeast
Description: Master bedroom with wood base and window trim, and plaster crown molding
Date: September 2012

Photograph No.

SAH-259



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth floor Presidential Suite interior, looking southwest
Description: Master bedroom with wood base and window trim, and plaster crown molding
Date: September 2012

Photograph No.

SAH-260



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor conference room (Bowie Room)
Description: Typical small conference room previously converted from guest room
Date: September 2012

Photograph No.

SAH-261



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Third floor conference room
Description: Typical small conference room previously converted from guest room
Date: September 2012

Photograph No.

SAH-262



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement level boiler room
Description: Defunct mechanical equipment to be replaced or modernized
Date: September 2012

Photograph No.

SAH-263



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement level mechanical room
Description: Concrete and metal decking to be removed for construction access
Date: September 2012

Photograph No.

SAH-264



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement level mechanical room
Description: Deteriorated concrete slab at mechanical piping
Date: September 2012

Photograph No.
SAH-265



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement level mechanical room
Description: Typical stained and dirty concrete walls and floors throughout basement
Date: September 2012

Photograph No.
SAH-266



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine level at terrace above Navarro Street arcade
Description: Mechanical ductwork, fire suppression piping, and lay-in ceiling to be removed
Date: September 2012

Photograph No.

SAH-267



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Fifth floor level in parking garage
Description: Corroded structural steel supporting sixth floor swimming pool above
Date: September 2012

Photograph No.

SAH-268



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Roof above Mezzanine between Towers 2 & 3, looking southeast
Description: Deteriorated wood windows to be rehabilitated; roof repairs/replacement
Date: November 2012

Photograph No.

SAH-269



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Roof above Mezzanine between Towers 2 & 3, looking northeast
Description: Deteriorated wood windows to be rehabilitated; roof repairs/replacement
Date: November 2012

Photograph No.

SAH-270



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Roof above Mezzanine between Towers 1 & 2, looking northeast
Description: Deteriorated wood windows to be rehabilitated; roof repairs/replacement
Date: November 2012

Photograph No.

SAH-271



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical wood windows at Third Level
Description: Deteriorated wood window to be rehabilitated; masonry cleaned
Date: November 2012

Photograph No.

SAH-272



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical wood window at Third Level
Description: Deteriorated wood window to be rehabilitated; masonry cleaned
Date: November 2012

Photograph No.

SAH-273



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical wood window at Third Level
Description: Deteriorated wood window to be rehabilitated; masonry cleaned
Date: November 2012

Photograph No.

SAH-274



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical pair of wood windows at Third Level with central wood mull panel
Description: Deteriorated wood windows to be rehabilitated; masonry cleaned
Date: November 2012

Photograph No.

SAH-275



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Detail view of typical wood window at Third Level
Description: Deteriorated wood windows to be rehabilitated; masonry cleaned
Date: November 2012

Photograph No.

SAH-276



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement view of typical service corridor
Description: Non-historic, non-character-defining features to be renovated
Date: November 2012

Photograph No.

SAH-277



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement view of typical service corridor
Description: Non-historic, non-character-defining features to be renovated
Date: November 2012

Photograph No.

SAH-278



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement view of typical work area
Description: Non-historic, non-character-defining features to be renovated
Date: November 2012

Photograph No.

SAH-279



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Basement view of laundry facilities
Description: Non-historic, non-character-defining features to be renovated
Date: November 2012

Photograph No.

SAH-280



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: View of typical back-of-house service corridor at Mezzanine Level
Description: Areas to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-281



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: View of typical back-of-house storage area at Mezzanine Level
Description: Areas to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-282



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical view of main kitchen looking east w/ non-historic finishes
Description: Kitchen to be renovated and modernized with new finishes and equipment
Date: November 2012

Photograph No.

SAH-283



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical view of main kitchen looking east w/ non-historic finishes
Description: Kitchen to be renovated and modernized with new finishes and equipment
Date: November 2012

Photograph No.

SAH-284



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Anacacho Room First Floor Level back stage area looking east
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-285



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Anacacho Room First Floor Level back stage area looking west
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-286



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Anacacho Room Mezzanine Level back stage area looking east
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-287



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Anacacho Room Mezzanine Level back stage area looking west
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-288



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level typical back-of-house space looking west toward elevator
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-289



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level back-of-house storage space looking southwest
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-290



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Anacacho Pre-function Vestibule, looking southwest
Description: Non-historic (1983) vestibule space to be reconfigured with Motor Lobby
Date: November 2012

Photograph No.

SAH-291



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Anacacho Pre-function Vestibule, looking west
Description: Non-historic (1983) coat check to be demolished to re-create corridor
Date: November 2012

Photograph No.

SAH-292



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Anacacho Pre-function Vestibule, looking east southeast
Description: Non-historic (1983) vestibule space to be reconfigured with Motor Lobby
Date: November 2012

Photograph No.

SAH-293



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Anacacho Pre-function Vestibule, looking north toward Motor Lobby
Description: Non-historic (1983) vestibule space to be reconfigured with Motor Lobby
Date: November 2012

Photograph No.

SAH-294



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Vestibule, looking southeast at coat check door
Description: Non-historic (mid-1960s, 1983) walls and finishes to be removed & renovated
Date: November 2012

Photograph No.

SAH-295



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Vestibule, looking south at Peraux Room entry
Description: Non-historic (mid-1960s, 1983) walls and finishes to be removed & renovated
Date: November 2012

Photograph No.

SAH-296



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Vestibule, looking northeast
Description: Non-historic (mid-1960s, 1983) walls and finishes to be removed & renovated
Date: November 2012

Photograph No.

SAH-297



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Vestibule, looking north at Peacock Alley door
Description: Historic door to remain *in situ*, non-historic finishes renovated
Date: November 2012

Photograph No.

SAH-298



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Mens Restroom, looking east
Description: Non-historic (mid-1960s, 1983) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-299



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peraux Pre-function Womens Restroom, looking southwest
Description: Non-historic (mid-1960s, 1983) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-300



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at St. Anthony Bar Vestibule
Description: Non-historic (1983, 2000) finishes to be removed & partial demolition of floor slab
Date: November 2012

Photograph No.

SAH-301



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at Womens Restroom door
Description: Non-historic (1983, 2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-302



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at Womens Restroom
Description: Non-historic (1983, 2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-303



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at Mens Restroom
Description: Non-historic (1983, 2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-304



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at Mens Restroom
Description: Non-historic (1983, 2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-305



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level above Peraux Pre-function, looking at Mens Restroom
Description: Non-historic (1983, 2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-306



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Lobby Mens Restroom, looking northwest at lavatory & urinals
Description: Non-historic (2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-307



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Lobby Mens Restroom, looking southwest at lavatory & stalls
Description: Non-historic (2000) walls, finishes & fixtures to be removed
Date: November 2012

Photograph No.

SAH-308



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking north at bar
Description: Non-historic (1983) finishes & fixtures to be removed & pub renovated
Date: November 2012

Photograph No.

SAH-309



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking northwest at exterior wall & windows
Description: Historic windows & structure to remain *in situ*, pub renovated
Date: November 2012

Photograph No.


SAH-310



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking southeast at bar and lobby entry
Description: Non-historic (1983) finishes & fixtures to be removed & pub renovated
Date: November 2012

Photograph No.

SAH-311



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking east at bar
Description: Non-historic (1983) finishes & fixtures to be removed & pub renovated
Date: November 2012

Photograph No.

SAH-312



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking southwest at exterior walls, windows & entry
Description: Historic windows, structure and door to remain *in situ*, pub renovated
Date: November 2012

Photograph No.

SAH-313



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking south at exterior walls, windows & entry
Description: New pub entry to Navarro Street Lobby to re-establish historic relationship
Date: November 2012

Photograph No.

SAH-314



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking east at stair to Main Lobby pub entry
Description: Historic door salvaged and reused; non-historic stair removed
Date: November 2012

Photograph No.


SAH-315



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level at Pete's Pub, looking north at bar
Description: Non-historic (1983) finishes & fixtures to be removed & pub renovated
Date: November 2012

Photograph No.


SAH-316



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Retail Space, looking southwest at exterior wall and windows
Description: Historic windows retained *in situ*; creation of ADA access elevator lobby
Date: November 2012

Photograph No.


SAH-317



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Retail Space, looking northeast at corner of interior walls
Description: Creation of ADA accessible elevator and small lobby space
Date: November 2012

Photograph No.


SAH-318



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices, looking northeast from reception area
Description: Non-historic ceiling, walls and plexi-glass panels to be removed
Date: November 2012

Photograph No.

SAH-319



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices, looking east in corridor
Description: Non-historic ceiling & walls to be removed; historic columns & beams to remain
Date: November 2012

Photograph No.

SAH-320



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices, looking north toward exterior wall in office
Description: Non-historic ceiling & walls to be removed; historic pilaster & beams to remain
Date: November 2012

Photograph No.

SAH-321



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices at Terrace, looking north end of terrace
Description: Non-historic glazing, walls & finishes to be removed; exterior terrace restored
Date: November 2012

Photograph No.

SAH-322



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices at Terrace, looking south southwest
Description: Non-historic glazing, walls, ceilings, finishes & piping to be removed
Date: November 2012

Photograph No.
SAH-323



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Admin. Offices at Terrace, looking south southwest
Description: Non-historic glazing, walls, ceilings, finishes & piping to be removed
Date: November 2012


Photograph No.
SAH-324



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Storage at Terrace, looking south southeast
Description: Non-historic glazing, walls, ceilings, finishes, piping & mech. to be removed
Date: November 2012

Photograph No.

SAH-325



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Storage at Terrace, looking south southwest
Description: Non-historic glazing, walls, ceilings, finishes, piping & mech. to be removed
Date: November 2012

Photograph No.

SAH-326



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Storage at Terrace, detail of parapet and alum. window
Description: Non-historic (1970s) window to be removed and masonry restored
Date: November 2012

Photograph No.

SAH-327



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Mezzanine Level Storage at Terrace, detail of parapet and alum. window
Description: Non-historic (1970s) window to be removed and masonry restored
Date: November 2012

Photograph No.


SAH-328



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Navarro Street entry lobby interior, looking east at stair and rail
Description: Historic stair retained; non-historic rail replaced; display cases removed
Date: November 2012

Photograph No.

SAH-329



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Navarro Street entry lobby, looking west at Madrid Rm. entry doors
Description: Historic doors to be salvaged and reused; new entry to restaurant
Date: November 2012

Photograph No.

SAH-330



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Navarro Street entry lobby, detail of historic doors
Description: Historic doors to be salvaged and reused (not original to this location)
Date: November 2012

Photograph No.


SAH-331



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Navarro Street entry lobby, detail of non-historic display case
Description: Display case to be removed; location of new (original) entry to Pete's Pub
Date: November 2012


Photograph No.

SAH-332



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of historic cast stone arch casing
Description: Historic feature exhibiting high degree of craftsmanship & refined details
Date: November 2012

Photograph No.
SAH-333



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of non-historic carved Canterra stone arch casing
Description: Non-historic (after 1983) feature exhibiting crude craftsmanship & different material
Date: November 2012

Photograph No.
SAH-334



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of historic cast stone arch casing
Description: Historic feature exhibiting high degree of craftsmanship & refined details
Date: November 2012

Photograph No.

SAH-335



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of non-historic carved Canterra stone arch casing
Description: Non-historic (after 1983) feature exhibiting crude craftsmanship & different material
Date: November 2012

Photograph No.

SAH-336



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth Floor Starlight Terrace, detail at stage platform revealing construction
Description: Stage platform composed of contemporary plywood and saltillo tile
Date: November 2012

Photograph No.

SAH-337



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth Floor Starlight Terrace, detail at back wall of stage revealing construction
Description: Contemporary cementitious walls partially concealing historic steel structure
Date: November 2012

Photograph No.

SAH-338



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of historic tile beneath existing carpet
Description: Carpet to be removed and tile cleaned of mastic and rehabilitated
Date: November 2012

Photograph No.

SAH-339



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Floor Peacock Alley, detail of historic tile beneath existing carpet
Description: Carpet to be removed and tile cleaned of mastic and rehabilitated
Date: November 2012

Photograph No.

SAH-340



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Ninth Floor Tower One Corridor, view of proposed new door mockup
Description: New door in existing opening (showing primer, not finish color)
Date: December 2012

Photograph No.

SAH-341



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Ninth Floor Tower One Corridor, view of proposed new door mockup
Description: New door in existing opening (showing primer, not finish color)
Date: December 2012

Photograph No.

SAH-342



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Ninth Floor Tower One Corridor, view of proposed new door mockup
Description: New door w/ faux transom panel and bar for proposed new openings
Date: December 2012

Photograph No.

SAH-343



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Ninth Floor Tower One Corridor, view of proposed new door mockup
Description: New door w/ faux transom panel and bar for proposed new openings
Date: December 2012

Photograph No.

SAH-344



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth Level Fitness Center, looking northwest
Description: Non-historic space to be renovated and expanded
Date: November 2012

Photograph No.
SAH-345



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Sixth Level Fitness Center, looking northwest at millwork
Description: Non-historic space to be renovated and expanded
Date: November 2012

Photograph No.
SAH-346



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth Level Starlight Terrace Event Room, looking southwest
Description: Non-historic finishes renovated; historic relationship to terrace re-established
Date: November 2012

Photograph No.

SAH-347



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth Level Starlight Terrace Event Room, looking northwest
Description: Non-historic finishes renovated; historic relationship to terrace re-established
Date: November 2012

Photograph No.

SAH-348



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Tenth Level Starlight Terrace Event Room, looking southeast
Description: Non-historic finishes renovated; historic relationship to terrace re-established
Date: November 2012

Photograph No.

SAH-349



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Front Desk back offices, looking east
Description: Non-historic spaces to be removed; historic relationship to lobby re-established
Date: November 2012

Photograph No.

SAH-350



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Concierge Office, looking southwest
Description: Non-historic finishes (1983 or later) renovated to create boutique
Date: November 2012

Photograph No.

SAH-351



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Concierge Office, looking northeast toward Travis Entrance
Description: Non-historic finishes (1983 or later) renovated to create boutique
Date: November 2012

Photograph No.

SAH-352



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Concierge Office, looking southeast
Description: Non-historic finishes (1983 or later) renovated to create boutique
Date: November 2012

Photograph No.

SAH-353



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Concierge Office, looking east-southeast toward Grand Lobby
Description: Non-historic finishes (1983 or later) renovated to create boutique
Date: November 2012

Photograph No.

SAH-354



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: Typical housekeeping and linen closet (Tenth Floor)
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-355



Name: Saint Anthony Hotel, 300 East Travis Street, San Antonio, Texas
View: First Level Front Desk back offices, looking east
Description: Area to receive routine maintenance, repairs & life safety upgrades
Date: November 2012

Photograph No.

SAH-356