HISTORIC AND DESIGN REVIEW COMMISSION

May 20, 2015 Agenda Item No: 5

HDRC CASE NO: 2015-188

ADDRESS: 227 FLORIDA ST

LEGAL DESCRIPTION: NCB 3006 BLK 4 LOT 16

ZONING: RM4 H

CITY COUNCIL DIST.:

DISTRICT: Lavaca Historic District

APPLICANT: Russell Evatt
OWNER: Russell Evatt
TYPE OF WORK: Re-roof

REOUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

To replace the existing shingle roof with a new standing seam metal roof.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

3. Metal Roofs

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Roof replacement—Consider roof replacement when more than 25-30 percent of the roof area is damaged or 25-30 percent of the roof tiles (slate, clay tile, or cement) or shingles are missing or damaged.

ii. Roof form—Preserve the original shape, line, pitch, and overhang of historic roofs when replacement is necessary. iii. Roof features—Preserve and repair distinctive roof features such as cornices, parapets, dormers, open eaves with exposed rafters and decorative or plain rafter tails, flared eaves or decorative purlins, and brackets with shaped ends. vi. Materials: metal roofs—Use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Refer to Checklist for Metal Roofs on page 10 for desired metal roof specifications when considering a new metal roof. New metal roofs that adhere to these guidelines can be approved administratively as long as documentation can be provided that shows that the home has historically had a metal roof.

FINDINGS:

- a. The house at 227 Florida is a modest single family residence featuring a simple hipped roof and was constructed circa 1910. The applicant is proposing to remove the existing asphalt shingle roof with a standing seam metal roof with a galvalume finish.
- b. Given its approximate time of construction and architectural style, this single family residence would have featured a standing seam metal roof. The applicant's proposal is consistent with the Guidelines for Exterior Maintenance and Alterations 3.B.vi. The applicant should ensure that the new standing seam metal roof include panels that are 18 to 21 inches wide, the seams are an appropriate height (1 to 2 inches), that a crimped ridge seam that is consistent with the historic application is used and that a low profile ridge cap is used if now crimped ridge seam is used.

RECOMMENDATION:

Staff recommends approval as submitted based on findings a and b.

CASE MANAGER:

Edward Hall





Flex Viewer

Powered by ArcGIS Server

Printed:May 12, 2015

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.







