HISTORIC AND DESIGN REVIEW COMMISSION

May 20, 2015 Agenda Item No: 20

HDRC CASE NO: 2015-196

ADDRESS: 500 KENDALL ST

LEGAL DESCRIPTION: NCB 1735 BLK 14 LOT 18

ZONING: R6 H CITY COUNCIL DIST.:

DISTRICT: Tobin Hill Historic District

APPLICANT: Mario Herrera
OWNER: Americo Canales
TYPE OF WORK: Exterior alterations

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Remove metal staircases on both sides. Paint exterior.
- 2. Demolish rear addition that is partially collapsed
- 3. Replace front porch columns with 10"x10" square wood columns and repair second floor porch railing.
- 4. Enclose two portions of each side of the house. The proposed cladding is hardi board.
- 5. Construct a rear addition
- 6. Enclose two windows on the north side

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- 7. Architectural Features: Porches, Balconies, and Porte-Cocheres

A. MAINTENANCE (PRESERVATION)

i. *Existing porches, balconies, and porte-cocheres*—Preserve porches, balconies, and porte-cocheres. Do not add new porches, balconies, or porte-cocheres where not historically present.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- ii. *Side and rear porches*—Refrain from enclosing side and rear porches, particularly when connected to the main porch or balcony. Original architectural details should not be obscured by any screening or enclosure materials. Alterations to side and rear porches should result in a space that functions, and is visually interpreted as, a porch.
- iii. *Replacement*—Replace in-kind porches, balconies, porte-cocheres, and related elements, such as ceilings, floors, and columns, when such features are deteriorated beyond repair. When in-kind replacement is not feasible, the design should be compatible in scale, massing, and detail while materials should match in color, texture, dimensions, and finish.

Historic Design Guidelines, Chapter 3, Guidelines for Additions

1. Massing and Form of Residential Additions

A. GENERAL

i. *Minimize visual impact*—Site residential additions at the side or rear of the building whenever possible to minimize views of the addition from the public right-of-way. An addition to the front of a building would be inappropriate.

- iii. Similar roof form—Utilize a similar roof pitch, form, overhang, and orientation as the historic structure for additions.
- iv. *Transitions between old and new*—Utilize a setback or recessed area and a small change in detailing at the seam of the historic structure and new addition to provide a clear visual distinction between old and new building forms.

3. Materials and Textures

A. COMPLEMENTARY MATERIALS

i. *Complementary materials*—Use materials that match in type, color, and texture and include an offset or reveal to distinguish the addition from the historic structure whenever possible. Any new materials introduced to the site as a result of an addition must be compatible with the architectural style and materials of the original structure.

FINDINGS:

- a. The house at 500 Kendall first appears on Sanborn maps in 1911-1951. Prior to 1951, the house had a one story porch at the front and a one story rear addition. The map also shows two side extrusions, one that is tied onto the house located on the south wall and one that appears to be a later addition located on the north wall.
- b. The existing metal staircases to the sides are likely not original to the structure. Removal will not cause an adverse effect.
- c. The rear addition is likely not original to the structure. Removal will not cause an adverse effect.
- d. Consistent with the Guidelines for Exterior Maintenance and Alterations, porch elements should be replaced in kind or with new elements that are compatible to the style of the structure. The proposed replacement columns are consistent with the guidelines.
- e. According to the Guidelines for Exterior Maintenance and Alterations, side porches and original architectural details should not be obscured by enclosure materials. The existing wall offset on the south side appears to be original to the house and should be preserved. The existing wall offset on the north side is likely a later addition and modifications to this element will not impact the historic portions of the house.
- f. As recommended by the Guidelines for Additions, new additions should be located at the side or rear of the building, use a similar roof form and a setback or recessed area to provide clear distinction between old and new. The proposed addition is in keeping with the guidelines in location and roof form, however the walls of the addition will align with the walls of the main house and will not provide a clear separation between old and new.
- g. Consistent with the Guidelines for Additions, materials that match in type, color and texture should be used. The proposed hardi board siding may be appropriate for this installation.
- h. According to the Guidelines for Exterior Maintenance and Alterations, existing windows and window openings should be preserved. The proposed windows to be infilled are located in the main portion of the house and are likely original to the structure. Filling in these windows is not consistent with the guidelines and should be avoided.

RECOMMENDATION:

- 1-3. Staff recommends approval as submitted based on findings b-d.
- 4. Staff does not recommend approval as submitted based on findings a and e. Staff recommends the original portion of the house is preserved.
- 5. Staff recommends approval based on findings f and g with the following stipulations:
 - a. The siding is smooth and painted
 - b. The new additions are differentiated from the old
- 6. Staff does not recommend approval based on finding h. If the existing window pattern does not fit with the new interior layout staff recommends the windows are covered on the inside only so that the windows remain on the exterior.

CASE MANAGER:

Adriana Ziga





500 Kendall

Powered by ArcGIS Server

Printed:May 06, 2015

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.




























FLOOD ZONE INTERPRETATION. IT IS THE RESPONSIBILITY OF ANY INTERESTED PERSONS TO VERIFY THE ACCURACY OF FRIA FLOOD ZONE DESIGNATION OF THIS PROPERTY WITH PAUL AND STATE AND LOCAL OFFICIALS. AND TO DETERMINE THE SEFECT THAT STUE DESIGNATION DESIGNATION THE INTERPED USE OF THE PROPERTY. The property made the subject of this survey appears to be calculed in a MAY HAVE REGARDING THE INTERPED USE OF THE PROPERTY. The property made the subject of this survey appears to be calculated in a community in 0.4005 of countries to be calculated in a community in 0.4005 of countries to be calculated in a continuous Relation of Community in 0.4005 of countries and the latest september 29, 2010, By FEMA Flood Instrumers Relation from the TRM, it appears that all or a portion of the property may be in Flood Zone(s) X. This flood zone identification is this survey of the property may be in Flood Zone(s) X. This flood zone identification is this survey of the property may be in Flood Zone(s) X. This flood zone identification is this survey. In the continuous property of the property may be in Flood Zone(s) X. This flood zone identification is this survey. In the continuous property of the property may be in Flood Zone(s) X. This flood zone identification is this survey. In the continuous property of the property may be in Flood Zone(s) X. This flood zone identification is this survey. The flood Zone(s) X. This flood zone identification is this country. The flood Zone(s) X. This flood Zone(s) X. This flood zone identification is this country. The flood Zone(s) X. This flood Zone 91/2" IRF SOOKENDALL WAY 1/2" IRF Q (50' RIGHT-OF-WAY) NO° 00' 00"E 39:42 GRUAL DESCRIPTION: 1/2" IRF LOT 12, NBH CITY BLOCK 1735, OUT OF A RESUMBITISION OF LOTS 9, 10 AND 11 STRAINE MILE SO THE CORPORATE LIMITES OF THE CITY OF SAN ANTONIO, BEAR COUNTY, TEXAS, ACCORDING TO THE PLAT THEREOF, RECORDED IN VOLUME 368, PAGE 288, DEED AND PLAT RECORDS OF BEAR COUNTY, TEXAS, SAYS AND EXCEPT THE SOUTH 10 FEET THEREOF. NOO OO' OF BEARING 1GM ΕΝΔ PROPOSED BORROWER: KD HOMES & PROPERTIES, LLC AND SELE TITLE COMPANY: MISSION TITLE COMPANY SEINE ROW. G.F. No: 1402860-08 PROPERTY ADDRESS: 500 KENDALL WAY SAN ANTONIO, TEXAS 78212 TWO STORY HOUSE 1/2" IRF CARMENT ROBLEDO 14, N.C.B. 368, PC. VALDEZ VOL. 8100, PG 589 LOT 2 2375 EGT LOT 18 N.C.B. 1785 LOT 8 ARNOLD C. ORTIZ VOL. 12307, PG. 1156 50.17 S84° 42' 55"W CHAPTER OF THE STREET OF THE S JUAN & JUANA M. MORA VOL. 5074, PG. 0782 LEGEND 1/2" IPON ROD FOUND GRAPHIC SCALE 1/2" INON ROD SET ٥ 働 CONTROL MONUMENTS f" == 20" I. Enrique C. Bizando, a Registered Professional Land Surveyer do hareby certify that this plat represents an actual survey made on the ground under my superintion and substantially complete with the minimum standards for fand surveying in Tenas as set forth by the lease Board of Professional Land Surveying and that there we no encountenents or visible casements, is the best of my knowledge and butlef, except as shown berein. This 16th day of July, 2014. RECORD BEARINGS (R) P.R.B.C.T. MAP , PLAT RECORDS. BEXAG COUNTY, TEXAS Drawn By: LJG | Job No.: Survey Date: 07/16/2014 Phone: (210) 376-4128 Fex: (210) 376-5130 5505 Calleghan Road, Suile 109 San Anlardo, Toxas 18228 TEXAS LICENSED SURVEYING FIRM No. 10183654 PUBLIC UTILITY EASEMENT P.U.E. AIR COCDITIONER ACO WATER METER WMO. ww.siizondossaclates.com GAS LIETER OMA POWER POLE COVERSD AREA CHAIN LINK FENCE Elizondo & Associates IRON PENCE

HO














A2




EXISTING FIRST FLOOR PLAN



EXISTING SECOND FLOOR PLAN SCALE: 1/4" a 11-0"








AMERICO CANALES 500 KENDALL



REVISIONS	


PROJECT #
DATE: 03/28/15
DRAWN: M.H.
CHECKED BY: M.H.
SHEET #

Å3



REVISED SECOND FLOOR PLAN SCALE, 1/4" = 1-0"







7006-23



