### HISTORIC AND DESIGN REVIEW COMMISSION

### May 18, 2016 Agenda Item No: 15

HDRC CASE NO:	2016-172
ADDRESS:	283 W MARIPOSA
LEGAL DESCRIPTION:	NCB 9012 BLK 6 LOT 89 90 AND W 12.50 FT OF 88
ZONING:	R4 H
CITY COUNCIL DIST.:	1
DISTRICT:	Olmos Park Terrace Historic District
APPLICANT:	Edward Pape
OWNER:	Christine Catsifas
TYPE OF WORK:	Expand driveway, replace garage door

### **REQUEST:**

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. replace existing wooden swinging garage door with a steel overhead garage door
- 2. expand existing concrete driveway from 10' wide to 17' wide by repouring slab

### **APPLICABLE CITATIONS:**

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alteration

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.

ii. Doors-Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.

iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.

iv. Screens and shutters-Preserve historic window screens and shutters.

v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.

### B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.

ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.

iii. *Glazed area*—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows. iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.

v. Muntins—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.

vi. Replacement glass—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.

vii. Non-historic windows—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.

viii. Security bars-Install security bars only on the interior of windows and doors.

ix. Screens—Utilize wood screen window frames matching in profile, size, and design of those historically found when

the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.

x. Shutters—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

Historic Design Guidelines, Chapter 5, Guidelines for Site Elements

5. Sidewalks, Walkways, Driveways, and Curbing

### A. SIDEWALKS AND WALKWAYS

i. *Maintenance*—Repair minor cracking, settling, or jamming along sidewalks to prevent uneven surfaces. Retain and repair historic sidewalk and walkway paving materials—often brick or concrete—in place.

ii. *Replacement materials*—Replace those portions of sidewalks or walkways that are deteriorated beyond repair. Every effort should be made to match existing sidewalk color and material.

iii. *Width and alignment*— Follow the historic alignment, configuration, and width of sidewalks and walkways. Alter the historic width or alignment only where absolutely necessary to accommodate the preservation of a significant tree.

iv. *Stamped concrete*—Preserve stamped street names, business insignias, or other historic elements of sidewalks and walkways when replacement is necessary.

v. *ADA compliance*—Limit removal of historic sidewalk materials to the immediate intersection when ramps are added to address ADA requirements.

### **B. DRIVEWAYS**

i. *Driveway configuration*—Retain and repair in place historic driveway configurations, such as ribbon drives. Incorporate a similar driveway configuration—materials, width, and design—to that historically found on the site. Historic driveways are typically no wider than 10 feet. Pervious paving surfaces may be considered where replacement is necessary to increase stormwater infiltration.

### **FINDINGS:**

- a. The applicant is requesting to replace existing wooden swinging garage door with an overhead paneled steel garage door painted to match existing door and trim. This is not consistent with the Guidelines for Exterior Maintenance and Alteration 6.B., which states that doors should be replaced with in-kind materials.
- b. The applicant is proposing to tear up existing 10' concrete driveway and repour a 17' wide concrete driveway, which is not consistent with the Guidelines for Site elements. The Guidelines state that historic driveways are typically no wider than 10' and that new driveway configurations should be similar to what is found in the district. Staff made a site visit on May 6, 2016, and found that driveways in Olmos Park Terrace Historic District typically are 10' to 15' wide. Staff recommends that the applicant not expand the driveway to the corner of the house, but towards to left property line.

### **RECOMMENDATION:**

Staff does not recommend approval of item #1 or #2 based on findings a through b.

### **CASE MANAGER:**

Lauren Sage

### CASE COMMENT:

A stop work order was issued for doing stone work prior to receiving approval. The application for the stone work along with the post-work application fee was submitted and an administratively Certificate of Appropriateness was issued.






### **Flex Viewer**

### Powered by ArcGIS Server

Printed:May 11, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.















283 West Mariposa Contents List by Page Number

1) Application 2) Application (signature page) 3) Table of Contents for document package 4) Project Narrative 5) Photo showing South façade (Street View) 6) Photo showing South (Detail of affected area) 7) Photo showing West facade 8) Photo Showing North Facade (Unaffected) 9) Photo showing East Façade (Unaffected) 10) Photo for location reference 11) Photo for location reference (enlarged) 12) Survey 13) Sketch of proposed plot plan 14) Photo illustrating proposed driveway expansion 15) Sketch of elevation showing door to be replaced 16) Door Product Specification literature (1 of 2) 17) Door Product Specification literature (2 of 2) 18) Copy of current Administrative Certificate (for stone repairs)

City of San Antonio Historic Design and Review Commission 1901 South Alamo San Antonio, TX 78204

283 West Mariposa San Antonio TX

The homeowner wishes to make the following repairs and upgrades and requests a certificate of appropriateness.

- 1) Replace non-working garage doors with new overhead door for garage access. The new door and trimwork will be painted to match the rest of the woodwork on the house. The door width will not change.
- 2) Replace the existing 4' wide foot path (sidewalk) extending from the street to the curb. The existing sidewalk had failed over time and presents a trip hazard. The termination of the sidewalk at the street was removed by the street contractor in order to accommodate the ongoing curb and street repairs.
- 3) Replace the existing single car driveway and expand the width to approximately 17' to accommodate 2 vehicles. The homeowner has previously been parking on a gravel extension of the driveway. The original driveway had numerous cracks and failures due to time.


Other relevant information.

- The west façade of the home is currently undergoing repair to the exterior stone veneer under an administrative certificate of appropriateness. (Copy attached)
- The neighborhood is currently undergoing a street and curb/approach replacement project. The homeowner would like to coordinate their repairs to be completed at the same time if possible. The original application for driveway permit permit was deemed unnecessary by Mr. Johnny Aguilar Sr. Sr. Engineering Technician with Development Services due to the replacement of the approach being incorporated into the street repair project.
- Numerous homes on the street have previously expanded their driveways in varying widths and designs to also accommodate 2 vehicles including 267,263,260, 249, 244, 235, 238, 234, 224, 218, 167, 131, 128, 124, 108, and 106 Mariposa.

Thankyou for your consideration. Edward Pape


4/18

SOUTH (STREET) FACASE Mandalay Dr W Mariposa Dr W Wildwood Dr










# 283 W. MARIPOSA




10/18




283 W. MARIPOSA

1/18




12/18

Copyright @ AmeriSurveyors LLC. Improvements shown on this survey are for general illustration purposes only and may not partray exact shape and size. Survey is based on a Title report issued by the Title Company listed above issued under Commitment No./GF No. shown on this survey.










# STRATFORD° COLLECTION



Time-honored style. The Stratford Collection offers four traditional designs, 11 color choices, and 21 decorative window options. This durable low-maintenance collection provides section interfaces designed to reduce serious finger and hand injuries. The Stratford Collection. A statement of style.





+Color only available in Stratford 3000

### PANEL DESIGNS

### SP . SHORT PANEL

SP • SHORT PANEL	LP . LONG PANEL	FP • FLUSH PANEL*	RP • RIBBED PANEL*
		1	
		]	
		1	

16/18

\*Available on 3000 model only

### STRATFORD°COLLECTION

### Construction



Steel Exterior

Vinyl-Coated

Bottom

ather Seal

Polystyrene

Insulation



### 1000

Single-Layer: Steel

Get value and durability with a Stratford 1000 single-layer steel door. These heavy-duty steel doors are durable, reliable, and low maintenance.


- Heavy-duty Exterior Steel
- Durable, Reliable, Low Maintenance

### 2000

### Double-Layer: Steel + Insulation

A Stratford 2000 double-layer door provides durable, low maintenance features, plus a layer of vinyl-coated insulation for increased thermal properties and quieter operation.

- Heavy-duty Exterior Steel
- Durable, Reliable, Low Maintenance
- Environmentally Safe Polystyrene Thermal Insulation with Vinyl Backing
- Energy Efficient
- Quiet Operation



**Specifications** 

### Triple-Layer: Steel + Insulation + Steel

For the toughest, most energy-efficient steel door, a Stratford 3000 triple-layer door includes the ultimate in thermal properties, plus a layer of steel for a finished interior look and added durability.

- Heavy-duty Exterior and Interior Steel
- Durable, Reliable, Low MaintenanceEnvironmentally Safe Polystyrene
- Thermal InsulationSuperior Energy Efficiency
- Extra Quiet Operation

		STRATFORD 1000	STRATFORD 2000	STRATFORD 3000
PANEL DESIGNS		a la companya di serie di seri		ан на с
Short		•		•
Long		•	•	•
Flush				۰
Ribbed				•
INSULATION <sup>1</sup>			Polystyrene	Polystyrene
R-VALUE <sup>2</sup>			6.64	6.48
DOOR THICKNESS		2" (5.1cm)	2" (5.1cm)	1-3/8" (3.5cm)
STEEL THICKNESS		25 ga	25 ga	27/27 ga
WINDOW GLASS O	PTIONS			
3/32" Single Strei	ngth	•	•	•
Insulated Glass				•
Obscure		•	•	•
WIND LOAD <sup>3</sup> AVAIL	ABLE	•	•	•
PAINT FINISH WAF	RANTY4	15 Years	25 Years	Lifetime
WORKMANSHIP/H	ARDWARE WARRANTY	1 Year	2 Years	3 Years
<sup>1</sup> Insulation has passed self-ignition, flamesoread	<sup>2</sup> Calculated door section <sup>3</sup> R-value is in accordance	It is your responsibility to make sure your garage doo		warranty details, n or contact your

self-ignition, flamespread R-value is in accordance and smoke developed with DASMA TDS-163. index fire testing. make sure your garage door visit amarr.com or contact meets local building codes. local Amarr dealer.

Entrematic reserves the right to change specifications and designs without notice and without incurring obligations.

Sectional door products from Entrematic may be the subject of one or more U.S. and/or foreign, issued and/or pending, design and/or utility patents. Amarr and Stratford as words or logos are registered trademarks belonging to Entrematic Group AB or other companies controlled by the same organization. All rights reserved.

©Entrematic Group AB 2014. All rights reserved. Printed in USA Form #6331114/75M/GVS

### DecraTrim Window Inserts


PRAIRIE [21]

OBSCURE (0)

CATHEDRAL (22)

STOCKTON (20)

CASCADE [23]



## SHORT PANEL CLEAR (C)





# CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION

### ADMINISTRATIVE CERTIFICATE OF APPROPRIATENESS

34

#

April	19.	2016	
	/		

ADDRESS:	283 W MARIPOSA	
LEGAL DESCRIPTION:	NCB 9012 BLK 6 LOT 89 90 AND W 12.50 FT OF 88	
HISTORIC DISTRICT:	Olmos Park Terrace	
PUBLIC PROPERTY:	No	
RIVER IMPROVEMENT OVERLAY:	No	
APPLICANT:	Edward Pape - PO Box 6391	
OWNER:	Christine Catsifas - 283 W Mariposa	
TYPE OF WORK:	Repair and Maintenance	

### **REQUEST:**

The applicant is requesting a Certificate of Appropriateness for approval to remove and replace the existing stones on the facade of the garage.

CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION DATE: 4/19/2016 4:16:28 PM

ADMINISTRATIVE APPROVAL TO: remove and replace the existing stones on the facade of the garage. Existing stones will be re-used on the exterior of the garage.

6 14

145

APPROVED BY: Katie Totman

For:

Shanon Shea Miller Historic Preservation Officer