HISTORIC AND DESIGN REVIEW COMMISSION September 21, 2016 Agenda Item No: 3

HDRC CASE NO:	2016-366
ADDRESS:	131 W MULBERRY AVE
LEGAL DESCRIPTION:	NCB 1768 BLK 3 LOT 10 & W 25 FT OF 11
ZONING:	R4 H
CITY COUNCIL DIST.:	1
DISTRICT:	Monte Vista Historic District
APPLICANT:	Richard Specia
OWNER:	Monica Dobie, Richard Daly
TYPE OF WORK:	New window fenestration

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to install three wood windows on the first floor east elevation with same profile as existing windows.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

6. Architectural Features: Doors, Windows, and Screens

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.

iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.

v. *Muntins*—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.

vi. *Replacement glass*—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.

FINDINGS:


- a. The home at 131 W Mulberry is a Prairie four-square with covered front porch, a second floor balcony and wood siding. It was identified as contributing in the 1975 designation survey.
- b. The home has several configuration of wood windows including 2 over 2, 1 over 1, and 8 over 4. The applicant is proposing to create 3 new window openings and install 3 wood windows: two 3 by 2 fixed windows and one 9 over 6. According to the Guidelines for Exterior Maintenance and Alterations 6.B., new openings should be compatible in size, scale, shape proportion and material; new windows should match the historic windows in terms of size, type configuration, material, form and appearance; muntins should not be false. Staff finds the proposed windows compatible with the existing historic windows, and thus consistent with the Guidelines.

RECOMMENDATION:

Staff recommends approval based on findings a and b with the following stipulation that the new windows feature clear glass, feature the existing exterior muntin profile and size, and be inset within to match the profile of those windows existing.

CASE MANAGER:

Lauren Sage





Flex Viewer

Powered by ArcGIS Server

Printed:Sep 13, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.













FRONT Porch



west side




EAST Side





New windows




Existing Mirror









SELECTING AN APPROPRIATE REPLACEMENT

6.B.iv. Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.



Recommended stipulations for replacement:

Individual sashes should be replaced where possible. Should a full window unit require replacement, inserts should

- Match the original materials;
- Maintain the original dimension and profile;
- Feature clear glass. Low-e or reflective coatings are not recommended for replacements;
- Maintain the original appearance of window trim or sill detail.

Details to avoid:



- Vinyl product changes the material
- Window is not recessed within frame
- Sash components do not feature traditional dimensions



- Track insert alters profile
- Meeting rails thicker than original
- Low-e coating alters hue and reflectivity



• Window trim and sill detail not consistent with original

SELECTING WINDOWS FOR NEW BUILDINGS

3.A.i. Complementary materials—Use materials that complement the type, color, and texture of materials traditionally found in the district. Materials should not be so dissimilar as to distract from the historic interpretation of the district...

Windows used in new construction should:

- Maintain traditional dimensions and profiles;
- Be recessed within the window frame. Windows with a nailing strip are <u>not</u> recommended;
- Feature traditional materials or appearance. Wood windows are most appropriate. Double-hung, block frame windows that feature alternative materials may be considered on a case-by-case basis;
- Feature traditional trim and sill details. Paired windows should be separated by a wood mullion.

The use of low-e glass is appropriate in new construction provided that hue and reflectivity are not drastically different from regular glass.

Examples in New Construction:

