HISTORIC AND DESIGN REVIEW COMMISSION February 01, 2017 Agenda Item No: 11

HDRC CASE NO: ADDRESS: LEGAL DESCRIPTION: ZONING: CITY COUNCIL DIST.: DISTRICT: APPLICANT: OWNER: TYPE OF WORK: 2016-522 841 E GUENTHER ST NCB 2917 BLK 6 LOT E IRR 67 FT OF S 43.43 FT OF 11 RM-4,H,RIO-4 1 King William Historic District Carlos Villarreal Carlos Villarreal Exterior modifications, hardscaping, addition

REQUEST:

The applicant is requesting conceptual approval to perform exterior modifications to the primary historic structure including altering each elevation, the height and roof form.

APPLICABLE CITATIONS:

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

2. Materials: Masonry and Stucco

A. MAINTENANCE (PRESERVATION)

i. Paint—Avoid painting historically unpainted surfaces. Exceptions may be made for severely deteriorated material where other consolidation or stabilization methods are not appropriate. When painting is acceptable, utilize a water permeable paint to avoid trapping water within the masonry.

ii. Clear area—Keep the area where masonry or stucco meets the ground clear of water, moisture, and vegetation. *iii. Vegetation*—Avoid allowing ivy or other vegetation to grow on masonry or stucco walls, as it may loosen mortar and stucco and increase trapped moisture.

iv. Cleaning—Use the gentlest means possible to clean masonry and stucco when needed, as improper cleaning can damage the surface. Avoid the use of any abrasive, strong chemical, sandblasting, or high-pressure cleaning method.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Patching—Repair masonry or stucco by patching or replacing it with in-kind materials whenever possible. Utilize similar materials that are compatible with the original in terms of composition, texture, application technique, color, and detail, when in-kind replacement is not possible. EIFS is not an appropriate patching or replacement material for stucco. *ii. Repointing*—The removal of old or deteriorated mortar should be done carefully by a professional to ensure that masonry units are not damaged in the process. Use mortar that matches the original in color, profile, and composition when repointing. Incompatible mortar can exceed the strength of historic masonry and results in deterioration. Ensure that the new joint matches the profile of the old joint when viewed in section. It is recommended that a test panel is prepared to ensure the mortar is the right strength and color.

iii. Removing paint—Take care when removing paint from masonry as the paint may be providing a protectant layer or hiding modifications to the building. Use the gentlest means possible, such as alkaline poultice cleaners and strippers, to remove paint from masonry.

iv. Removing stucco—Remove stucco from masonry surfaces where it is historically inappropriate. Prepare a test panel to ensure that underlying masonry has not been irreversibly damaged before proceeding.

A. MAINTENANCE (PRESERVATION)

i. Regular maintenance and cleaning—Avoid the build-up of accumulated dirt and retained moisture. This can lead to the growth of moss and other vegetation, which can lead to roof damage. Check roof surface for breaks or holes and flashing for open seams and repair as needed.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Roof replacement—Consider roof replacement when more than 25-30 percent of the roof area is damaged or 25-30 percent of the roof tiles (slate, clay tile, or cement) or shingles are missing or damaged.

ii. Roof form—Preserve the original shape, line, pitch, and overhang of historic roofs when replacement is necessary. *iii. Roof features*—Preserve and repair distinctive roof features such as cornices, parapets, dormers, open eaves with exposed rafters and decorative or plain rafter tails, flared eaves or decorative purlins, and brackets with shaped ends. *iv. Materials: sloped roofs*—Replace roofing materials in-kind whenever possible when the roof must be replaced. Retain and re-use historic materials when large-scale replacement of roof materials other than asphalt shingles is required (e.g., slate or clay tiles). Salvaged materials should be re-used on roof forms that are most visible from the public right-of-way. Match new roofing materials to the original materials in terms of their scale, color, texture, profile, and style, or select materials consistent with the building style, when in-kind replacement is not possible.

v. Materials: flat roofs—Allow use of contemporary roofing materials on flat or gently sloping roofs not visible from the public right-of-way.

vi. Materials: metal roofs—Use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Refer to Checklist for Metal Roofs on page 10 for desired metal roof specifications when considering a new metal roof. New metal roofs that adhere to these guidelines can be approved administratively as long as documentation can be provided that shows that the home has historically had a metal roof. *vii. Roof vents*—Maintain existing historic roof vents. When deteriorated beyond repair, replace roof vents in-kind or with one similar in design and material to those historically used when in-kind replacement is not possible. Historic Design Guidelines, Chapter 3, Guidelines for Additions

1. Massing and Form of Residential Additions

A. GENERAL

i. Minimize visual impact—Site residential additions at the side or rear of the building whenever possible to minimize views of the addition from the public right-of-way. An addition to the front of a building would be inappropriate. *ii. Historic context*—Design new residential additions to be in keeping with the existing, historic context of the block. For example, a large, two-story addition on a block comprised of single-story homes would not be appropriate. *iii. Similar roof form*—Utilize a similar roof pitch, form, overhang, and orientation as the historic structure for additions. *iv. Transitions between old and new*—Utilize a setback or recessed area and a small change in detailing at the seam of the historic structure and new addition to provide a clear visual distinction between old and new building forms.

B. SCALE, MASSING, AND FORM

i. Subordinate to principal facade—Design residential additions, including porches and balconies, to be subordinate to the principal façade of the original structure in terms of their scale and mass.

ii. Rooftop additions—Limit rooftop additions to rear facades to preserve the historic scale and form of the building from the street level and minimize visibility from the public right-of-way. Full-floor second story additions that obscure the form of the original structure are not appropriate.

iii. Dormers—Ensure dormers are compatible in size, scale, proportion, placement, and detail with the style of the house. Locate dormers only on non-primary facades (those not facing the public right-of-way) if not historically found within the district.

iv. Footprint—The building footprint should respond to the size of the lot. An appropriate yard to building ratio should be maintained for consistency within historic districts. Residential additions should not be so large as to double the existing building footprint, regardless of lot size.

v. Height—Generally, the height of new additions should be consistent with the height of the existing structure. The maximum height of new additions should be determined by examining the line-of-sight or visibility from the street. Addition height should never be so contrasting as to overwhelm or distract from the existing structure.

FINDINGS:

a. The structure at 841 E Guenther was constructed circa 1948 and features traditional architectural elements

including a side gabled roof, a shed front porch roof and front porch columns. The structure features many modifications as well as construction materials that are indicative of its age, including walls consisting primarily of concrete masonry units.

- b. Conceptual approval is the review of general design ideas and principles (such as scale and setback). Specific design details reviewed at this stage are not binding and may only be approved through a Certificate of Appropriateness for final approval.
- c. This case was reviewed by the Design Review Committee on September 27, 2016. At that meeting, committee members asked questions regarding the existing structure's condition, asked questions regarding existing site conditions, noted that the proposed modifications would bring a large change to the structure's massing and that the proposed modifications seemed to have a random aspect to them; that they seemed disconnected from each other. This case was reviewed by the DRC a second time on October 26, 2016. At that meeting, committee members noted that the proposed roof structure was unbalanced, that there appeared to be too much roofing, that the proposed dormers were creating elevations that are architecturally inappropriate and noted that the installation of wood windows is appropriate. This case was reviewed a third time by the DRC on November 9, 2016. At that meeting, committee members noted that the proposed carport should be appropriately scaled, that the front elevation should be retained as it currently exists, that new roof should not be tied to the historic roof structure, that the proposed balcony should not be tied to the historic roof structure and that the addition of a third dormer is not appropriate. This case was reviewed a fourth time by the DRC on January 10, 2017, where commissioners noted that the proposed new design is significantly improved over the previous design and noted that all columns needed definition including capitals and bases.
- d. HEIGHT, DORMER AND ROOFING MODIFICATIONS The applicant has proposed to alter the existing roof form by removing the existing roof's dormers and increase the ridge height to 26' 5". The applicant has proposed to maintain the side gable as well as front shed roof forms and the massing of the structure's first floor. While the applicant is modifying the structure's height and partially modifying the structure's form, staff finds the proposed new massing and roof forms appropriate.
- e. BALCONY CONSTRUCTION The applicant has proposed to remove the existing balcony on the southeast façade and construct a balcony that wraps from the southeast façade to the west façade. The applicant has also proposed to construct a double height front porch to feature massing similar to the wrap around balconies on the front façade. The proposed balcony and porch massing are generally consistent with historic architectural forms found in the King William Historic District. Staff finds the proposed alterations appropriate.
- f. ADDITION To the side of the existing structure, the applicant has proposed to construct an addition to feature a mudroom and storage closet. The applicant has proposed for the addition to feature a setback from the primary façade of the structure. The Guidelines for Additions state that additions should be sited at the side or rear of the building whenever possible to minimize view of the addition from the public right of way. The applicant has noted that due site constraints, the proposed addition must exist at this location. Staff finds that the applicant's proposed location appropriate given the proposed setback from the primary façade as well as the subordinate massing of the addition.
- g. EXTERIOR MODIFICATION The applicant has proposed to modify many of the structure's original window openings including the relocation of some openings and the resizing of others. The applicant has proposed openings that generally are comparable to those found throughout the King William Historic District. Staff finds the proposed openings generally appropriate.
- h. MATERIALS The applicant has proposed materials that are generally appropriate and consistent with the Guidelines. These materials include a standing seam metal roof, wood windows and doors.
- i. DRIVEWAY The applicant has proposed a new driveway on the west side of the lot to feature a ribbon strip driveway. The proposed design of the driveway does not lead to a parking location at the side or rear of the property. Staff finds that the installation of a driveway at this location facilitates front yard parking, which is inconsistent with the Guidelines.

RECOMMENDATION:

Staff recommends approval based on findings a through i with the following stipulations:

- i. That the applicant proposed an alternative parking location that will not result in front yard parking.
- ii. That the applicant provide a detailed landscaping plan prior to returning to the HDRC for final approval.

CASE MANAGER:

Edward Hall





Flex Viewer

Powered by ArcGIS Server

Printed:Dec 13, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





1911	SAMPARE A	AN APPENDED AND AND	1. 1.2.2	JAC SOLLIA	. 11A
	-			2 211 10 10 10 10 10 10 10 10 10 10 10 10 1	
1. 2. 2. 2. 2. 1. 2. 2. 2. 2.		Mark All as give at poste	$q_{i} \in [+, +, +, +]$	$a_{1}b_{1}A + b_{1}A = \frac{1}{2}A + \frac{1}{2}A$	^
		Historic and Design Review Commission			

CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION

Historic and Design Review Commission **Design Review Committee Report & Recommendation**

DATE: SEPTEMBER 17, 1016 HDRC Case#____

ADDRESS: 84 E GUENTHER Meeting Location: 140 S ALAND

APPLICANT: LAPLOS VILLAPPEAL

DRC Members present: MILHAEL GUARINO, DESIREE SALNON, ANNE-MARIE GRUBE

Staff present: ENWARA HALL

Others present:

REQUEST: EXTEDIOR MODIFICATIONS, MASSING MODIFICATIONS

COMMENTS/CONCERNS: MGL QUESTIONS RELADING EXISTING STEUCIDEE'S CONDUTION, QUESTIONS REGARDING EXISTING SITE CONDUTIONS, FRONT PARKING MAY BE ACCEPTABLE; VARIANCE MAY BE NEEDED BUT ONLY IF NO OTHER PARKING IS AVAILABLE, LAN EXISTING WEB LOT BE UTILIZED? PEOPOSED MODIFICATIONS BEING A BIG LHANGE TO THE EXISTING ELEVATIONS. THE POBLY EXTENSION HEAVILY MODIFIES THE EXISTING MASSING. WHAT IS THE OVERALL HEIGHT THAT THE ROOF PLAGE WILL BE PAISED/CHANGER? AMG: ALL PROPOSED MODIFICATIONS SHOULD BE LEARLY NOTED/SHOWN, A MATERIALS PAGE SHOULD BE PROVIDED. COMMITTEE RECOMMENDATION: **APPROVE**[] **DISAPPROVE**[] **APPROVE WITH COMMENTS/STIPULATIONS:** NO Action Totter Non contributing Status

Committée Chair Signature (or representative)

- AMG: ADDITIONAL DEL SESSIONS SHOULD BE CONSIDERED AS APPROACHING FINAL APPROVAL.
- MG! THE PEOPOSED MODIFICATIONS SEEM TO HAVE A PANDOM ASPECT -- THEY SEEM DISCONNECTED FROM EACH OTHER.

1.4 1. 4. 1. 1. Mar.

自己的复数形式 机合金

As and Westers

ADMARKE EXCEPTION REPORT FAINTRY ADMINISTRATING AMERICANING AMERI Americaning americaning americaning americaning americaning americaning americaning americaning americaning ameri

DITTE MARKARY REALTER ALLER

AND THE CONTRACT PRESS AND TO THE CONTRACT OF

SMALL A 199

Reference M. R. Selection and M. R. Strand, M. R. R. Strand, M. T. Strand, M. S. R. Strand, M. S. Strand, S. S



Historic and Design Review Commission Demolition and Designation Committee AESIGN REVIEW CONMITTEE

 DATE:
 <u>GLTOBER 16, 1016</u>
 HDRC Case#______

 ADDRESS:
 <u>841 E GUENTHER</u>
 Meeting Location:
 <u>1901 S ALANO</u>

 APPLICANT:
 <u>CAPLOS VILLAPPEAL</u>
 Meeting Location:
 <u>1901 S ALANO</u>

 DRC Members present:
 <u>NESIPEE SALMON, DANUEL LAZAPINE</u>
 Staff present:
 <u>EDWAPA HALL</u>

 Others present:
 <u>Others present:</u>
 <u>Meeting Location</u>
 <u>Meeting Location</u>

REQUEST: EXTERIOR MODEFICATIONS, LANASCATING

COMMENTS/CONCERNS: AL' QUESTIONS REGARDING THE EXISTING FOUNDATION,

DE: SUCCEPTIONS ON THE LAYOUT OF PEBENTATION ADJUMENTS, AL! THE

TROPOSED ROOF IS BEENERING OFF BALANCE; THERE APPEARS TO

BE TOO MULH ROOF. QUESTIONS REGARDING SQUARE FOOTAGE. THE

VARIOUS MORMER ELEMENTS ARE LERATING ELEMATIONS THAT ARE

ARCHITELTURALLY WAPPEOPRIATE, QUESTIONS REGARDING WINDOW

MATERIALS -- WOOL WINDOWS ARE APPROPRIATE.

COMMITTEE RECOMMENDATION: APPROVE [] DISAPPROVE [] APPROVE WITH COMMENTS/STIPULATIONS:

DESIDER SAMON

Committee Chair Signature (or representative)

10.26.206 Date



Historic and Design Review Commission Design Review Committee Report & Recommendation

DATE: NOVEMBER 9, JONG HDRC Case#						
ADDRESS: 841 E GUENTHER Meeting Location: 1901 S ALANO						
APPLICANT: CARLOS VILLARREAL						
DRC Members present: TIM CONE						
Staff present: ENVARIA HALL						
Others present:						
REQUEST: EXTERIOR MONFICATIONS, ADALTION						
COMMENTS/CONCERNS: IL QUESTIONS REGARAING PROPOSED MODIFICATIONS						
TO THE EXISTING FLOOPPLAN, LARPORT STRUCTURE SHOULD BE						
SEPARATELY SCALE/MASSEL - SET BACK FROM FRONT FACADE.						
MAIN ELEVATION SHOULD BE RETAINED, ADD MASSING AT MEN						
EACH SIDE NEW BOOFS SHOULD NOT BE TIED TO THE HISTOPIC						
BOOF, BALLONY SHOULD NOT BE TIED TO THE INSTORIC POOF. THE						
ADDITION OF A THIRD DORMER IS THE NOT APPOPRIATE WITHIN						
A HISTORIC AUSTRICT.						

COMMITTEE RECOMMENDATION: APPROVE [] DISAPPROVE [] APPROVE WITH COMMENTS/STIPULATIONS:

Committee Chair Signature (or representative)



Historic and Design Review Commission Design Review Committee Report & Recommendation

C Case#
•

ADDRESS: <u>SHIE GUENTHER</u> Meeting Location: <u>1961 S ALAMO</u>

APPLICANT: CAPLOS VILLAPPEAL

DRC Members present: MILHAEL GUARINO, JOHN LAFFOON

Staff present: EDWARD HALL

Others present:_____


REQUEST: EXTERIOR MORIFILATIONS, ADDITION

COMMENTS/CONCERNS: Mo: QUESTIONS DEGARDING PROPOSED MATERIALS. M.G. IN THE PROPOSED ABJOND; CONCERN WAS WITH THE PROPOSED MODIFIED MADELING DORMERS. THE LURDENT DESIGN DOES NOT PRATURE THIS ISSUE. JL: THE PROPOSED NEW DESIGN IS SIGNIFICANTLY IMPROVED OVER THE PREVIOUS DESIGN. MG: ALL COLUMNS NEED SOME DEFINITION; LAPITALS AND BASES ARE NEEDED - GXG ALMENSION IS APPROPRIATE.


COMMITTEE RECOMMENDATION: APPROVE [] DISAPPROVE [] APPROVE WITH COMMENTS/STIPULATIONS:

Committee Chair Signature (or representative)

10 Date




SECOND FLOOR PLAN (2)






1/4"=1'-0"


















24 GA. STANDING SEAM ROOF

METAL ROOFING UNDER -- LAYMENT OVER 5/8 DECKING TYP. 2 - 24 GA. GALV. IRON FLASHING. PNT. @ EXPOSED

2x6 FASCIA BOARD PEFRORATED HARDIE SOFFIT PANELS - 1x2 MOULDING 1x6 CEDAR BOARD TRIM 6 x 6 S4S STRUCTURAL WOOD COLUMN

2x6 RAIL CAP

2x4 SUB RAIL


2x2 BALUSTER

2x4 BOTTOM RAIL 1x6 CEDAR BOARD TRIM

-- Beam as required

1x6 CEDAR BOARD TRIM 6 x 6 S4S STRUCTURAL WOOD COLUMN

1x6 CEDAR BOARD TRIM






















Left Elevation (Facing Eagleland)





Left Elevation (Facing Eagleland)

Left Elevation (Facing Eagleland)

