HISTORIC AND DESIGN REVIEW COMMISSION

December 06, 2017

HDRC CASE NO: 2017-619 ADDRESS: 204 NOLAN

LEGAL DESCRIPTION: NCB 557 BLK 40 LOT S IRR 175.9 FT OF 1 & S 181.9 FT OF 2

ZONING: D, HS CITY COUNCIL DIST.: 2

DISTRICT: Healy-Murphy Historic District **LANDMARK:** Dullnig / Schneider House

APPLICANT: Fernando Aguilar/Slay Architecture

OWNER: City of San Antonio

TYPE OF WORK: Gutter installation on front porch

APPLICATION RECEIVED: November 8, 2017 **60-DAY REVIEW:** January 7, 2018

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to removal an original, integral porch gutter and replace with a surface mounted gutter and downspouts. This modification includes the removal of the existing, decorative fascia and replacement with a flat profiled fascia.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

7. Architectural Features: Porches, Balconies, and Porte-Cocheres

A. MAINTENANCE (PRESERVATION)

- *i. Existing porches, balconies, and porte-cocheres*—Preserve porches, balconies, and porte-cocheres. Do not add new porches, balconies, or porte-cocheres where not historically present.
- *ii.* Balusters—Preserve existing balusters. When replacement is necessary, replace in-kind when possible or with balusters that match the originals in terms of materials, spacing, profile, dimension, finish, and height of the railing.
- *iii. Floors*—Preserve original wood or concrete porch floors. Do not cover original porch floors of wood or concrete with carpet, tile, or other materials unless they were used historically.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- *i. Front porches*—Refrain from enclosing front porches. Approved screen panels should be simple in design as to not change the character of the structure or the historic fabric.
- *ii. Side and rear porches*—Refrain from enclosing side and rear porches, particularly when connected to the main porch or balcony. Original architectural details should not be obscured by any screening or enclosure materials. Alterations to side and rear porches should result in a space that functions, and is visually interpreted as, a porch.
- *iii.* Replacement—Replace in-kind porches, balconies, porte-cocheres, and related elements, such as ceilings, floors, and columns, when such features are deteriorated beyond repair. When in-kind replacement is not feasible, the design should be compatible in scale, massing, and detail while materials should match in color, texture, dimensions, and finish.
- *iv.* Adding elements—Design replacement elements, such as stairs, to be simple so as to not distract from the historic character of the building. Do not add new elements and details that create a false historic appearance.
- v. Reconstruction—Reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns.

FINDINGS:

- a. The historic structure at 204 Nolan was constructed circa 1895 and is commonly known as the Dullnig/Schneider House. The structure features Folk Victorian architectural elements as well as a plaster coated limestone façade.
- b. The applicant is requesting a Certificate of Appropriateness for approval to removal an original, integral porch gutter and replace with a surface mounted gutter and downspouts. This modification includes the removal of the existing, decorative fascia and replacement with a flat profiled fascia. The Guidelines for Exterior Maintenance

and Alterations 7. notes that porches and porch elements are to be repaired to match the existing. The removal of the integral gutter and decorative fascia would result in the removal of a character defining feature and is not consistent with the Guidelines. Staff recommends that the existing, integral gutter as well as decorative parapet remain as original constructed. Repairs are eligible for administrative approval.

RECOMMENDATION:

Staff does not recommend approval based on finding b. If the HDRC finds that circumstances such as maintenance issues warrant approval to remove the integral gutter, then staff finds the simple, half-round gutter to be an acceptable alternative solution.

CASE MANAGER:

Edward Hall



Phone: 210-736-3009 Fax: 210-734-6401

November 6, 2017

RE: Dullnig Structure Stabilization Scope of Work 204 Nolan Street San Antonio, TX 78202


The intent of the proposed scope of work is to bring this City of San Antonio owned building that has been identified as a Vacant Building by the Office of Historic Preservation up to the minimum maintenance requirements as outlined in City of San Antonio Ordinance No. 2014-06-19-0461. The scope of work can be summarized as stabilizing & weatherproofing existing Historic Building & Addition, and demolishing Non-Historic Additions, except for a toilet room addition.

Existing Condition	Proposed
Cement Plaster, apprx. 3/4" thick	Remove and replace with new 3/4" Portland Cement-
	Based Plaster. Refer to attached specification.
Limestone Masonry	Remove cement plaster, re-point limestone and
	stabilize movement, install new 3/4" cement plaster,
	painted to match existing.
Asphalt Shingle Roof	Remove and replace with Prefinished Standing Seam
	Metal Roof
Metal Porch Roof	Remove and replace with Prefinished Standing Seam Metal Roof
Porch Roof Framing	Demo, salvage and rebuild.
Existing Half Round Gutters at	Replace with new half-round gutter profile.
eaves of Original Historic	
Residence	
Existing Round Downspouts	Replace with new round downspouts.
Integral Gutter at Front Porch	Remove built in porch gutter, replace with surface
	mounted gutter and downspouts. This includes
	replacing existing decorative fascia profile with a flat
	profile to provide proper attachment for new surface
	mounted gutter.
Wood Front Porch Columns	Reinforce porch columns with post.
Front Porch Decorative Wood	Reconstruct missing brackets and decoration based on
Brackets & Trim	existing profiles. Repaint to match existing.
Porch Decking	Replace with new tongue and groove deck planks,
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	painted to match existing.
Wood Windows – West Side	Reconstruct to match existing
Wood Windows – North, South &	Patch and repair existing windows. Repaint to match
East Sides	existing.
Window AC Units & Cages	Remove entirely.
Wood Shutters	Reconstruct and repaint to match existing.
Wood Siding - Non Historic	Salvage wood siding for reinstallation at new exterior
Addition	wall to enclose the portion of the Non-Historic
	Addition that is remaining. Remove and salvage
	wood siding from Non-Historic Addition that is being
	demolished. Reinstall salvaged wood siding at new




Phone: 210-736-3009 Fax: 210-734-6401

	exterior wall to enclose the portion of the Non-Historic Addition that is remaining. The profile of this siding is #105 which is different from the siding used on the Historic Addition, so there will be a distinction between the historic material and the non-historic material.
Unlevel Cedar Piers at Historic	Foundation of wood framed Historic Addition to be
Addition	made level with new concrete piers as required.
Non-Historic Building Addition	Demolish easternmost portion. Portion of Non-Historic Addition to remain to provide a toilet room. A portion of the Non-Historic Addition is to remain to provide access to an existing toilet room. If all of the Non-Historic Addition were to be removed, this would leave the building without any toilet facilities and would make the building non-occupiable.
Non-Historic Rear Porch & Ramp	Demolish entirely. Provide new wood temporary stairs at new exterior entrance.
Historic Wood Doors	Make secure and install interior security mesh. Historic wood doors and transoms that are currently on the interior of the building were at one time exterior doors. With the demolition of the non-historic portion of the addition, these doors will become exterior again.



The record of this drawing is on file at the offices of Slay Architecture, 123 Altgelt, San Antonio, Texs. This document is released for the pupose of refernce, coordination, and/or facility management under authority of the named professional, registration number and date on the seal affixed above. COPYRIGHT 2000-2014, Slay Architecture. This document was prepared using computer assisted design and drafting equipment and saved on managing media. Neither the printed document not the managing media may be altered or amended.



HALF ROUND GUTTERS



STANDING SEAM METAL ROOF





EXISTING #105 SIDING PROFILE

EXISTING BEVELED SIDING PROFILE

SELECTED PAINT COLORS TO BE SUBMITTED AND APPROVED AT A LATER TIME. ALL COLORS TO MATCH EXISTING.

PAINT

PROJECT NO.: 16016B

COLOR SELECTION

DATE: 10/26/17

DULLNIG STRUCTURE STABILIZATION CITY OF SAN ANTONIO 204 NOLAN STREET, SAN ANTONIO, TEXAS



PRELIMINARY This Drawing indicates the design concept and the general scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction. REGISTERED ARCHITECT MADELINE ANZ SLAY LICENSE NO. 16442 Date: 10/26/17

9 OF 9



- REPLACE MAIN HOUSE ASPHALT SHINGLE ROOF ON WOOD FRAME ADDITION WITH NEW STANDING SEAM METAL ROOF
- LEVEL & STABILIZE FOUNDATION OF HISTORIC WOOD FRAME ADDITION
- PAINT HISTORIC WOOD SIDING
- SALVAGE TOILET ROOM PORTION OF NON-HISTORIC WOOD FRAME ADDITION



DEMOLISH NON-HISTORIC WOOD FRAME ADDITION INCLUDING PORCH AND RAMP

PRELIMINARY
This Drawing indicates the design concept and the general scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction.
REGISTERED ARCHITECT
MADELINE ANZ SLAY
LICENSE NO. 16442
Date: 10/26/17

3 OF 9

PROJECT NO.: 16016B


DATE: 10/26/17

EXISTING CONDITIONS

DULLNIG STRUCTURE STABILIZATION CITY OF SAN ANTONIO


204 NOLAN STREET, SAN ANTONIO, TEXAS





PATCH & REPAIR EXISTING WOOD WINDOW, PAINT

REPLACE CEMENT PLASTER WITH NEW, PAINT (TYP.)



REPLACE PORCH ROOF FRAMING INCLUDING METAL ROOF

RECONSTRUCT MISSING BRACKET/DECORATION

REINFORCE PORCH COLUMN WITH POST. SALVAGE COMPONENTS FOR REINSTALLATION, (TYP.)

REPLACE WOOD DECK . PLANKS WITH NEW, PAINT

PRELIMINARY

This Drawing indicates the design concept and the general scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction. REGISTERED ARCHITECT MADELINE ANZ SLAY LICENSE NO. 16442 Date: 10/26/17

4 OF 9

PROJECT NO.: 16016B

DATE: 10/26/17

EXISTING CONDITIONS


DULLNIG STRUCTURE STABILIZATION CITY OF SAN ANTONIO

204 NOLAN STREET, SAN ANTONIO, TEXAS



SAN ANTONIO 123 Altgelt Ave San Antonio, Texas 78201 T: (210) 736-3009 LAREDO 9901 McPherson Ave, Ste 104 Laredo, Texas 78045

T: (956) 791-0405




REPLACE CEMENT
PLASTER WITH NEW, PAINT
(TYP.)

REMOVE AC UNITS & CAGES, (TYP.)

RECONSTRUCT WOOD WINDOWS AND SHUTTERS. SALVAGE EXISTING COMPONENTS FOR REINSTALLATION (TYP.) —

RE-POINT MASONRY & STABILIZE MOVEMENT, (TYP.)





RECONSTRUCT MISSING BRACKET/DECORATION TO MATCH EXISTING SIZE & PROFILE

a completed contract doc.

scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction. REGISTERED ARCHITECT MADELINE ANZ SLAY

PRELIMINARY
This Drawing indicates the design concept and the general

LICENSE NO. 16442 Date: 10/26/17

5 OF 9

PROJECT NO.: 16016B


DATE: 10/26/17

EXISTING CONDITIONS

DULLNIG STRUCTURE STABILIZATION CITY OF SAN ANTONIO

204 NOLAN STREET, SAN ANTONIO, TEXAS





REPLACE MAIN HOUSE ASPHALT SHINGLE ROOF WITH NEW STANDING SEAM METAL ROOF


REPLACE PORCH ROOF FRAMING INCLUDING METAL ROOF

REPLACE GUTTER & DOWNSPOUTS, (TYP.)

REINFORCE PORCH COLUMN WITH POST. SALVAGE COMPONENTS FOR REINSTALLATION, (TYP.)

REPLACE CEMENT PLASTER WITH NEW, PAINT (TYP.)

REPLACE WOOD DECK PLANKS WITH NEW, PAINT



REMOVE AC UNITS & CAGES, (TYP.)

REPLACE CEMENT PLASTER WITH NEW, PAINT (TYP.)

RECONSTRUCT WOOD WINDOWS AND SHUTTERS. SALVAGE EXISTING COMPONENTS FOR REINSTALLATION (TYP.)

RE-POINT MASONRY & STABILIZE MOVEMENT, (TYP.)

PRELIMINARY

This Drawing indicates the design concept and the general scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction. REGISTERED ARCHITECT MADELINE ANZ SLAY LICENSE NO. 16442 Date: 10/26/17

2 OF 9

PROJECT NO.: 16016B


DATE: 10/26/17

EXISTING CONDITIONS

DULLNIG STRUCTURE STABILIZATION S


204 NOLAN STREET, SAN ANTONIO, TEXAS





REPLACE WOOD DECK PLANKS WITH NEW, PAINT

REINFORCE PORCH COLUMN WITH POST. SALVAGE COMPONENTS FOR REINSTALLATION, (TYP.)



REPLACE BUILT-IN GUTTER WITH HALF ROUND METAL GUTTER AND ROUND DOWNSPOUT

REPLACE PORCH ROOF FRAMING INCLUDING METAL ROOF WITH NEW METAL ROOF

PRELIMINARY

This Drawing Indicates the design concept and the general scope of the project. It is not yet a completed contract document. Not for regulatory approval, permitting or construction. REGISTERED ARCHITECT MADELINE ANZ SLAY LICENSE NO. 16442 Date: 10/26/17

6 OF 9

PROJECT NO.: 16016B

DATE: 10/26/17

EXISTING CONDITIONS

DULLNIG STRUCTURE STABILIZATION CITY OF SAN ANTONIO

204 NOLAN STREET, SAN ANTONIO, TEXAS

