HISTORIC AND DESIGN REVIEW COMMISSION July 18, 2018

HDRC CASE NO:	2018-333
ADDRESS:	131 ADAMS ST
LEGAL DESCRIPTION:	NCB 931 BLK 1 LOT 15
ZONING:	RM-4, H
CITY COUNCIL DIST.:	1
DISTRICT:	King William Historic District
APPLICANT:	Beverly Bunn/Beaver Meadows II, LLC
OWNER:	Beverly Bunn, Beverly Bunn/Beaver Meadows II, LLC
TYPE OF WORK:	Installation of a mansard roof over an existing porch roof
APPLICATION RECEIVED:	June 25, 2018
APPLICATION RECEIVED:	June 25, 2018
60-DAY REVIEW:	August 24, 2018

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to remove the existing, front porch balcony railing and install a mansard roof featuring a black standing seam metal roof.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance

3. Materials: Roofs

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

vi. Materials: metal roofs—Use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Refer to Checklist for Metal Roofs on page 10 for desired metal roof specifications when considering a new metal roof. New metal roofs that adhere to these guidelines can be approved administratively as long as documentation can be provided that shows that the home has historically had a metal roof.

7. Architectural Features: Porches, Balconies and Porte-Cocheres

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

iv. Adding elements—Design replacement elements, such as stairs, to be simple so as to not distract from the historic character of the building. Do not add new elements and details that create a false historic appearance. *v. Reconstruction*—Reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns.

FINDINGS:

- a. The historic structure at 131 Adams was constructed circa 1910 and is found on the 1912 Sanborn Map. The structure originally featured a double height, wrap around front porch. The original design has been modified to its current state which includes a uniform front facade with a centered, entrance porch with balusters above the porch roof. These modifications which exist presently are found on the 1951 Sanborn Map.
- b. PORCH MODIFICATION The applicant has proposed to remove the existing balusters above the existing porch roof and install a mansard roof to feature a black standing seam metal roof. The Guidelines for Exterior Maintenance and Alterations 7.B.iv. notes that new elements and details should not be added that create a false historic appearance. While the existing porch roof and balusters are not original, mansard roofs are not found commonly throughout the King William Historic District and the proposed installation on the historic structure's existing porch roof is not consistent with the Guidelines. A modification that would create a simple, low pitch

shed roof above the existing roof to accommodate appropriate water displacement would be appropriate.


c. ROOFING MATERIAL – The applicant has proposed to install a black, standing seam metal roof. The Guidelines for Exterior Maintenance and Alterations, Checklist for Metal Roofs notes that a standard galvalume finish, or gray color should be used unless historic evidence of an alternate roofing color exists. Staff finds the proposed roofing color to be inconsistent with the Guidelines.

RECOMMENDATION:

Staff does not recommend approval based on finding b and c.

CASE MANAGER:

Edward Hall





Flex Viewer

Powered by ArcGIS Server

Printed:Jul 09, 2018


The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.



1912 SANBORN MAP NOTING ORIGINAL PORCH DESIGN




1951 SANBORN MAP NOTING MODIFIED PORCH DESIGN (CURRENT)




















SW 7103 Whitetail 261-C1

SW 6255 234-C3 Morning Fog



251-C1 SW 6258 **Tricorn Black**

Light reflective value: 3 (dark) Valor de reflectancia de luz: 3 (oscuro)

Complementary colors Colores complementarios SW 6252 Ice Cube SW 0050 Classic Light Buff SW 9052 Blithe Blue

SHERWIN-WILLIAMS. sherwin-williams.com 1-800-45HERWIN

©2015 The Sherwin-Williams Company Samples approximate the actual paint color. Las muestras se aproximan al color real de la pintura.



234-C3 SW 6255 Morning Fog

Light reflective value: 42 (medium) Valor de reflectancia de luz: 42 (intermedio)

Complementary colors Colores complementarios SW 6252 Ice Cube SW 7006 Extra White

SW 6169 Sedate Gray



SHERWIN-WILLIAMS.

sherwin-williams.com 1-800-4SHERWIN

©2015 The Sherwin-Williams Company

Samples approximate the actual paint color. Las muestras se aproximan al color real de la pintura.



SW 7103 Whitetail 261-C1

Light reflective value: 86 (light) Valor de reflectancia de luz: 86 (claro)

Complementary colors Colores complementarios SW 9084 Cocoa Whip SW 9085 Touch of Sand

SHERWIN-WILLIAMS. sherwin-williams.com 1-800-4SHERWIN ©2015 The Sherwin-Williams Company Samples approximate the actual paint colo: Las muestras se aproximan al color real de la pinturo.

CS 10/15 6505-00978 CS 10/15