

## HISTORIC AND DESIGN REVIEW COMMISSION

September 19, 2018

**HDRC CASE NO:** 2018-461  
**ADDRESS:** 603 KAMPMANN BLVD  
**LEGAL DESCRIPTION:** NCB 6824 BLK LOT E 75 FT OF 18  
**ZONING:** R-6, H  
**CITY COUNCIL DIST.:** 7  
**DISTRICT:** Monticello Park Historic District  
**APPLICANT:** Daniel Campo/DC Civil Construction LLC  
**OWNER:** Daniel Campo/DC Civil Construction LLC  
**TYPE OF WORK:** Window Replacement, removal of window awnings and burglar bars  
**APPLICATION RECEIVED:** August 29, 2018  
**60-DAY REVIEW:** October 28, 2018

### REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1) Replace ten wood windows with vinyl windows.
- 2) In-kind repair of all remaining wood windows and trim.
- 3) Remove all metal window awnings and burglar bars.

### APPLICABLE CITATIONS:

6. Architectural Features: Doors, Windows, and Screens

#### A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- ii. *Doors*—Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- iv. *Screens and shutters*—Preserve historic window screens and shutters.
- v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.

#### B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
- ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. *Glazed area*—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. *Muntins*—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.
- vi. *Replacement glass*—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. *Non-historic windows*—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.
- viii. *Security bars*—Install security bars only on the interior of windows and doors.
- ix. *Screens*—Utilize wood screen window frames matching in profile, size, and design of those historically found when

the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.

x. Shutters—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

## **FINDINGS:**

- a. The primary structure at 603 Kampmann was constructed circa 1939 and contributes to the Monticello Park Historic District. The single-family two-story structure features a primary turned-gable with a crossed street-facing gable and one-story window bay, an exterior stone chimney, stonework in the inset porch, wood windows, asbestos siding, and composition shingle roof. The structure features a number of additions with generally consistent window dimensions and trim, siding, and roof form but varying height and locations.
- b. On a site visit conducted on August 21, 2018, staff found that the removal of window awnings and the installation of new vinyl windows had occurred prior to the issuance of a Certificate of Appropriateness. The applicant submitted a request to be heard at an HDRC hearing on August 29, 2018. A \$500 post-work applicant fee has not been paid at this time.
- c. **WINDOW REPLACEMENT**
  - i. **EXISTING WINDOWS** – The structure features predominantly one-over-one wood windows, which have been exposed with the removal of the metal window awnings. According to the applicant, the front bay window has been replaced with a vinyl window previously featured a metal casement window with divided lights and with hinged opening panes. According to the applicant, the front facing window setback on the side addition that had been replaced with a vinyl picture window previously featured a wood picture window. Staff is not able to verify the previous conditions of those windows prior replacement because they have been discarded by the applicant.
  - ii. **WINDOW REPLACEMENT** – The applicant has proposed to remove a number of wood windows to install nine (9) new vinyl windows and one (1) sliding door. The Guidelines for Exterior Maintenance and Alterations 6.B.iv. notes that window replacement should only be considered when the original windows are deteriorated beyond repair. The applicant noted that the removed windows were rotted, but staff did not receive supporting evidence to verify at this time.
  - iii. **NEW WINDOWS** – The applicant has proposed to install two (2) large picture windows, one in the gabled front bay and on the setback side addition. The applicant has also proposed to install in the rear of the property one (1) vinyl sliding door, four (4) one-over-one vinyl windows, and three (3) linear vinyl block windows. The Guidelines for Exterior Maintenance and Alterations 6.B.iv. notes that new windows are to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and details. Staff finds that the proposed windows are not compatible in style or materials with the original windows.
- d. **WINDOW REPAIR** – The applicant has proposed to repair the remaining wood windows, excluded from the proposed vinyl replacements. Staff finds that in-kind repair is eligible for administrative approval if the property has no outstanding violations or pending design.
- e. **WINDOW AWNINGS** – The applicant has proposed to remove the non-original window awnings. Staff finds that removal of non-historic elements is eligible for administrative approval if the property has no outstanding violations or pending design.

## **RECOMMENDATION:**

- i. Staff does not recommend window replacement based on finding c. Staff recommends the applicant provide support evidence that the windows were deteriorated beyond repair and an accurate inventory of the previous fenestration condition of the house prior to consideration of replacement material. New windows should be consistent with the Guidelines and adhere to the standard stipulations: *Meeting rails that are no taller than 1.25" and stiles no wider than 2.25". White manufacturer's color is not allowed, and color selection must be presented to staff. There should be a minimum of two inches in depth between the front face of the window trim and the front face of the top window sash. This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness. Window trim must feature traditional dimensions and an architecturally appropriate sill detail. Window track components must be painted to match the window trim or concealed by a wood window screen set within the*


- opening.*
- ii. Staff recommends window repair and removal of non-original window awnings based on findings c and d with the stipulation that the applicant address the outstanding violation of window replacement prior to approval.

**CASE COMMENT:**

On a site visit conducted on August 21, 2018, staff found that the removal of window awnings and the installation of new vinyl windows had occurred prior to the issuance of a Certificate of Appropriateness. The applicant submitted a request to be heard at an HDRC hearing on August 29, 2018. A \$500 post-work applicant fee has not been paid at this time.

**CASE MANAGER:**

Huy Pham



603 Kampmann

Powered by ArcGIS Server

Printed: Sep 12, 2018

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





Kampmann Blvd

Shearer Blvd

603 Kampmann  
Boulevard

Kampmann Blvd

Kampmann Blvd

Kampmann Blvd

West Summit

West Summit

West Summit

Wedding, Paper, I

Kampmann Blvd




Google





603 Kampmann  
Boulevard



Google



628 Kampmann Blvd  
San Antonio, Texas

Google, Inc.

Street View - Dec 2014






628 Kampmann Blvd  
San Antonio, Texas

Google, Inc.

Street View - Jun 2016




©2016 Google

Google







603 KAMPMANN

## 603 Kampmann Blvd



Front Window 6' x 6' Living Room



Front Window 6' x 6' Living Room





Front Window 7' x 5' ' Master Bed-Room





Back Windows 4' x 6' Master Bed-Room

Patio Sliding Door 5'x7' Master Bed-Room



Back Windows 4' x 6' Master Bed-Room

Block Windows 6" x 40" Master Bathroom

Back Window 2' x 3' Master Bathroom





Back Windows 4' x 6' Master Bed-Room

Block Windows 6" x 40" Master Bathroom

Back Window 2' x 3' Master Bathroom

Back Window 4' x 3' Master Bathroom

## Specifications

---

### Details

Exterior Color/ Finish

White

Exterior Color/Finish Family

White

Features

Argon Gas Insulated,Integrated Nail Fin

Frame Material

Vinyl

Frame Type

Nail Fin

Glass Type

Energy Efficient Glass,Low-E Glass

Glazing Type

Double-Pane

Grid Pattern

None

Grid Pattern

No Grid

Grille Type

No Grille

Hardware Color/Finish Family

White

Included

Screen

Interior Color/Finish Family

White

Lock Type

Cam Action

Lock Type

Cam Action

Number of Grids

No Grid

Number of Locks

1

Product Weight (lb.)

28lb

Returnable

90-Day

Solar Heat Gain Coefficient

.21

U-Factor

0.3

Window Type

Double Hung

Window Type

Double Hung

Window Use Type

New Construction,Replacement



## Warranty / Certifications

Energy Star Qualified

North-Central, South-Central, Southern

Manufacturer Warranty

Lifetime Limited



## Investigation Report

### Property

Address	603 Kampmann Blvd
District/Overlay	Monticello Park
Owner Information	DC Civil Construction LLC

### Site Visit

Date	08/20/2018
Time	08:43 AM (-5 GMT)
Context	citizen report
Present Staff	Huy Pham
Present Individuals	Contractor(s)
Present Companies	Rusted Belt (2 contractors)
Types of Work Observed	Exterior Maintenance and Alterations
Amount of Work Completed	75%
Description of work	Removal of metal window awnings and replacement of front window with large vinyl picture window.
Description of interaction	Staff notified the two contractors on site that all work on the exterior of the property requires a Certificate of Appropriateness because of historic designation. The contractors explained that the front window was deteriorated. Staff spoke with the owner on the phone who will contact OHP the following day.

### Action Taken

Violation Type	No Certificate of Appropriateness (Code 35-451a)
OHP Action	Spoke with property owner, Spoke with contractor(s) and/or crew
Deadline to contact office	08/21/2018
Will post-work application fee apply?	Yes

### Documentation

Photographs	
-------------	--



## Investigation Report

	 A photograph of a historic building's exterior. The building has white siding and a prominent stone chimney. A metal railing runs along the side of the building. A black sign with white text is visible on the railing. The photo is dated August 20, 2018 at 4:11 PM, 609 Kampmann Blvd, San Antonio, TX 78207, United States. <p>August 20, 2018 at 4:11 PM 609 Kampmann Blvd San Antonio, TX 78207 United States</p>	
	08/21/2018 08:48 AM	