HISTORIC AND DESIGN REVIEW COMMISSION

October 17, 2018

HDRC CASE NO: 2018-520

ADDRESS: 2020 W HUISACHE AVE **LEGAL DESCRIPTION:** NCB 1953 BLK LOT 23

ZONING: R-6 H CITY COUNCIL DIST.: 7

DISTRICT: Monticello Park Historic District

APPLICANT: Andrew Gooding

OWNER: Five Missions Properties
TYPE OF WORK: Window replacement
APPLICATION RECEIVED: September 28, 2018
60-DAY REVIEW: November 27, 2018

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to replace approximately 15 one over one wood windows with new one over one white vinyl windows.

APPLICABLE CITATIONS:

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- ii. Doors—Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- iv. Screens and shutters—Preserve historic window screens and shutters.
- v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
- ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. Glazed area—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. *Muntins*—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.
- vi. *Replacement glass*—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. *Non-historic windows*—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.

FINDINGS:

- a. The primary structure located at 2020 W Huisache is 1-story single family home constructed in approximately 1935 with Tudor and Craftsman influences. The home features a side gable configuration with a dominant sloping roof on the front facade, one over one wood windows, and a full-length front porch with four supports. The structure is contributing to the Monticello Park Historic District.
- b. EXISTING WINDOWS: CONDITION The applicant has provided multiple photographs of the existing windw condition. Several openings are boarded up and do not contain sashes. Other windows exhibit severe deterioration, including dropped meeting rails and rotted bottom rails. A few windows in the photographs are in repairable condition based on staff's observation. Based on Google Maps images, several windows were covered with aluminum exterior screens or by the front porch, which may contribute to better sash conditions in these areas. Staff finds that several windows are eligible for replacement and some are repairable based on the photographs.
- c. WINDOW REPLACEMENT According to the Guidelines for Exterior Maintenance and Alterations 6.A.iii. and 6.B.iv., in kind replacement of windows is only appropriate when the original windows are beyond repair. As noted in finding b, staff finds several windows eligible for replacement, but requires additional photo documentation or a site visit to confirm which windows are eligible. Staff finds a few of the windows eligible for repair based on their condition. The applicant is requesting to replace the windows with new white vinyl windows. Based on the Guidelines, windows should be replaced in-kind. Staff finds that windows that are approved for replacement based on their deteriorated condition should be replaced with wood windows to be consistent with the Guidelines.


RECOMMENDATION:

Staff recommends approval of the window replacement based on findings a through c with the following stipulations:

- i. That the applicant retains the windows that are not deteriorated beyond repair as determined by staff. Photographic evidence or a site visit, in conjunction with an updated window schedule, is required to delineate which windows will be restored and which will be replaced. If the applicant believes all windows to be deteriorated beyond repair, the aforementioned site visit and updated documentation may be submitted for staff review and approval prior to the issuance of a Certificate of Appropriateness.
- ii. That the replacement windows be wood in lieu of the proposed vinyl. The applicant must submit a final window specification for the proposed windows to staff for review and approval. Meeting rails must be no taller than 1.25" and stiles no wider than 2.25". There should be a minimum of two inches in depth between the front face of the window trim and the front face of the top window sash. This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness. Window trim must feature traditional dimensions and architecturally appropriate sill detail. Window track components must be painted to match the window trim or concealed by a wood window screen set within the opening.

CASE MANAGER:

Stephanie Phillips





Flex Viewer

Powered by ArcGIS Server

Printed:Oct 11, 2018

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.






























Single Hung Vinyl Window with Nail Fin

Ventana de vinilo de guillotina sencilla, con aleta claveda



Bottom sash tills for easy cleaning

El bestidor interior se inclina hacia adentro y puede quitarse para fácil



To learn more about this

NEW CONSTRUCTION

MODEL Modelo

24 x 36

UNIT DIMENSIONS (WIDTH x HEIGHT) Sineralones de la unio (Ancho × Alto)

ROUGH OPENING

Abertura sin acabado FRAME TYPE/DEPTH

GRILLES Sejiller COLOR

HARDWARE INSECT SCREEN GLASS TYPE WARRANTY

derectle.

23 1/2" x 35 1/2"

24" x 36"

NAIL FIN 2 3/4" PESTANA DE CLAURE 2 3/4 NO MO

WHITE BLANCO INCLUDED HALF INCLUDED MOSSULTERA MESEA HP SC

20 YEAR GLASS PE AND EN YERRIS



1000013592

MODEL Modelo

24 x 36

UNIT DIMENSIONS (WIDTH x HEIGHT) Dimensiones de la unidad (Ancho x Alto)	23 1/2" x 35 1/2"
ROUGH OPENING Abertura sin acabado	24" x 36"
FRAME TYPE/DEPTH	NAIL FIN 2 3/4"
Bastidor de tipo/profundidad	PESTAÑA DE CLAVAR 2 3/4
GRILLES	NO
Rejillas	NO
COLOR	WHITE
Color	BLANCO
HARDWARE	INCLUDED
Harware	INCLUIDO
INSECT SCREEN	HALF INCLUDED
Mosquitera	MOSQUITERA MEDIA
GLASS TYPE	HP SC
Vidrio tipo de	HP SC
WARRANTY	20 YEAR GLASS
Garantia	20 AÑOS EN VIDRIO

ENERGY STAR® Qualified in Highlighted Regions







510

Single Hung Vinyl Window with Nat

Ventana de vinilo de guillotina sencil a, con de la claración



Bottom sash tilts for easy cleaning

El fastidor interior se inclina hacia adentro y puede quitarse para tácil timpleza



To learn more about this reduct scan with your ordertoto is app.

NEW CONSTRUCTION

La construcction nueva

MODEL Modelo 36 x 72

(WIDTH x HEIGHT)

Dimensiones de la unidad (Ancho x Alto)

35 1/2" x 71 1/2"

ROUGH OPENING

36" x 72"

Abertura sin acabado FRAME TYPE/DEPTH

NAIL FIN 2 3/4"

Bastidor de tipo/profundidad GRILLES

NO NO

Rejillas

WHITE

COLOR

INCLUDED

HARDWARE

HALF INCLUDED

INSECT SCREEN Mosquitera GLASS TYPE

HP SC

Vidrio tipo de WARRANTY Gerentia

20 YEAR GLASS 20 ANDS EN VIDRIO

ENERGY STAR" Qualified in Highlighted Room









To learn mor about this product scan with ye ir smartphone app.

NEW CONSTRUCTION

La construcctión nueva

MODEL Modelo

36 x 60

UNIT DIMENSIONS (WIDTH x HEIGHT)

Dimensiones de la unidad (Ancho x Alto)

ROUGH OPENING

Abertura sin acabado FRAME TYPE/DEPTH

Bastidor de tipo/profundidad GRILLES

Rejillas

COLOR Color

HARDWARE Harware

INSECT SCREEN Mosquitera

GLASS TYPE Vidrio tipo de

WARRANTY

Garantia

35 1/2" x 59 1/2"

36" x 60"

NAIL FIN 2 3/4"

PESTANA DE CLAVAR 2 3/4

NO NO

WHITE BLANCO

INCLUDED INCLUIDO

HALF INCLUDED MOSQUITERA MEDIA

HP SC HP SC

20 YEAR GLASS 20 AÑOS EN VIDRIO

ENERGY STAR® Qualified in Highlighted Regions





100013563