HISTORIC AND DESIGN REVIEW COMMISSION

February 06, 2019

HDRC CASE NO: 2019-044 829 N PINE ST **ADDRESS: LEGAL DESCRIPTION: ZONING:** R-5, H **CITY COUNCIL DIST.:** 2 **DISTRICT: David Flores APPLICANT: David Flores OWNER: TYPE OF WORK:** January 09, 2019 **APPLICATION RECEIVED: 60-DAY REVIEW:** March 08, 2019

NCB 540 BLK 11 LOT A ARB A2 **Dignowity Hill Historic District** Install rear yard fencing

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to replace the existing rear and side yard chainlink fence with the new metal-framed cattle panel fence at 5 feet tall.

APPLICABLE CITATIONS:

2. Fences and Walls

B. NEW FENCES AND WALLS

i. Design—New fences and walls should appear similar to those used historically within the district in terms of their scale, transparency, and character. Design of fence should respond to the design and materials of the house or main structure. ii. Location—Avoid installing a fence or wall in a location where one did not historically exist, particularly within the front yard. The appropriateness of a front yard fence or wall is dependent on conditions within a specific historic district. New front yard fences or wall should not be introduced within historic districts that have not historically had them. iii. Height-Limit the height of new fences and walls within the front yard to a maximum of four feet. The appropriateness of a front vard fence is dependent on conditions within a specific historic district. New front vard fences should not be introduced within historic districts that have not historically had them. If a taller fence or wall existed historically, additional height may be considered. The height of a new retaining wall should not exceed the height of the slope it retains.

iv. Prohibited materials—Do not use exposed concrete masonry units (CMU), Keystone or similar interlocking retaining wall systems, concrete block, vinyl fencing, or chain link fencing.

v. Appropriate materials-Construct new fences or walls of materials similar to fence materials historically used in the district. Select materials that are similar in scale, texture, color, and form as those historically used in the district, and that are compatible with the main structure. Screening incompatible uses—Review alternative fence heights and materials for appropriateness where residential properties are adjacent to commercial or other potentially incompatible uses.

FINDINGS:

- The primary structure at 829 N Pine was constructed circa 1910 in the Craftsman style and first appears on the a 1912 Sanborn map. The one-story single-family structure features a hipped, standing seam metal roof, an inset porch with square columns, and wood sash windows. The rear of the property currently features a chain-link fence covered with plantings. The property contributes to the Dignowity Hill Historic District.
- FENCE LOCATION The applicant has proposed to replace the existing, rear yard chain-link fence with a b. metal-framed cattle panel fence at 5 feet in height. Staff finds that replacement of an existing non-historic rear vard fence is generally appropriate.
- c. FENCE DESIGN The applicant has proposed the new fence to feature metal-framed cattle panels at 5 feet in height. According to the Guidelines for Site Elements 2.B.i., the design of the fence should respond to the design and materials of the primary historic structure or structures of a similar style in the neighborhood in relation to scale, transparency, and character. Staff finds that while metal-framed cattle panel fencing for front yards is consistently recommended against in historic districts, the request to replace the chain-link only in the rear yard is an improvement upon the existing conforming condition; however, staff also finds that the existing plant growth should be reintroduced to the new fence to minimize its visual impact.

RECOMMENDATION:

Staff recommends approval to replace the rear chain-link fence with metal-framed cattle panel fencing based on findings b and c with the following stipulations:


- i. That no portion of the fence exceeds 5 feet in height, nor encroach beyond the front façade plane of the primary historic structure.
- ii. That plant growth over the fence be reintroduced to the new fence to minimize its visual impact.

CASE COMMENT:

The final construction height of an approved fence may not exceed the maximum height as approved by the HDRC at any portion of the fence. Additionally, all fences must be permitted and meet the development standards outlined in UDC Section 35-514.

CASE MANAGER:

Huy Pham






Flex Viewer

Powered by ArcGIS Server

Printed:Jan 31, 2019


The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.



829 North Pine Street







with .







