HISTORIC AND DESIGN REVIEW COMMISSION September 04, 2019

HDRC CASE NO: 2019-498

ADDRESS: 354 NORTH DR

LEGAL DESCRIPTION: NCB 7014 BLK LOT 18, E 5 FT OF 17 & W 5 FT OF 19

ZONING: R-6, H CITY COUNCIL DIST.: 7

DISTRICT: Monticello Park Historic District
APPLICANT: VALDERAS LUIS HORACIO
OWNER: VALDERAS LUIS HORACIO
TYPE OF WORK: Construction of a rear covered patio

CASE MANAGER: Huy Pham

REQUEST:

The applicant is requesting a Certificate of Appropriateness to construct a 12.5' x 15' covered patio in the rear yard.

APPLICABLE CITATIONS:

- 4. Guidelines for New Construction
- 5. Garages and Outbuildings

A. DESIGN AND CHARACTER

- i. *Massing and form*—Design new garages and outbuildings to be visually subordinate to the principal historic structure in terms of their height, massing, and form.
- ii. *Building size* New outbuildings should be no larger in plan than 40 percent of the principal historic structure footprint.
- iii. *Character*—Relate new garages and outbuildings to the period of construction of the principal building on the lot through the use of complementary materials and simplified architectural details.
- iv. Windows and doors—Design window and door openings to be similar to those found on historic garages or outbuildings in the district or on the principle historic structure in terms of their spacing and proportions.
- v. *Garage doors*—Incorporate garage doors with similar proportions and materials as those traditionally found in the district.

B. SETBACKS AND ORIENTATION

- i. *Orientation*—Match the predominant garage orientation found along the block. Do not introduce front-loaded garages or garages attached to the primary structure on blocks where rear or alley-loaded garages were historically used.
- ii. *Setbacks*—Follow historic setback pattern of similar structures along the streetscape or district for new garages and outbuildings. Historic garages and outbuildings are most typically located at the rear of the lot, behind the principal building. In some instances, historic setbacks are not consistent with UDC requirements and a variance may be required.


FINDINGS:

- a. The primary structure at 354 North was constructed in the Minimal Traditional style and contributes to the Monticello Park Historic District. The one-story single-family structure features asbestos siding, a concrete slab porch with wrought iron columns, a Dutch gabled roof with a front facing gable, and a brick masonry chimney on the side elevation.
- b. COVERED PATIO The applicant has proposed to construct a detached covered rear patio featuring a concrete slab, wood posts and beams, with corrugated metal shed roof measuring 12.5' in depth, 15' in width, and 9' to 10' in height. The rear yard features an existing garage structure and a recently approved storage shed structure. The proposed covered patio would be in the rear southeast corner of the property between the garage and shed. Staff finds that the proposed covered patio would not be visible from the front right-of-way and minimally visible from the rear alley way. Staff finds that the scale, massing, material, and orientation are consistent with the Guidelines.


RECOMMENDATION:


Staff recommends approval based on finding b. The applicant is responsible for complying with all setback requirements as required by Zoning and obtains a variance from the Board of Adjustment, if applicable.


354 North



August 28, 2019



















8/22/2019 IMG_0562.JPG

















Open air concrete patio with metal roof cover.


Location: directly behind the garage but not connected to the garage.
354 North Drive, SATX, 78201





I PROPOSED FLOOR PLAN







Property

Address	354 North Dr	
District/Overlay	Monticello Park	
Owner Information	HORACIO LUIS VALDERAS	
Location Map	Quentin Dr Quentin Dr	
	North Dr	rth i
	Club Dr Blvd Monticello Park © OpenStreeth	u b [Map
	Lat: 29.4675748279969 Long: -98.5365795208752	

Site Visit

0.10 1.0.0	
Date	08/13/2019
Time	01:40 PM (-5 GMT)
Context	citizen report
Present Staff	Huy Pham
Present Individuals	Contractor(s)
Types of Work Observed	New Construction
Amount of Work Completed	50%
Description of work	Construction of a rear accessory structure: wood frame shed roof, tall one-story.
Description of interaction	Staff provided stop work order to contractor who called the owner. The contractor said he or the owner will obtain the permits and understood to stop work.

Action Taken

	Violation Type	No Certificate of Appropriateness (Code 35-451a)	
--	----------------	--	--



OHP Action	Posted "Notice of Investigation", Posted additional "Stop Work Notice"
Will post-work application fee apply?	To be determined

Documentation

Photographs























08/13/2019 01:43 PM


584 North Drive, San Antonio, TX 78201 Backyard Shed Front View
























North Drive






North Drive








Furr




Furr



Furr




Fur



Club Drive



Club Drive



Club Drive



Club Drive



Mantonolla Park