HISTORIC AND DESIGN REVIEW COMMISSION October 16, 2019

HDRC CASE NO: 2019-582 ADDRESS: 1120 IOWA ST

LEGAL DESCRIPTION: NCB 3885 BLK 1 LOT 6

ZONING: RM-4, H

CITY COUNCIL DIST.: 2

DISTRICT: Knob Hill Historic District

APPLICANT: Michael Elizondo

OWNER: ELIZONDO MICHAEL & SANDRA

TYPE OF WORK: Window replacement APPLICATION RECEIVED: September 27, 2019 November 26, 2019

CASE MANAGER: Huy Pham

REOUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Replace seven existing wood windows with new aluminum clad wood windows.
- 2. Enclose two window openings on the east side of the house and infill with wood siding.

APPLICABLE CITATIONS:

- 2. Guidelines for Exterior Maintenance and Alterations
- 6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- ii. Doors—Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- iv. Screens and shutters—Preserve historic window screens and shutters.
- v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
- ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. Glazed area—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. Muntins—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.
- vi. Replacement glass—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. Non-historic windows—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.
- viii. Security bars—Install security bars only on the interior of windows and doors.
- ix. Screens—Utilize wood screen window frames matching in profile, size, and design of those historically found when the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original

screens or those used historically.

x. Shutters—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

Standard Specifications for Window Replacement

- o MATERIAL: If replaced is approved, the new windows must feature primed and painted wood exterior finish. Cladded or composition options are not allowed unless explicitly approved by the commission.
- o SASH: Meeting rails must be no taller than 1.25". Stiles must be no wider than 2.25".
- o DEPTH: There should be a minimum of 2" in depth between the front face of the window trim and the front face of the top window sash.
 - This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness.
- TRIM: Window trim must feature traditional dimensions and architecturally appropriate casing and sloped sill detail. Window track components such as jamb liners must be painted to match the window trim or concealed by a wood window screen set within the opening.
- o GLAZING: Windows should feature clear glass. Low-e or reflective coatings are not recommended for replacements. The glazing should not feature faux divided lights with an interior grille. If approved to match a historic window configuration, the window should feature real exterior muntins.
- o COLOR: Wood windows should feature a painted finished If a clad product is approved, white or metallic manufacturer's color is not allowed, and color selection must be presented to staff.
- o INSTALLATION: Wood windows should be supplied in a block frame and exclude nailing fins. Window opening sizes should not be altered to accommodate stock sizes prior to approval.
- o FINAL APPROVAL: If the proposed window does not meet the aforementioned stipulations, then the applicant must submit updated window specifications to staff for review, prior to purchase and installation. For more assistance, the applicant may request the window supplier to coordinate with staff directly for verification.

FINDINGS:

- a. The primary historic structure 1120 Iowa was constructed in the Craftsman style and is contributing to the Knob Hill Historic District. The single-family, one-story structure features a standing-seam metal roof, asbestos siding, exposed rafter rails, wood brackets with Craftsman detailing, wood sash windows, and non-original, wrought iron columns and security bars.
- b. WINDOW REPLACEMENT The applicant has proposed to replace seven wood sash windows with new aluminum-clad wood windows (Pella-250).
- c. EXISTING WINDOWS Per the Guidelines for Exterior Maintenance and Alterations 6.B.iv., new windows should be installed to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair. On a site visit on October 3, 2019, staff found that deterioration of the original wood windows have been mitigated by wood screens and security bars. Staff finds that the applicant should exhaust all repair options prior to consideration of replacement.
- d. PROPOSED WINDOWS Per the Guidelines for Exterior Maintenance and Alterations 6.B.iv., new windows should be installed to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair. If the windows are found deteriorated beyond repair, staff finds that matching wood windows should be installed instead of the proposed aluminum-clad wood with the standard stipulations.
- e. WINDOW REMOVAL The applicant has proposed to remove and infill the set of ganged windows on the side elevation, closest to the front façade. Per the Guidelines for Exterior Maintenance and Alterations 6.A.i., existing window and door openings should be preserves and applicants should avoid filling in historic door or window openings. Staff finds the window openings to be original and should not be infilled.


RECOMMENDATION:


Staff does not recommend approval of item #1, wood window replacement, nor item #2 window removal based on findings b through e. All wood windows should be repaired in-place. If the commission is compelled to approve window replacement, staff stipulates that the new windows should be wood instead of aluminum-clad wood with the standard specifications.

1120 lowa



October 3, 2019



















To whom it may Concern

My name is Michael Elizondo, I currently living at 1120 Iowa St. My Area is a Hot Bed for Buyer Who Are Flip Homes Right and Left. Which bring me to mind that the houses getting Remodel in My Area is leave me behind in Appearance. Which I'm requesting to have 7 of my currently window replaces. I have enclose picture with Windows Approve for use. I'm Propose to have 1 of my Double windows encloses, which I will frame and use Siding to Close windows Area. The siding I'm propose to use is install in the back end of the House. Picture are encloses. My Foundation is Off Making my Window Hard to Open and Close. Some of my window have lose the weights on them making it Hard as well to Open Close my Windows. The Windows framing is also off, because of the Foundation, last time Level was back in 1989. Will be Fix my Foundation this Year 2019. The House next to me at 1118 Iowa St, just got remodel with Pella window in which was Approve by the Historic District. I have Pictures to Support my Propose and Request. I also enclosed Pella windows invoice to support the requirement requested by the Historic District. Burglar

Bars will be remove for better Curb Appearance. Thank You for Your Time on this Matter.


Michael Elizondo

1120 Iowa St.


San Antonio, TX 78203-1815


210-367-9649


Window Schedule



IOWA ST.










Propose to ENCLOSE WINDOW FrAME AND HAVE SIDINAPUT UP.

SINGLE WINDOW.





Download

Full screen Show email

Sindle window






×



X










SINGLE WINDOW





Double WINDOW.

X







 \circlearrowleft Reply \lor $\dot{\mathbb{I}}$ Delete \bigcirc Junk Block \cdots

(No subject)

+12103679649@tmomail.net

Thu 9/26/2019 11:37 PM

You \otimes













 \circlearrowleft Reply \checkmark $\dot{\mathbb{I}}$ Delete \bigcirc Junk Block \cdots

(No subject)

1

+12103679649@tmomail.net

Fri 9/27/2019 1:31 PM

You $\, \otimes \,$





T··Mobile·

This message was sent to you by a T-Mobile wireless phone.




USING PHIS TYPE OF SCOING To Cover WINDOW VIA FVAMING.



DOUBLE WINDOWS,


1118 FOWA ST WINDOWS APPROVE BY HISTORIC DISTRICT.



18 You 💝



SM WINDOW



+121036796

Our \$5 Wines Are

Wines

Better Than Most \$50



Upgrade to Premium













Proposal - Detailed

Sales Rep Name: Owens, Marcus Sales Rep Phone: 210-735-2030

Sales Rep E-Mail: mowens@pellasouthtexas.com

Sales Rep Fax:

Pella Window and Door Showroom of San Ant	tonio
6510 Blanco Road	
San Antonio, TX 78216	

Customer Information	Project/Delivery Address	Order Information
MARCUS OWENS 7940 Pipers creek 7940 Pipers creek San Antonio, TX 78251 Primary Phone: (210) 7791744 Mobile Phone: Fax Number: E-Mail: Contact Name:	Quote Purposes Lot # County: Owner Name:	Order Information Quote Name: Quote Purposes Order Number: 370 Quote Number: 10556228 Order Type: Non-Installed Sales Wall Depth: Payment Terms: Tax Code: SATGROUPTX
Great Plains #: 1004891802 Customer Number: 1008871912 Customer Account: 1004891802	Owner i Hone.	Cust Delivery Date: None Quoted Date: 8/31/2018 Contracted Date: Booked Date: Customer PO #:

Customer Notes: Pella 250 Series Window Quote

Location: 10 33 x 65 PK# 2045

Line#

Viewed From Exterior Rough Opening: 33 - 3/4" X 65 - 3/4"

Lifestyle, Double Hung, 33 X 65, Brown

Item Price Qty Ext'd Price \$421.55 \$3,372.40

total : 3, 918.08

5

1: 3365 Double Hung, Equal

Frame Size: 33 X 65

General Information: No Package, Without Hinged Glass Panel, Clad, Pine, 5", 3 11/16"

Exterior Color / Finish: Standard Enduraciad, Brown

Interior Color / Finish: Primed Interior

Glass: Insulated Low-E SunDefense™ Low-E Insulating Glass Argon Non High Altitude

Hardware Options: Cam-Action Lock, White, No Limited Opening Hardware, Order Sash Lift, No Integrated Sensor

Screen: No Screen

Performance Information: U-Factor 0.30, SHGC 0.22, VLT 0.52, CPD PEL-N-35-00386-00001, Performance Class LC, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, TDI WIN-694, Year Rated 08|11, Egress Meets Typical 5.7 sqft (E) (United States Only)

Attributes

Wrapping Information: Foldout Fins, Factory Applied, No Exterior Trim, 4 9/16", 5 7/8", Standard Four Sided Jamb Extension, Factory Applied, Pella Recommended Clearance, Perimeter Length = 196".

Project Name: Quote Purposes

Quote Number: 10556228

5

Line #	Location:	
15	23.5 x 35.5	
36.5"	₽ Û	PK# 2045

Viewed From Exterior Rough Opening: 24 - 1/4" X 36 - 1/4"

Lifestyle, Double Hung, 23.5 X 35.5, Brown

Item Price Qty **Ext'd Price** \$247.07 \$247.07

1: 23.535.5 Double Hung, Equal Frame Size: 23 1/2 X 35 1/2

General Information: No Package, Without Hinged Glass Panel, Clad, Pine, 5", 3 11/16"

Exterior Color / Finish: Standard Enduraciad, Brown

Interior Color / Finish: Primed Interior

Glass: Insulated Low-E SunDefense™ Low-E Insulating Glass Argon Non High Altitude

Hardware Options: Cam-Action Lock, White, No Limited Opening Hardware, Order Sash Lift, No Integrated Sensor

Screen: No Screen

Performance Information: U-Factor 0.30, SHGC 0.22, VLT 0.52, CPD PEL-N-35-00386-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, TDI WIN-694, Year Rated 08|11, Egress Does not meet typical United States egress, but may comply with local code requirements

Attributes

Grille: No Grille.

Wrapping Information: Foldout Fins, Factory Applied, No Exterior Trim, 4 9/16", 5 7/8", Standard Four Sided Jamb Extension, Factory Applied, Pella Recommended Clearance, Perimeter Length = 118".

Thank You For Your Interest In Pella® Products