HISTORIC AND DESIGN REVIEW COMMISSION July 15, 2020

HDRC CASE NO:	2020-307
ADDRESS:	515 BURLESON ST
LEGAL DESCRIPTION:	NCB 514 BLK 18 LOT 9
ZONING:	R-6, H
CITY COUNCIL DIST.:	2
DISTRICT:	Dignowity Hill Historic District
APPLICANT:	Stephanie Padua
OWNER:	Patricia Gonzalez
TYPE OF WORK:	Porch flooring replacement
APPLICATION RECEIVED:	June 25, 2020
60-DAY REVIEW:	Not applicable due to City Council Emergency Orders
CASE MANAGER:	Huy Pham

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to install 2x6 treated boards as porch decking.

APPLICABLE CITATIONS:

2. Guidelines for Exterior Maintenance and Alterations

7. Architectural Features: Porches, Balconies, and Porte-Cocheres

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. *Front porches*—Refrain from enclosing front porches. Approved screen panels should be simple in design as to not change the character of the structure or the historic fabric.

ii. *Side and rear porches*—Refrain from enclosing side and rear porches, particularly when connected to the main porch or balcony. Original architectural details should not be obscured by any screening or enclosure materials. Alterations to side and rear porches should result in a space that functions, and is visually interpreted as, a porch.

iii. *Replacement*—Replace in-kind porches, balconies, porte-cocheres, and related elements, such as ceilings, floors, and columns, when such features are deteriorated beyond repair. When in-kind replacement is not feasible, the design should be compatible in scale, massing, and detail while materials should match in color, texture, dimensions, and finish.

iv. *Adding elements*—Design replacement elements, such as stairs, to be simple so as to not distract from the historic character of the building. Do not add new elements and details that create a false historic appearance.

v. *Reconstruction*—Reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns.

FINDINGS:


- a. The primary historic structure at 515 Burleson was constructed circa 1920 and first appears on the 1951 Sanborn map. The one-story single-family structures originally featured a primary gable-on-hip roof with a number of dormers and secondary gable of the front door of the front porch, shake shingles in the front facing gables, sashed wood windows, and Corinthian columns and pilaster in the front porch. The property was subjected to a variety of non-conforming modifications including the installed of flagstone skirting, window replace on the driveway side elevation, and front porch reconstruction including simple square columns and wrought iron railing.
- b. COMPLIANCE The applicant has been making progress towards window restoration and correcting work without approval per the Commission Action at the June 5, 2019, HDRC hearing. No additional Certificate of Appropriateness may be issued until all corrections have been completed.
- c. PORCH DECK The applicant has proposed to replace the existing plywood decking with 2 x 6 wood planks laid parallel to the front façade plane. Per the Guidelines for Exterior Maintenance and Alterations 7.B.v., applicants should reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs; if no such evidence exists, the design should be based on the architectural style of the building and historic patterns. Staff finds that historic porches should be reconstructed with 1 x 3 tongue-and-groove wood decking laid perpendicular to the front façade plane and that the proposed 2 x 6 planks are inconsistent with the Guidelines.

RECOMMENDATION:


Staff recommends approval based on finding b with the following stipulations:


- i. That 1×3 inch tongue-and-groove wood decking laid perpendicular to the front façade plane is used instead the proposed 2×6 inch wood planks laid parallel,
- ii. That no additional Certificate of Appropriateness may be issued until all corrections per the June 6, 2019, Commission Action have been completed.

515 Burleson



April 23, 2019









509 BurlesonSan Antonio, Texas

🔀 Google

Street View - May 2014

- Altan














515 Burleson St. Front Deck Rehab Project

New deck will mimic the following deck using 2" x 6" pressure treated wood as decking material. Deck pictured below is Located down the street on a rehab project on Burleson and Muncey St. We are planning on using a stain for top decking and White for Banister and Stair Risers.








Banister will mimic the following using our existing 6" x 6" Posts.



Current Decking pictured below









831 Burleson



831 Burleson

The set of the set of

1.11







1127 Palmetto st

1127 Palmetto st

1127 N Palmetto st











724 olive st

724 Olive st

6

ñ

6

0. 0 2