

HISTORIC AND DESIGN REVIEW COMMISSION

May 20, 2020

HDRC CASE NO: 2020-152
ADDRESS: 2158 W KINGS HWY
LEGAL DESCRIPTION: NCB 6825 BLK LOT 15 & W 12.5 FT OF 14
ZONING: R-6, H
CITY COUNCIL DIST.: 7
DISTRICT: Monticello Park Historic District
APPLICANT: William Hazlewood
OWNER: William Hazlewood
TYPE OF WORK: Enclosure of front porch with windows and door
APPLICATION RECEIVED: April 03, 2020
60-DAY REVIEW: Not applicable due to City Council Emergency Orders
CASE MANAGER: Huy Pham

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to enclose the front porch to feature aluminum windows in the two front arches and doors in the side-facing arches.

APPLICABLE CITATIONS:

2. Guidelines for Exterior Maintenance and Alterations

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Front porches*—Refrain from enclosing front porches. Approved screen panels should be simple in design as to not change the character of the structure or the historic fabric.
- ii. *Side and rear porches*—Refrain from enclosing side and rear porches, particularly when connected to the main porch or balcony. Original architectural details should not be obscured by any screening or enclosure materials. Alterations to side and rear porches should result in a space that functions, and is visually interpreted as, a porch.
- iii. *Replacement*—Replace in-kind porches, balconies, porte-cocheres, and related elements, such as ceilings, floors, and columns, when such features are deteriorated beyond repair. When in-kind replacement is not feasible, the design should be compatible in scale, massing, and detail while materials should match in color, texture, dimensions, and finish.
- iv. *Adding elements*—Design replacement elements, such as stairs, to be simple so as to not distract from the historic character of the building. Do not add new elements and details that create a false historic appearance.
- v. *Reconstruction*—Reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns.


FINDINGS:

- a. The primary structure at 2158 W Kings Hwy was constructed circa 1930 in the Tudor Revival style, first appears on the 1934 Sanborn map, and contributes to the Monticello Park Historic District. The one-and-a-half story, single-family structure features brick masonry, stucco, and half-timbering façade elements, steep roof pitches with a front facing dormer centered above the front-extending arcade porch.
- b. COMPLIANCE – Staff conducted a site visit on April 2, 2020, and found that the property at 2158 W Kings Hwy was subject to front porch enclosure prior to approval. The property previously received administrative approval to reconstruct the porch in-kind after damage from a fallen tree. A subsequent Historic and Design Review Commission application was submitted, which was determined incomplete. The applicant proceeded with the enclosure, and a Stop Work Order was issued
- c. PORCH ENCLOSURE – The applicant has proposed to enclose the front porch by infilling the open arches with matching brick masonry and aluminum windows with faux divided lites. Per the Guidelines for Exterior Maintenance and Alterations 2.B.i., applicants should refrain from enclosing front porches. Staff finds that the proposed enclosure is inconsistent with the Guidelines and departs from a major character-defining feature of the Tudor Revival structure. Staff also remains concerned about the quality of the submitted drawings and the inconsistency between the drawings and the initiated work without approval, including door and window details.

RECOMMENDATION:


Staff does not recommend approval based on finding c. The applicant should perform in-kind reconstruction as approved.

2158 W Kings Hwy



October 24, 2019

— User drawn lines



(UNCL)
SAN ANTONIO, TEX. VOL. 5

541

TEX...041

ADD'L SHEET

DEC. 1934

THOMAS JEFFERSON HIGH SCHOOL GROUNDS

548

525



550

550

KAMPMANN

BLVD.

7012

6820

6824

6826

6828

6830

6832

6834

6836

6838

6840

6842

6844

6846

6848

6850

6852

6854

6856

6858

6860

6862

6864

6866

6868

6870

6872

6874

6876

6878

6880

6882

6884

6886

6888

6890

6892

6894

6896

6898

6900

6902

6904

6906

6908

6910

6912

6914

6916

6918

6920

6922

6924

6926

6928

6930

6932

6934

6936

6938

6940

6942

6944

6946

6948

6950

6952

6954

6956

6958

6960

6962

6964

6966

6968

6970

6972

6974

6976

6978

6980

6982

6984

6986

6988

6990

6992

6994

6996

6998

7000

7002

7004

7006

7008

7010

7012

7014

7016

7018

7020

7022

7024

7026

7028

7030

7032

7034

7036

7038

7040

7042

7044

7046

7048

7050

7052

7054

7056

7058

7060

7062

7064

7066

7068

7070

7072

7074

7076

7078

7080

7082

7084

7086

7088

7090

7092

7094

7096

7098

7100

7102

7104

7106

7108

7110

7112

7114

7116

7118

7120

7122

7124

7126

7128

7130

7132

7134

7136

7138

7140

7142

7144

7146

7148

7150

7152

7154

7156

7158

7160

7162

7164

7166

7168

7170

7172

7174

7176

7178

7180

7182

7184

7186

7188

7190

7192

7194

7196

7198

7200

7202

7204

7206

7208

7210

7212

7214

7216

7218

7220

7222

7224

7226

7228

7230

7232

7234

7236

7238

7240

7242

7244

7246

7248

7250

7252

7254

7256

7258

7260

7262

7264

7266

7268

7270

7272

7274

7276

7278

7280

7282

7284

7286

7288

7290

7292

7294

7296

7298

7300

7302

7304

7306

7308

7310

7312

7314

7316

7318

7320

7322

7324

7326

7328

7330

7332

7334

7336

7338

7340

7342

7344

7346

7348

7350

7352

7354

7356

7358

7360

7362

7364

7366

7368

7370

7372

7374

7376

7378

7380

7382

7384

7386

7388

7390

7392

7394

7396

7398

7400

7402

7404

7406

7408

7410

7412

7414

7416

7418

7420


7422

7424

7426

7428

7430



W Kings Hwy

W Kings Hwy

W Kings Hwy

W Kings Hwy

W Kings Hwy

2158 West
Kings Highway

Shearer Blvd

Shearer Blvd

West Summit


West Summit

West Summit

West Summit


Google

West Summit





2158 West
Kings Highway






2161 W Kings Hwy
San Antonio, Texas

Google

Street View



Google

A large red oak was uprooted during a sever wind storm in early May. The tree fell on our front porch damaging the roof,3 porch columns and the 2nd floor dormer. The damage was extensive enough that the porch has to be taken down and rebuilt. The roof in front of the dormer is sagging due to the instability of the damaged interior beams that runs above the porch ceiling, from the 3 brick columns to the actual framing of the house.

In conjunction to the rebuild we would like to enclose the porch. The foot print of the porch/house will not be changed. Building material will be stucco and brick, as is the house.

We will add curved picture windows in the front 2 arches, finishing the area with designed stucco complementing the existing designed stucco. We will keep the original iron railings. On the drive way side of the house a curved door with side lites will be added, keeping the existing designed stucco. On the sidewalk/front door side we will duplicate the drive way side,except with a dummy door rather than a functional door.

Due to the age of the brick and mortar {built in 1937} it will be cost prohibitive to clean and reuse the brick that was taken down during the repair. Instead we will incorporate stucco with usable salvaged brick accents on the sides of the house, similar to the the design of the front entrance.

Basically we are rebuilding the damaged parts of the front of the house, and to the porch we are adding 2 picture windows,1 functional door and a "dummy"door all in keeping with the existing design and building material.

Joe Hazlewood










EXIST'S
Brick
Siding

stucco




Entry Side's

New
craftsman
style
Entry
Door w/ side
lights

Stucco


New
cove
trim
match
EXIST'S
Trim

EXIS
Door
stucco



Falsedoor
New Brick
wainscott
using salvaged
Brick

Tail
Sini
di
110




3 tab
shingle to
Match #X51

New gutter

Down
spout

Keep iron re
under window


Foundation
plants TBD



3 tab
shingle to
match existing

New gutter


Down
spout
3'6"
4'9"



Keep iron railing
under windows

Soundatjan
plants TBD

Not in part of same permit





Investigation Report

Property

Address	2158 W Kings Hwy
District/Overlay	Monticello Park
Owner Information	HAZLEWOOD WILLIAM JOSEPH, TERRILYNN


Site Visit

Date	04/02/2020
Time	10:23 AM (-5 GMT)
Context	citizen report
Present Staff	Huy Pham, Edward Hall
Present Individuals	Homeowner, Contractor(s)
Types of Work Observed	Exterior Maintenance and Alterations
Amount of Work Completed	50%
Description of work	Porch reconstruction and enclosure
Description of interaction	Homeowners were cooperative to stop work order and will work with staff to submit missing application materials.

Action Taken

Violation Type	Beyond scope of Certificate of Appropriateness (Code 35-451h)
OHP Action	Spoke with property owner, Spoke with contractor(s)
Will post-work application fee apply?	No

Documentation

Photographs	
-------------	--



Investigation Report





Investigation Report



04/02/2020 10:58 AM

drive way side - undamaged
2018

Sent from my T-Mobile 4G LTE Device



damage of dormer which pushed
the dormer & roof down - leading to
joist damage.

Sent from my T-Mobile 4G LTE Device



Sent from my T-Mobile 4G LTE Device



Sent from my T-Mobile 4G LTE Device



Sent from my T-Mobile 4G LTE Device





TW

drive way side of house

Sent from my T-Mobile 4G LTE Device





TW

porch

Sent from my T-Mobile 4G LTE Device



broken stucco porch

Sent from my T-Mobile 4G LTE Device



From: terri terri@mwfamilylaw.com
Subject:
Date: October 17, 2019 at 1:00 PM
To: terri@mwfamilylaw.com

TW

broken stucco & brick on arch
on sidewalk side -

Sent from my T-Mobile 4G LTE Device





water damage

TW

Sent from my T-Mobile 4G LTE Device



water damage & cracked arches
in porch.

Sent from my T-Mobile 4G LTE Device





TW

porch arches

Sent from my T-Mobile 4G LTE Device





TW


Cracks porch ceiling

Sent from my T-Mobile 4G LTE Device



sunken roof under dormer window
due to porch ceiling joist broken when
dormer was hit.


Sent from my T-Mobile 4G LTE Device



add curved picture windows in arched opening. Follow the distinct characteristics in the window framings - keep iron rails -

Sent from my T-Mobile 4G LTE Device

damage seen
on dormer





TW

Drive way Side.
Door & side lites added

Sent from my T-Mobile 4G LTE Device



Side walk / front door side
similar to drive way side
w/ "dummy" door

Sent from my T-Mobile 4G LTE Device



Keep the distinct characteristic side
of the front door in the driveway door + wall
+ the sidewalk 'darning' door + side wall

Sent from my T-Mobile 4G LTE Device

























From: Terri Terri@mwfamilylaw.com
Subject:
Date: October 17, 2019 at 9:06 AM
To: Terri@mwfamilylaw.com

TW

damage of dormer which pushed
the dormer & roof down, leading to
joint damage.

Sent from my T-Mobile 4G LTE Device






ICC - Español

ICC

SR - 2955



FRAMING/FOUNDATION PLAN

SCALE: 1/4" = 1'-0"







ICC-ES ESR

29

VERBIT

TM

ICC - ES ESR - 2955









CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION

ADMINISTRATIVE CERTIFICATE OF APPROPRIATENESS RE-ISSUE

April 6, 2020

ADDRESS: 2158 W KINGS HWY
LEGAL DESCRIPTION: NCB 6825 BLK LOT 15 & W 12.5 FT OF 14
HISTORIC DISTRICT: Monticello Park
PUBLIC PROPERTY: No
RIVER IMPROVEMENT OVERLAY: No
APPLICANT: William Hazlewood - 2158 W Kings
OWNER: William Hazlewood - 2158 W Kings
TYPE OF WORK: Porch/Patio, Repair and Maintenance

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to repair the front porch.

CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION

DATE: 4/6/2020 9:15:19 AM

ADMINISTRATIVE APPROVAL TO: make repairs to the front porch. The roof and masonry were damaged by a fallen tree. The front porch at this time will be returned to previous appearance. No changes to the existing roof form are taking place; the porch roof has a steep roof slope with composition shingles and the porch is made up of arches. Any missing brick may be replaced with comparable brick and mortar joints.

Non-brick elements that were previously painted may be re-painted to match existing colors.


APPROVED BY: Katie Totman

RE-ISSUE REASON:

COA expired - REPAIRS may be made to the dormer window and areas that are leaking. No changes to the existing form is taking place.

RE-ISSUE DATE: 4/6/2020 9:15:19 AM

RE-ISSUED BY: Katie Totman



Shanon Shea Miller
Historic Preservation Officer

A Certificate of Appropriateness (COA) serves as a record of design approval and is valid for 180 days. Work that is not completed in accordance with this certificate may be subject to correction orders and other penalties.

A COA does not take the place of any required building permits nor does it authorize the use of a property beyond what is allowed by the Unified Development Code. Prior to beginning your construction project, please contact the Development Services Department at (210) 207-1111 to ensure that all requirements have been met.

This Certificate must remain posted on the job site for the duration of your project. Modifications to an approved design or an expired approval will require a re-issue of your Certificate of Appropriateness by OHP staff. Please contact OHP Staff at (210) 207-0035 with any questions.

Huy Pham (OHP)

From: Office Of Historic Preservation
Sent: Thursday, April 02, 2020 10:46 AM
To: [REDACTED]
Cc: Edward Hall (OHP); Huy Pham (OHP)
Subject: FW: [EXTERNAL] Re: 2158 W Kings Hwy - Incomplete Application Notice

Good morning Mr. Hazlewood,

Below is the original incomplete notice that was sent to you on October 22, 2019, regarding the additional information we need to review for the screening in/enclosing of the front porch.

At this time, we would need a new application for a Certificate of Appropriateness (COA) and you may submit this on our website: www.sapreservation.com and clicking on Applications Portal. Documents may be uploaded on the online form and sent electronically for review.

Please let us know if there is anything additional we may provide or assist with.

Best,
Katie ☺

Best Regards,
Katie Totman, M.A.
Historic Preservation Specialist

Our team is practicing social distancing with limited availability at our physical office. During this time, we encourage you to utilize our many online resources including the online application portal and explorer map. Visit www.sapreservation.com or contact us at 210-207-0035.

City of San Antonio • Office of Historic Preservation
1901 South Alamo • San Antonio, TX 78204
direct: 210.207.0066 • main: 210.207.0035 • 210.207.0199
katie@sapreservation.com • www.sapreservation.com



How are we doing? Please take our short customer service [survey](#).



From: joe hazlewood [mailto:REDACTED] **Sent:**
Wednesday, October 23, 2019 3:30 PM

To: Office Of Historic Preservation

Subject: [EXTERNAL] Re: 2158 W Kings Hwy - Incomplete Application Notice

May I reapply once I add the measurements for the openings to be enclosed, to the drawings I submitted?

Joe Hazlewood

On Tuesday, October 22, 2019, 01:42:31 PM CDT, Office Of Historic Preservation
<OfficeOfHistoric.Preservation@sanantonio.gov> wrote:

Good afternoon Mr. Hazlewood,

Thank you for submitting a Certificate of Appropriateness Application for screening in your front porch. Following review by Office of Historic Preservation senior staff, the application has been determined to be **incomplete** due to a lack of sufficient information as outlined in the UDC, Section 35-402(C)(3)(D). Staff has identified the following items that are currently required in order to complete your application:

- Measured, dimensioned drawings that illustrate how a screened porch will look as installed on your home. The drawings you submitted are a good start though they should have measurements and dimensions.

No further action regarding your request, including placement on an HDRC agenda nor issuing a Certificate of Appropriateness, will be taken until the requested materials have been received.

An OHP specialist is on duty between 7:45 AM and 4:30 PM at our counter on the first floor of 1901 S Alamo. This specialist can assist you in submitting additional documents, or you can e-mail them directly to me.

Please let me know if you have any questions or need further assistance at this time.

Best Regards,

Katie Totman, M.A.

Historic Preservation Specialist

City of San Antonio · Office of Historic Preservation

1901 South Alamo · San Antonio, TX 78204

direct: 210.207.0066 · main: 210.207.0035 · 210.207.0199

katie@sapreservation.com · www.sapreservation.com



How are we doing? Please take our short customer service [survey](#).



****THIS EMAIL IS FROM AN EXTERNAL SENDER OUTSIDE OF THE CITY.
Be cautious before clicking links or opening attachments from unknown sources. Do not provide personal or
confidential information.****