


# Background





### Task Order



#### Reason

Wear and weather

### Scope of Work

- Remove existing exterior skylights' frame and panels
- Remove and replace the lower interior gasket and sill flashing
- Clean the gutters and replace all the fasteners
- Install new exterior clamping bars, gaskets and fasteners
- Install a new expansion joint
- Install new color panels

## Fiscal Impact





- Task order value
  - \$208,787.14
- Funding source
  - FY 2020 Airport Operating & Maintenance Budget

