HISTORIC AND DESIGN REVIEW COMMISSION

June 17, 2015

Agenda Item No: 25

HDRC CASE NO:	2015-152
ADDRESS:	428 BURLESON ST
LEGAL DESCRIPTION:	NCB 520 BLK 24 LOT N 122.3 FT OF 7
ZONING:	R5 H
CITY COUNCIL DIST.:	2
DISTRICT:	Dignowity Hill Historic District
APPLICANT:	Lucas Davila/LOROM LLC
OWNER:	Lucas Davila/LOROM LLC
TYPE OF WORK:	Replace windows and install wood screens
	-

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Replace aluminum windows with new vinyl windows
- 2. Install wood frame screens

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations 6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

i. Openings—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

vii. Non-historic windows—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.

ix. Screens—Utilize wood screen window frames matching in profile, size, and design of those historically found when the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.

FINDINGS:

- a. A request to replace the aluminum windows was heard by the HDRC on April 15, 2015. At that time, the Commission approved replacement of the windows with the stipulation that the applicant submits an appropriate replacement window option to staff for approval. An appropriate option was submitted to staff on April 15, 2015.
- b. A stop work order was issued on May 20, 2015 for going beyond the approved scope of work. Staff visited the property on May 28, 2015, and confirmed that the windows installed do not match the previously approved window style.
- c. Consistent with the Guidelines for Exterior Maintenance and Alterations, non-historic windows should be replaced with windows that are typical of the architectural style of the building. Although replacement of the existing windows may be appropriate, the proposed windows are not consistent with the architectural style of the building. In addition, the proposed windows will be mounted flush on the wall instead of set inside the opening as typical with historic windows. A replacement window that matches historic windows in proportion, size and placement of brickmolds, blind stops, and rails would be more appropriate.
- d. According to the Guidelines for Exterior Maintenance and Alterations, wood screen frames that match those historically found in profile, size and design should be used. The proposed wood window screens are compatible with the Folk Victorian house and consistent with the guidelines.

RECOMMENDATION:

- 1. Staff does not recommend approval of item 1 based on findings a-c. Staff recommends the windows are replaced with new windows that match historic windows in placement of brickmolds, blind stops, and rails.
- 2. Staff recommends approval as submitted based on finding d.

CASE MANAGER:

Adriana Ziga



428 Burleson

Ν

Powered by ArcGIS Server


Printed:Apr 08, 2015


The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.

Original conditions









Original windows







Previously approved windows

SERIES 8050

Multi-cavity vinyl lineals improve thermal performance and enhance sound absorbency

Insulating glass provides energy saving thermal efficiency

Fusion welded frame and sash minimizes air and water infiltration and enhances overall durability

- Sweep lock helps provide a weather-tight seal and added security
- Removable operable sash includes full-length interlock and bottom weather reflector
- Dual screw boss, metal reinforced meeting rail provides added strength

Custom sized to the nearest 1/8"

 Dual weather-stripping helps block air and water infiltration, keeping harsh elements outside and energy saving comfort inside Dual lift rails for convenient sash operation Versatile half-screen* installed from the inside or outside

Sloped sill reduces air infiltration and accommodates easy water run-off

Built-in accessory channels accommodate multiple installation options


Transferable, limited lifetime warranty

Modular sized so that rough opening widths for multiple units are easy to calculate: 3050 Single=35.5*

3050 Twin=71.5"

3050 Triple=107.5"

DP Rating R50 (window size tested 36" x 96") Jamb depth: 2.625"



CUSTOM Openation

- Low-E Glass
- Low-E Glass + Argon Gas
- Ultra Low-E Glass + Argon Gas (May be required for Energy Star rating.)
- 5/8" or 3/4" flat, 5/8" or 1" contoured, 5/8" contoured valance grids available

Factory mulling of twins, triples and architectural shapes Custom sizes available Safety latch for sash restriction (field app!ied)

White

COLOR

С IC .



All products may be ordered to meet Energy Star requirements.

Note: Manufacturer reserves the right to substitute components as necessary for continued product improvement. "Screens are not meant to restrain a child from folling through an open window. "Punting provide may affect open shown. Provide relation to actual window sample when selecting objets.

Almond







BUILDER SERIES

Proposed windows

PLY GEM



1110 SERIES SINGLE HUNG




MORE VALUE. MORE PERFORMANCE. MORE SOLUTIONS

If you're looking for a window that delivers the best possible performance at the best possible value, look no further than Ply Gem Windows Builder Series. It's energy-efficient and offers a variety of material choices, most of which are virtually maintenance free and can withstand the toughest tests, including the test of time. Plus, with our service and support you'll be able to get the job done the right way on time and on budget.





1110 SERIES SINGLE HUNG



SINGLE HUNG SELECTION GUIDE

				CONSTRUCTION TYPE				
1"					•			
13/a"				٥	•			•
1		٥	•	•				
FLANGE		0	0				•	
L\$/s"		0	۰	0	0			0
1	0			0	•	•		
13/8"	0			0	0			0

THERMAL PERFORMANCE 0.65 2.04 0.49 0.62 2.86 0.35 0.29 0.55 0.43 2.86 0.35 0.23 3.23 0.29 0.55 0.31 3.33 0.30 0.22 0.43

STANDARD FEATURES







WARM EDGE

OPTIONS

GLASS OPTIONS:

GRILLE OPTIONS:

PRODUCT CONFIGURATION:

COLOR OPTIONS:





















