HISTORIC AND DESIGN REVIEW COMMISSION

September 21, 2016 Agenda Item No: 11

	0
HDRC CASE NO:	2016-365
ADDRESS:	108 N MEDINA
LEGAL DESCRIPTION:	NCB 264 BLK 76 N 69.05 FT OF S 133.45 FT OF 9 ARB A9
ZONING:	D H HE
CITY COUNCIL DIST.:	5
DISTRICT:	Cattleman Square Historic District
LANDMARK:	I&GN Depot Cluster
APPLICANT:	Michael Mauldin/Mauldin Architects

REQUEST:

TYPE OF WORK:

OWNER:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Remove existing non-original wooden front door and install new single front door with single light and side lights in original opening on west façade.
- 2. Install new steel door to the left of proposed front entry.
- 3. Remove CMU block infill and plywood, and replace with fixed store front and transom windows.

Randall Hoover/North Medina. LLC

Door fenestration, entry modifications

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.

ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.

iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.

vi. Replacement glass—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.

vii. Non-historic windows—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.

10. Commercial Facades

A. MAINTENANCE (PRESERVATION)

i. *Character-defining features*—Preserve character-defining features such as cornice molding, upper-story windows, transoms, display windows, kickplates, entryways, tiled paving at entryways, parapet walls, bulkheads, and other features that contribute to the character of the building.

ii. *Windows and doors*—Use clear glass in display windows. See Guidelines for Architectural Features: Doors, Windows, and Screens for additional guidance.

iii. Missing features-Replace missing features in-kind based on evidence such as photographs, or match the style of the

building and the period in which it was designed.

iv. *Materials*—Use in-kind materials or materials appropriate to the time period of the original commercial facade when making repairs.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. *New features*—Do not introduce new facade elements that alter or destroy the historic building character, such as adding inappropriate materials; altering the size or shape of windows, doors, bulkheads, and transom openings; or altering the façade from commercial to residential. Alterations should not disrupt the rhythm of the commercial block.

ii. *Historical commercial facades*—Return non-historic facades to the original design based on photographic evidence. Keep in mind that some non-original facades may have gained historic importance and should be retained. When evidence is not available, ensure the scale, design, materials, color, and texture is compatible with the historic building. Consider the features of the design holistically so as to not include elements from multiple buildings and styles.

FINDINGS:

- a. The building at 108 N Medina is a two-part commercial block, with three stories, red brick façade and CMU block enclosing the first floor windows.
- b. There is an existing non-original wooden door with a wood transom. The applicant is proposing to remove the doors and install a single wood door with panels and single light and two side lights. According to the Guidelines for Exterior Maintenance and Alterations 6.B., non-historic incompatible elements should be replaced with what are typical of the architectural style of the building. Staff finds the proposal to replace the non-original appropriate and consistent with the Guidelines.
- c. There is a door way filled with CMU blocks on the left of the west façade. The applicant is proposing to install a steel door with single light. According to the Guidelines for Exterior Maintenance and Alterations 6.B. and 10.B.ii., non-historic incompatible elements and facades should be replaced with what are typical of the architectural style of the building and based on photographic evidence. Staff finds the proposal appropriate and consistent with the guidelines.
- d. The front window openings currently are filled with CMU blocks and the existing front covered entry is boarded with plywood. The applicant is proposing to remove the plywood and CMU blocks and install fixed windows painted off-white to match those of the neighboring property. According to the Guidelines for Exterior Maintenance and Alterations 6.B. and 10.B.ii., non-historic incompatible elements and facades should be replaced with what are typical of the architectural style of the building and based on photographic evidence. Staff finds that historically these areas would be window openings with glass. Staff finds the proposal consistent with the Guidelines.
- e. Staff made a site visit on September 9, 2016, and found the original door opening, original covered front entry, and CMU filled in front windows and door.
- f. HISTORIC TAX CERTIFICATION At this time, the applicant has not applied for Historic Tax Certification. Staff recommends the applicant apply for the historic tax incentive which lasts a total of ten (10) years.

RECOMMENDATION:

Staff recommends approval based on finding a through f with the following stipulations:

- 1. That the windows be inset one to two inches into the window frame and be made of wood.
- 2. If the applicant is considering the rehabilitation of the primary historic structure, staff recommends the applicant apply for Historic Tax Certification.

CASE MANAGER:

Lauren Sage





Flex Viewer

Powered by ArcGIS Server

Printed:Sep 13, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





































. .

1.1





6.1

4.0











PRELIMINARY DRAWING - NOT FOR CONSTRUCTION OR REGULATORY APPROVAL MICHAEL D. MAULDIN TEXAS #16733 Santa Monica Hotel Bldg. West Elevation Improvements San Antonio, Tx. 78207

SHEET TITLE: Building SCALE: N.T.S.	Site	Plan	SHEET	NUMBER
DATE: 08-31-2016			5	P









EXISTING CONDITIONS









SHEET TITLE: SHEET NUMBER Santa Monica Hotel Bldg. PRELIMINARY West Elevation-W/ Improvements DRAWING - NOT FOR CONSTRUCTION OR SCALE: 1/8" = 1'-0" West Elevation Improvements San Antonio, Tx. 78207 REGULATORY APPROVAL DATE: ARCHITECTS MICHAEL D. MAULDIN 09-14-2016 TEXAS #16733 SAN ANTONIO, TEXAS

NO PROPOSED WORK FOR EAST ELEVATION



MAULDIN ARCHITECTS SANANTONIO, TEXAS PRELIMINARY DRAWING - NOT FO CONSTRUCTION OR REGULATORY APPROVAL MICHAEL D. MAULI TEXAS #16733	West Elevation Improvements	SHEET ITTLE: Existing East Elevation SCALE 1/8"=1"-0" DATE: 08-31-2016	sheet number SK2
--	-----------------------------	--	---------------------



NO PROPOSED WORK FOR SOUTH ELEVATION





NO PROPOSED WORK FOR NORTH ELEVATION

