HISTORIC AND DESIGN REVIEW COMMISSION February 06, 2019

HDRC CASE NO: 2019-036

ADDRESS: 215 NELSON AVE

LEGAL DESCRIPTION: NCB 3888 BLK 4 LOT 16

ZONING: RM-4, H

CITY COUNCIL DIST.: 2

DISTRICT: Knob Hill Historic District

APPLICANT: Jordan Mengele/Sotex Property Brothers LLC **OWNER:** Jordan Mengele/Sotex Property Brothers LLC

TYPE OF WORK: Window replacement APPLICATION RECEIVED: January 10, 2019 60-DAY REVIEW: March 09, 2019

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to install new vinyl windows to replace existing, wood windows.

APPLICABLE CITATIONS:

- 6. Architectural Features: Doors, Windows, and Screens
- B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)
- i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
- ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. Glazed area—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. Window design—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. Muntins—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.
- vi. Replacement glass—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. Non-historic windows—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.
- viii. Security bars—Install security bars only on the interior of windows and doors.
- ix. Screens—Utilize wood screen window frames matching in profile, size, and design of those historically found when the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.
- x. Shutters—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

FINDINGS:

- a. The primary structure at 215 Nelson was constructed circa 1928 in the Craftsman style and first appears on a 1951 Sanborn Map. The one-story, single-family residential structure features both a front facing gabled roof and a rear hipped roof, wood lap siding, and a covered porch. Recently issued administrative approvals include: demolition of non-original rear addition, window repair, porch repair with column replacement, fencing, removal of vinyl siding, wood siding repair, and the removal of overgrown plantings. The primary and accessory structures are contributing to the Knob Hill Historic District.
- b. VIOLATION After receiving a report regarding window replacement at 215 Nelson on January 8, 2019, staff contacted the applicants to verify if they are complying with the approved scope of work. The applicants explained that the original wood windows were stolen during their repairs off-site and that they cannot afford in-

kind wood window replacements at this time. The applicants have been cooperative with staff in seeking compliance and submitted an application on January 10, 2019, to be heard at the next HDRC hearing.

- c. EXISITNG WINDOWS The windows prior to removal were deemed repairable according to the administrative approval to repair them issued on August 17. 2018. The structure originally featured nineteen (19) sashed wood windows:
 - 12 60" x 30" sashed window
 - 4 60" x 34" sashed window
 - 2 40" x 30" sashed window
 - 1-18" x 24" picture window
- d. NEW WINDOWS The proposed replacement windows are constructed with a vinyl frame, feature faux interior muntins and a dimension of 23.5" x 35.5". Per the Guidelines for Exterior Maintenance and Alterations 6.B.iv., new windows are to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair. Staff finds that the proposed windows do not match in size, configuration, or materials.

RECOMMENDATION:


Staff does not recommend approval based on findings a through d. Staff recommends in-kind replacement of the wood sash windows to match the original size, configuration, location, materials, and the standard stipulations. If in-kind replacement is approved, the applicant must submit updated window specifications to staff prior to the issuance of a Certificate of Appropriateness.

CASE COMMENT:

After receiving a report regarding window replacement at 215 Nelson on January 8, 2019, staff contacted the applicants to verify if they are complying with the approved scope of work. The applicants explained that the original wood windows were stolen during their repairs off-site and that they cannot afford in-kind wood window replacements at this time. The applicants have been cooperative with staff in seeking compliance and submitted an application on January 10, 2019 to be heard at the next HDRC hearing.

CASE MANAGER:

Huy Pham





Flex Viewer

Powered by ArcGIS Server

Printed:Jan 31, 2019

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





Ply Gem 23.5 in. x 35.5 in. Single
Hung Vinyl Window - White-510
Dimensions
Grid Width (in.)
3/4
Jamb Depth (in.)
2.6875
Product Depth (in.)
2.6875
Product Height (in.)
59.25
Product Width (in.)
31.375
Rough Opening Height (In.)
59.75
Rough Opening Width (In.)
31.875
Width (in.) x Height (in.)
31.375 x 59.25
Details
Exterior Color/ Finish
White
Exterior Color/Finish Family
White
Features Tile In Classica
Tilt-In Cleaning
Frame Material
Vinyl Eromo Typo
Frame Type Standard Frame
Glass Type
Low-E Glass
Glazing Type
Double-Pane
Grid Pattern


Colonial


Colonial

Grid Pattern

Grille Type
Grille Between Glass

Hardware Color/Finish Family	
White	
Included	
Grid, Hardware, Screen	
Insect screen included	
Yes	
Interior Color/Finish Family	
White	
Lock Type	
Standard Lock	
Lock Type	
Cam Action	
Locking	
Yes	
Number of Grids	
3 Wide 2 High	
Number of Locks	
1	
Privacy glass	
No	
Product Weight (lb.)	
36.8lb	
Returnable	
90-Day	
Solar Heat Gain Coefficient	
0.23	
Storm window	
No	
Tilt-in cleaning	
Yes	
Tinted glass	
No	
U-Factor	
0.29	
Window Type	
Single Hung	
Window Use Type	
New Construction	
1 10 W CONSTITUTION	





Stolen wood window to replace with vinyl

