HISTORIC AND DESIGN REVIEW COMMISSION

June 03, 2020

HDRC CASE NO: 2020-231

ADDRESS: 120 KING WILLIAM LEGAL DESCRIPTION: NCB 737 BLK 2 LOT 4

ZONING: RM-4,H

CITY COUNCIL DIST.: 1

DISTRICT: King William Historic District

LANDMARK: Individual Landmark

APPLICANT: Travis Louie

OWNER: Ronald Guyer/GUYER RONALD P & MADELINE N

TYPE OF WORK: Window relocation and replacement, exterior modifications

APPLICATION RECEIVED: May 12, 2020

60-DAY REVIEW: Not applicable due to City Council Emergency Orders

CASE MANAGER: Stephanie Phillips

REQUEST:

The applicant is requesting a Certificate of Appropriateness to:

- 1. Relocate a south elevation window to the east elevation.
- 2. Modify the existing fenestration on the rear elevation.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- ii. *Doors*—Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- iv. Screens and shutters—Preserve historic window screens and shutters.
- v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
- ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. Glazed area—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. *Muntins*—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.
- vi. *Replacement glass*—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. *Non-historic windows*—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.

viii. Security bars—Install security bars only on the interior of windows and doors.

ix. *Screens*—Utilize wood screen window frames matching in profile, size, and design of those historically found when the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.

x. *Shutters*—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

FINDINGS:


- a. The primary structure located at 120 King William is a 1-story residential structure constructed circa 1890 in the Folk Victorian style. The home features a stucco façade, a metal roof, and a full-width front porch. The structure is contributing to the King William Historic District.
- b. EXTERIOR MODIFICATIONS The applicant is requesting to perform two fenestration modifications, including the relocation of one window from the west to east elevation and modifying three windows on the rear elevation. Both requests are located on a rear addition. According to the Guidelines, existing openings should be preserved where possible, and new openings should match the pattern, dimensions, size, and inset. Staff generally finds the proposal appropriate given the location of the modifications and the reuse of the side window.

RECOMMENDATION:

Staff recommends approval based on findings a through b with the following stipulations:

- i. That the applicant matches the existing board and batten siding and profile.
- ii. That the applicant submits a final window specification for the rear windows prior to the issuance of a Certificate of Appropriateness. Staff finds fully wood windows to be appropriate. Meeting rails must be no taller than 1.25" and stiles no wider than 2.25". White manufacturer's color is not allowed, and color selection must be presented to staff. There should be a minimum of two inches in depth between the front face of the window trim and the front face of the top window sash. This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness. Window trim must feature traditional dimensions and architecturally appropriate sill detail. Window track components must be painted to match the window trim or concealed by a wood window screen set within the opening.

City of San Antonio One Stop


















EXTERIOR AND INTERIOR RENOVATION FOR

THE GUYER RESIDENCE

CONSTRUCTION DOCUMENTS (PRICING SET)

LOCATION MAP



SPECIAL INSPECTIONS

BC SECTION		APPLICABLE	NOT APPLICABLE			
1705.1.1	SPECIAL CASES	-	-			
1705.2	STEEL CONSTRUCTION	-	-			
1705.3	CONCRETE CONSTRUCTION	-	-			
1705.4	MASONRY CONSTRUCTION	-	-			
1705.5	WOOD CONSTRUCTION	-	-			
1705.6	SOILS	-	-			
1705.7	DRIVEN DEEP FOUNDATIONS	-	-			
1705.8	CAST-IN-PLACE FOUNDATIONS	-	-			
1705.9	HELICAL PILE FOUNDATIONS	-	-			
1705.10	SPECIAL INSPECTIONS FOR WIND RESISTANCE	-	-			
1705.11	SPECIAL INSPECTIONS FOR SEISMIC RESISTANCE	-	-			
1705.12	TESTING & QUALIFICATION OF SEISMIC RESISTNACE -					
1705.13	SPRAYED FIRE-RESISTANT MATERIALS -					
1705.14	MASTIC AND INTUMESCENT FIRE RESISTANT COATINGS	-	-			
1705.15	EXTERIOR INSULATION AND FINISH SYSTEMS (EIFS)	-	-			
1705.16	FIRE-RESISTANT PENETRATIONS AND JOINTS	-	-			
1705.17	SPECIAL INSPECTION FOR SMOKE CONTROL	-	-			
1706	DESIGN STRENGTHS OF MATERIALS	-	-			
1707	ALTERNATIVE TEST PROCEDURES	-	-			
1708	TEST SAFE LOAD	-	-			
1709	IN-SITU LOAD TESTS	-	-			
1710	PRECONSTRUCTION LOAD TESTS	-	-			
1711	MATERIAL AND TEST STANDARDS	-	-			

<u>ARCHITECT</u>

FISHER HECK ARCHITECTS 915 S. ST. MARY'S STREET SAN ANTONIO, TX 78205 PH: (210) 299-1500 FAX: (210) 299-1622 CONTACT: DAVID HANNAN JR EMAIL: dhannan@fisherheck.com www.fisherheck.com

STRUCTURAL ENGINEER

CALVETTI & ASSOCIATES 342 WILKENS AVE. SAN ANTONIO, TX 78210 PH: (210) 828-6419 FAX: (210) 534-0065 CONTACT: LAWRENCE CALVETTI EMAIL: lcalvetti@calprofengr.com www.calprofengr.com

CODE ANALYSIS

APPLICABLE CODES AND STANDARDS

2015 INTERNATIONAL FUEL GAS CODE

• ALTERATION - LEVEL 2

FIRE RESISTANCE RATINGS REQUIRED

STRUCTURAL FRAME

INTERIOR ROOF CONSTRUCTION

SMOKE AND CARBON MONOXIDE DETECTORS

AREAS:EXISTING DWELLING AREA - 1,215 SF

GENERAL

G-100 TITLE SHEET

DEMOLITION

D-100 DEMO SITE PLAN

LOCATION MAP, SPECIAL INSPECTIONS

A-200 EXTERIOR ELEVATIONS


A-300 BUILDING & WALL SECTIONS


A-400 INTERIOR ELEVATIONS


GENERAL NOTES


ARCHITECTURAL

DOOR & WINDOW SCHEDULES AND DETAILS












COPYRIGHT 2016 FISHER*HECK, INC. ALL RIGHTS RESERVED


SYMBOLS







ENLARGED DETAIL DESIGNATION



WALL PARTITION TYPE

KEYNOTE DESIGNATION


EXISTING CONSTRUCTION

EXISTING WALL CONSTRUCTION

NEW CONSTRUCTION

NEW FRAMED WALL CONSTRUCTION NEW CONCRETE WALL CONSTRUCTION





NORTH ARROW


GENERAL NOTES

- 1. THESE DOCUMENTS SHOULD NOT BE CONSIDERED AS A SURVEY OF EXISTING CONDITIONS. THE GENERAL CONTRACTOR SHALL FIELD VERIFY ALL EXISTING DIMENSIONS AND CONDITIONS, AND NOTIFY THE ARCHITECT OF ANY DISCREPANCIES OR OMISSIONS BETWEEN THE CONTRACT DOCUMENTS AND FIELD CONDITIONS BEFORE COMMENCING ANY WORK AND REQUEST CLARIFICATION.
- 2. ALL NOTES REFERENCE NEW WORK UNLESS NOTED AS EXISTING.
- 3. ALL SURFACES TO RECEIVE PAINT FINISH SHALL BE PREPARED TO SHOW NO DEFECTS. APPLY ONE COAT OF PRIMER-SEALER, THEN APPLY TWO FINISH COATS (NO STIPPLE FINISH ON ALL PAINTED
- 4. PATCH ALL SURFACES AND AREAS AFFECTED BY DEMOLITION AND PREPARE FOR NEW CONSTRUCTION.
- 5. THE EXTENT OF DEMOLITION WORK IS SHOWN ON THE DRAWINGS. IT IS NOT POSSIBLE TO SHOW REQUIRED DEMOLITION, REMODELING AND PATCHING IN EVERY DETAIL. THE CONTRACTOR SHALL VISIT THE FACILITY TO DETERMINE THE EXTENT OF DEMOLITION AND REMODELING WORK, AND TO FAMILIARIZE HIMSELF WITH THE CONDITIONS UNDER WHICH THE WORK WILL BE PERFORMED. NO ADDITIONAL COMPENSATION WILL BE ALLOWED FOR ADDITIONAL WORK REQUIRED AS A RESULT OF THE WORK INDICATED HEREIN OR FOR PATCHING REQUIRED AS A RESULT OF NEW WORK, REMODELING OR DEMOLITION.
- INSULATION BETWEEN EXISTING STUDS AFTER REMOVAL OF EXISTING INTERIOR SHEATHING.

BOARD AND BATTEN EXTERIOR WALLS ARE TO RECIEVE MIN. R-15 OPEN-CELL SPRAY FOAM

- 7. UNLESS SPECIFICALLY DESIGNATED FOR SALVAGE, DEMOLITION INCLUDES REMOVAL AND DISPOSAL OF DEMOLISHED MATERIALS. CONTRACTOR SHALL PROVIDE SUITABLE MEANS FOR DISPOSAL OF DEMOLISHED MATERIALS AND CONSTRUCTION DEBRIS.
- 8. ITEMS INDICATED FOR SALVAGE BY OWNER SHALL BE REMOVED BY THE CONTRACTOR AND DELIVERED TO OWNER'S DESIGNATED STORAGE AREA.
- 9. REMOVE ALL DEBRIS, RUBBISH AND OTHER MATERIALS RESULTING FROM DEMOLITION AND NEW CONSTRUCTION OPERATIONS.
- 10. ALL MATERIALS NOT DESIGNATED FOR SALVAGE BY OWNER SHALL BE THE PROPERTY OF THE
- CONTRACTOR AND SHALL BE REMOVED FROM THE SITE AND DISPOSED OF PROPERLY. 11. REPAIR, AT NO COST TO THE OWNER, DAMAGE CAUSED TO ADJACENT AREAS, MATERIALS AND EQUIPMENT BY DEMOLITION AND NEW CONSTRUCTION OPERATIONS.
- 12. WHERE PLUMBING FIXTURES ARE INDICATED TO BE REMOVED, PROPERLY TERMINATE ALL SUPPLY, WASTE AND VENT LINES BELOW SLAB AND/OR ABOVE FINISHED CEILING AS APPROPRIATE. WATER SUPPLY LINES SHALL BE REMOVED BACK TO NEAREST LIVE BRANCH LINE. CLOSE VENT PIPES THROUGH ROOF
- 13. WHERE ELECTRICAL DEVICES ARE SHOWN TO BE REMOVED, PROPERLY TERMINATE ALL WIRING. 14. ALL WALL CEILING AND FLOOR CONSTRUCTION WHICH IS AFFECTED BY MEP DEMOLITION IS TO BE
- PATCHED AND PREPARED FOR NEW CONSTRUCTION. 15. THE GENERAL AND SUBCONTRACTOR(S) MUST COMPLY WITH ALL RULES AND REGULATIONS OF AGENCIES HAVING JURISDICTION AND SHALL CONFORM TO ALL CITY, STATE, AND FEDERAL
- CONSTRUCTION SAFETY ADN SANITARY LAWS, CODES, STATUES, AND ORDINANCES. 16. ALL CONDENSATE LINES AND ROOF DOWNSPOUTS SHALL DISCHARGE AT LEAST 1'-0" AWAY FROM
- STRUCTURE SIDEWALL. 17. VERIFY W/ OWNER EXACT SIZE OF ALL EQUIPMENT FURNISHED BY OWNER FOR PROPER FIT W/
- CONTRACTOR SUPPLIED MILLWORK & CASEWORK. 18. ALL FURNITURE IS TO BE PROVIDED BY OWNER.
- 19. THE GENERAL CONTRACTOR IS RESPONSIBLE FOR THE MEANS, METHODS, AND TECHNIQUES OF CONSTRUCTION.SAFETY PRECAUTIONS IN CONNECTION WITH THE WORK, AND FOR THE ACTS OR OMISSIONS OF THE SUBCONTRACTORS.
- 20. ALL INSTALLED PLUMBING, MECHANICAL, AND ELECTRICAL EQUIPMENT SHALL OPERATE QUIETLY AND FREE FROM VIBRATION.
- 21. ALL PAINTS USED SHOULD COMPLY WITH LOW OR ZERO V.O.C. STANDARDS.
- 22. NEW HVAC SYSTEM IS TO BE DESIGN-BUILD BY LICENSED MECHANICAL CONTRACTOR. ALL EXISTING DUCTWORK AND GRILLES ARE TO BE CLEANED AND REUSED IF POSSIBLE. PROVIDE NEW ENERGY STAR RATED GAS FURNICE WITHIN REFINISHED EXISTING HVAC CLOSET AND CONNECT ALL EXISTING DUCTWORK AS REQUIRED. CONTRACTOR TO VERIFY IF EXISTING GAS LINE TO FURNICE EXISTS AND IS ACCEPTABLE CONDITION - REPLACE IF REQUIRED.
- 23. ALL NEW DOORS SHALL BE FRAMED WITH DOUBLE 2X10 HEADERS ABOVE AND DOUBLE 2X WOOD STUDS AT THE JAMBS.
- 24. PROVIDE ADEQUATE BLOCKING BEHIND WALLS AND CEILINGS WHERE PLUMBING AND ELECTRICAL FIXTURES ARE TO BE LOCATED.
- 25. ALL INTERIOR AND EXTERIOR WALLS ARE TO RECEIVE 2 COATS OF NEW PAINT AFTER PLASTER REPAIR

PARTITIONS



A

TYPE	STUD SIZE	SAB	STC	WALL THK_	MAX HT 5 PSF
A3	2X4	45	-	4-1/2"	13'-6"
A6	2X6	45	-	6-1/2"	15'-0"



GUYER RESIDENCE

S - S

He

Fisher

11/22/2016


COPYRIGHT 2016


FISHER*HECK, INC.

ALL RIGHTS RESERVED

REVISION DATE

WINDOW ELEVATIONS & DETAILS






D2 KITCHEN WINDOW DETAIL

1 1/2" = 1'-0"

DOOR SCHEDULE

•	PANEL		FRAME		DETAILS					
NUMBER	PAIR	TYPE	MATERIAL	TYPE	MATERIAL	HEAD	JAMB	THREASHOLD	HARDWARE	COMMENTS
101A	PAIR	В	WD-1	EXST	WD-2	EXST	EXST	EXST	A-1	[1], [3],
101B		-	-	EXST	WD-2	EXST	EXST	EXST	-	[2], [3], [4],
102		-	-	EXST	WD-2	EXST	EXST	EXST	-	[3], [4], [5]
103		С	WD-1	EXST	WD-2	EXST	EXST		A-1	[1], [7]
104		D	WD-1		WD-2				D-1	[6], [8]
105		D	WD-1	EXST	WD-2	EXST	EXST	EXST	B-1	[3], [8]
106A	PAIR	В	WD-1	EXST	WD-2	EXST	EXST	EXST	A-1	[1], [3],
106B		Α	WD-1		WD-2				B-1	[9]
106C		D	WD-1	EXST	WD-2	EXST	EXST	EXST	C-1	[3], [8]
107		D	WD-1	FXST	WD-2	FXST	FXST	FXST	C-1	[3], [8]


MATERIAL LEGEND		COMMENTS LEGEND				
WD-1 WOOD, STAINED WD-2 WOOD, PAINTED TO WD-3 PRESSURE TREATI STL-1 STEEL TG CLEAR TEMPERED FG FROSTED PRIVACY	ED WOOD, PAINTED TO MATCH SIDING GLASS	 [1] STRIP, CLEAN AND RE-STAIN EXISTING DOOR PANEL. CLEAN AND REPAIR EXISTING GLAZING AS REQUIRED. REPLACE ALL EXISTING CRACKED OR BROKEN GLASS PANES AS REQUIRED. CLEAN STRIP AND REFINISH SEALANT AROUND GLASS PANES AND RE-SEAL. [2] CAREFULLY REMOVE EXISTING DOOR PANEL. STRIP AND RE-STAIN PANEL AND PREP TO BE REINSTALLED AT DOOR 106C LOCATION. [3] STRIP AND PREP EXISTING FRAME AND TRIM TO BE PAINTED. REPAIR ANY DAMAGED SECTIONS AS NEEDED. [4] PATCH AND REPAIR SECTIONS OF DOOR FRAME WHERE EXISTING HARDWARE HAS BEEN REMOVED. [5] CAREFULLY REMOVE EXISTING DOOR PANEL. STRIP, CLEAN AND RE-STAIN PANEL AND PREP 				
	B-1 PRIVACY LOCKSET 3 HINGES PER PANEL (AS NEEDED) 1 PRIVACY LOCKSET 1 KEYING BALDWIN - PV.TAP.RSR.481 D-1 SLIDING POCKET PRIVACY LOCKSE 1 POCKET SLIDING TRACK 1 PRIVACY LOCKSET FOR POCKET DOO! RIVACY LOCKSET CK (HORSESHOE FLAT TRACK HARDWARE - #SF-HR; BLACK)					



DOOR PANEL ELEVATIONS


1/4" = 1'-0"


Fisher Heck
ARCHITECTS
915 South St. Mary's Street




THE GUYER RESIDENCE
120 KING WILLIAM STREET, SAN ANTONIO, TX 78

PROJECT NO. 1514 A2







_____WOOD BASE (MATCH EXISTING SIZE & PROFILE)_____TBD_

LIGHT GREY-

WITH MATCHING WHITE GROUT

WD-1_____STAINED WOOD FLOORING TO MATCH EXISTING_____TBD_

_WB-X______EXISTING WOOD BASE -_PAINTED___

_WD-1X_____EXISTING WOOD CEILING --STAINED_

-WD-2X———EXISTING WOOD CEILING --PAINTED—

WT-1———CERAMIC SUBWAY WALL TILE—

WT-2———12X12 CERAMIC WALL TILE—

STRIP AND REFINISH EXISTING WOOD BASE. REPAIR ANY DAMAGED SECTIONS AS REQUIRED PRIOR TO REFINISHING

KEY NOTES

01 TILE FLOOR THRESHOLD.

02 STRIP AND REFINISH EXISTING WINDOW FRAME TRIM, SASHES AND HARDWARE. REPAIR AND/OR REPLACE ANY DAMAGED PIECES OF WOOD TO MATCH EXISTING SPECIES.

03 WOOD FRAMED, DOUBLE-PANE WINDOW TO MATCH EXISTING STYLE AND SIZE. APPLY FROSTED

WINDOW FILM TO INTERIOR FACE OF GLAZING. 04 WOOD FRAMED, DOUBLE-PANE WINDOW TO MATCH

05 AC CONDENSER CAST IN PLACE CONCRETE PAD. COORDINATE WITH MECHANICAL CONTRACTOR ON OVERAL SIZE REQUIRED. PAD IS TO BE AT LEAST 2' AWAY FROM EXISTING FOUDNATION WALL.

06 INSTALL NEW SURFACE MOUNTED HOSE BIBB WITH INSULATED COPPER PIPE AGAINST WALL.

07 EXISTING GAS METER.

08 REPAIR INTERIOR WALLS OF FIREPLACE AND PAINT WITH A HIGH HEAT ENAMEL PAINT. REPAIR

S |

Fish

COPYRIGHT 2016

FISHER*HECK, INC. ALL RIGHTS RESERVED

PLASTER CHMINEY FINISH AND PAINT.

09 SLIDE-IN GAS RANGE PER SCHEDULE. 10 UNDER-COUNTER DISHWASHER AND DRYER PER

12 CONTRACTOR TO REVIEW EXISTING CONDITIONS OF BATHROOM FLOOR. INSTALL NEW 2X6 JOISTS @16"O.C. CONSULT WITH ENGINEER AND ARCHITECT AS REQUIRED TO PROVIDE A FINISH FLOOR. ALL SIMPSON JOIST HANGER AND

13 STABILIZED GRAVEL DRIVEWAY

14 EXISTING ACCESSORY STRUCTURE 15 INFILL DEMOLISHED WINDOW OPENIGN WITH MATCHING WALL CONSTRUCTION AND EXTERIOR

16 WALL SCONCE FIXTURE. 18 NEW METAL CLAD WOOD WINDOW; TRIPLE CASEMENT. REFER TO WINDOW ELEVATION

19 PREFINISHED METAL DOWNSPOUT WITH PRECAST

20 PREFINISHED METAL DOWNSPOUT.

21 STAINED WOOD LAPYERE STAIR (i.e. ALTERNATE

TREAD STAIRCASE). 22 TOILET FIXTURE. INSTALL TO ALIGN WITH EXISTING

DRAIN PIPE. CONTRACTOR TO VERIFY CONDITION OF EXISTING DRAIN PIPE TO BE FUNCTIONAL AND CODE COMPLIANT. REPLACE EXISTING CAST IRON PIPE WITH PVC, BACK TO MAIN LINE CONNECTION AT STREET.

24 FREESTANDING WHIRPOOL STAINLESS STEEL REFRIDGERATOR (WRB329DMBM).

27 CLEAN AND PREP EXISTING RETURN AIR GRILLE TO BE REPAINTED TO MATCH THE WALL COLOR.

30 CAST IN PLACE CONCRETE PAD FOR EXTERIOR GRADE WATER SOFTENER AND ENCLOSURE. PROVIDE NECESSARY PLUMBING AND ELECTRICAL CONNECTIONS REQUIRED PER MANUFACTURER.

33 WALL MOUNTED, EXTERIOR GRADE TANKLESS WATER HEATER

34 CONSTRUCT NEW PLYWOOD PLATFORM FOR NEW

35 2" SQ. BLACK IRON RAILING WITH 3/4"DIA HORIZONTAL IRON BALUSTERS @ 6" O.C. REPAIR EXISTING CONCRETE FOUNDATION WALL

39 INSTALL NEW CONCRETE PIER AT CORNER TO

MATCH EXISTING

40 INFILL BETWEEN CONCRETE PIERS WITH

41 REMOVE LOOSE DIRT AND LEVEL OUT FLOOR SURFACE. INSTALL SALVAGED DHANIS BRICK PAVERS IN RUNNING BOND PATTERN ON 1" SAND

42 EXISTING STONE RETAINING WALL. BUILD UP TO BOTTOM OF EXISTING WOOD JOISTS. 43 PRESSURE TREATED WOOD STUD WALL WITH 1/2"

PRESSURE TREATED PLYWOOD SHEATHING FOR

MOUNTING OF ELECTRICAL PANEL 44 2" SQ IRON HANDRAIL @ 36" AFF, MOUNTED TO

STONE WALL AND JOINED TO RAILING ABOVE.

45 REFINISH EXISTING WOOD COLUMNS; STAINED.

46 REFINISH EXISTING WOOD FLOOR BOARDS; STAINED & SEALED.

47 CLEAN OFF ALL DIRT FORM EXISTING FLOOR AND APPLY A THIN COAT OF SELF-LEVELING CONCRETE TOPPING, THEN STAIN TO MATCH WOOD STAIR

48 LEAVE OPENING IN WALL FOR VENTILATION THROUGH CRAWL SPACE.


49 INSTALL POLYURETHANE VAPOR BARRIER OVER TOP OF EXISTING DIRT SURFACE.

PROJECT NO. 1514 A2

 \triangle REVISION DATE

RESIDENCE

GUYER I



FIRST FLOOR REFLECTED CEILING PLAN

KEY NOTES

- 01 CEILING FAN FIXTURE L3. INSTALL ADDITIONAL BLOCKING ABOVE CEILING FOR SUPPORT AS REQUIRED.
- 02 CLEAN AND PAINT EXISTING AIR GRILLE TO MATCH ADJACENT SURFACE
- COLOR.

 O3 INSTALL NEW ONE WAY SUPPLY AIR GRILLE AIMED TOWARD WINDOW. SIZE
- TO MATCH EXISTING. PAINT TO MATCH CEILING

 REFINISH EXISTING ATTIC DOOR. REPAIR DAMAGED TREADS AND SUPPORT
- HARDWARE OF STAIR

 05 DECORATIVE PENDANT LIGHT FIXTURE L4.
- 6 FIXED RECESSED LED LIGHT FIXTURE L5; CENTERED ON JOINT BETWEEN
- WOOD CEILING BOARDS.

 VANITY WALL SCONCE LIGHT FIXTURE L8.

WALL SCONCE LIGHT FIXTURE - L1.

THE FULL THICKNESS OF THE RAFTER.

- INSTALL NEW LIGHT SWITCHES AND FACEPLATE AT EXISTING LOCATION.
- MODIFY FIXTURE WIRING AS REQUIRED.
- INSTALL REFINISHED EXISTING CEILING BOARDS AND PAINT TO MATCH ADJACENT CEILINGS. PRIOR TO INSTALLATION, INSULATE BETWEEN EXISTING ROOF RAFTERS WITH OPEN-CELL SPRAY FOAM INSULTATION TO
- 1 KITCHEN HOOD VENT PER SCHEDULE. INSTALL REQUIRED VENT PIPE THROUGH ROOF WITH FLASHING PER CODE.
- RECESSED ADJUSTABLE L.E.D. LIGHT FIXTURE L6.
- RECESSED ADJUSTABLE L.E.D. LIGHT FIXTURE L7; CENTERED ON THE
- WINDOW PANES AND COUNTERTOP BELOW.

 14 SIDEWALL EXHAUST FAN
- 15 EXISTING FURR DOWN FOR MECHANICAL DUCT. REPAIR ANY DAMAGED PLASTER AND PREP FOR PAINTING. COLOR TO MATCH THE WALL COLOR.
- 23 UNDERCABINET LED STRIP LIGHT.
- 3-WAY LIGHT SWITCH FOR BASEMENT LIGHT FIXTURES.
- WALL SCONCE LIGHT FIXTURE L2.
- DIMMER SWITCH.
- BATHROOM WALL SCONCE LIGHT FIXTURE L9; CENTERED ABOVE EXISTING WINDOW REFER TO ELEVATION.



11/22/2016

COPYRIGHT 2016
FISHER*HECK, INC.
ALL RIGHTS RESERVED

LIGHT FIXTURE LEGEND

L1 DARKENED COPPER WALL SCONCE (DIRECT FROM MEXICO #AS3232)

- INSTALL WITH 75 WATT EQUAL L.E.D. BULB; 3000K MAX

WHITE OVAL OUTDOOR WALL SCONCE (SEA GULL LIGHTING #GX3170)

- INSTALL WITH 75 WATT EQUAL L.E.D. BULB; 3000K MAX

L3 HUNTER WINDEMERE CEILING FAN (#59039 BRUSHED NICKEL FINISH)
-INSTALL WITH TWO 40 WATT EQUAL L.E.D. BULBS; 3000K MAX
-INSTALL WALL MOUNTED CRADLE ACCESSORY FOR REMOTE

L4 20TH C. FACTORY FILAMENT MILK GLASS CAFÉ ROUND PENDANT BY
RESTORATION HARDWARE; 5 CHORD; (#68070493 PNMK)
-INSTALL WITH 40 WATT EQUAL DIMMABLE L.E.D. BULBS; 2700K MAX
-POLISHED NICKEL FINISH

L5 5" DIA RECESSED, FIXED L.E.D. LIGHT FIXTURE WITH WHITE TRIM; 3000K MAX

L6 5" DIA RECESSED, ADJUSTABLE L.E.D. LIGHT FIXTURE WITH WHITE TRIM; 3000K

L7 4" DIA RECESSED, ADJUSTABLE L.E.D. LIGHT FIXTURE WTH WHITE TRIM; 3000K MAX

L8 MODERN FORMS VOGUE 3-LIGHT L.E.D. WALL SCONCE (*MFDE1065*)
-INSTALL VERTICALLY PER INTERIOR ELEVATION
-BRUSHED NICKEL FINISH

L9 MODERN FORMS VOGUE 6-LIGHT L.E.D. WALLS CONCE (*MFDE1067*)
-INSTALL HORIZONTALLY PER INTERIOR ELEVATION
-BRUSHED NICKEL FINISH

RIOR RENOVATION FOR

THE GUYER RESIDENCE

120 KING WILLIAM STREET, SAN ANTON
REFLECTED CEILING PLAN


PROJECT NO. 1514 A2


Approximately revision date

SHEET NO.

102







THE GUYER RESIDENCE

FISHER*HECK, INC. ALL RIGHTS RESERVED

🗦 IRON RAILING 🚣 1X2 STAINED WOOD TRIM ON THREE SIDES OF EXISTING OPENING BASE BOARD TO MATCH EXISTING; PAINTED SELACE EXISTING WOOD SUPPORT FRAMING. CLEAN REFINISH BY STAINING TO MATCH WOOD FLOOR 5" (FIELD VERIFY) NEW BASEBOARD TO MATCH EXISTING — REINSTALLED-REFINISHED FLOORING — CONTINUOUS 2X8 BEAM **BOLTED TO EXISTING** FRAMING. — BUILD LIMESTONE WALL UP TO UNDERSIDE OF WOOD STRINGER WHILE TIEING INTO EXISTING STONE WALL 2X BLOKING WITH FACE MOUNTED — 4 LAYERS OF 3/4" PLYWOOD; SCONCE LIGHT FIXTURE GLUED TOGETHER TO FORM CENTER STRINGER (2 LAYERS PER COLUMN. STAINED TO MATCH WOOD FLOOR ABOVE. REMOVE STEEL MESH —— INSTALL SECONDARY 3/4" STAINED PLYWOOD STRINGER AT SCREEN WITHIN EXISTING OPENING; CLEAN AND SEAL EACH END OF STAIR, JUST OFFSET FROM EXISTING
MASONRY WALL FOR ADDITIONAL STAINED 3/4" PLYWOOD TREADS AND RISERS; GRAIN FOR BOTH RISERS AND SUPPORT. TREADS TO RUN PERPENDICULAR TO STONE WALL CLEAN EXISTING STONE WALL (TYPICAL THROUGHOUT BASEMENT EXISTING CONCRETE FLOOR
WITH NEW SELF-LEVELING AREA) TOPPING; STAINED EXISTING ----STONE RETAINING WALL BASEMENT 93'-8" C5 STAIR SECTION DETAIL

1" = 1'-0"

COPYRIGHT 2016 FISHER*HECK, INC.

ALL RIGHTS RESERVED

