HISTORIC AND DESIGN REVIEW COMMISSION

February 03, 2021

HDRC CASE NO:	2021-028
ADDRESS:	1829 N NEW BRAUNFELS AVE
LEGAL DESCRIPTION:	NCB: 1268 BLK: 4 LOT: 9 KITCHEN SUBDIVISION
ZONING:	C-2 IDZ, H
CITY COUNCIL DIST.:	2
DISTRICT:	Government Hill Historic District
APPLICANT:	Pam Carpenter/Seventh Generation Design, Inc.
OWNER:	GOVERNMENT HILL SQUARE
TYPE OF WORK:	Removal of existing, historic blade sign
APPLICATION RECEIVED:	January 15, 2021
60-DAY REVIEW:	Not applicable due to City Council Emergency Orders
CASE MANAGER:	Edward Hall

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to remove the existing, historic blade sign at 1829 N New Braunfels and place in storage until the sign can be rehabilitated and re-installed.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 6, Guidelines for Signage

B. HISTORIC SIGNS

i. Preservation—Preserve historic signs, such as ghost signs or other signs characteristic of the building's or district's period of significance, whenever possible.

ii. Maintenance—Repair historic signs and replace historic parts in-kind when deteriorated beyond repair.

FINDINGS:

- a. The applicant is requesting a Certificate of Appropriateness for approval to remove the existing, historic blade sign at 1829 N New Braunfels and place in storage until the sign can be rehabilitated and re-installed.
- b. The historic structure at 1829 N New Braunfels, commonly known as the Emil Weilbacher Building was constructed in 1921 and is contributing to the Government Hill Historic District. The existing blade sign, while not original to the structure, is also contributing, and was installed in the mid-20th century.
- c. BLADE SIGN REMOVAL At this time, the applicant has proposed to remove the existing, contributing blade sign from the façade of the historic structure and to store it off site until it can be rehabilitated and re-installed. The applicant has noted that the sign will be stored off site until funds can be raised, not to exceed a ten-year period. Staff finds the removal of contributing features to be inappropriate and the removal of the historic sign to be inconsistent with the Guidelines for Signage 1.B.i., which notes that historic signage should be preserved.
- d. BLADE SIGN REMOVAL While the sign has fallen into disrepair, staff finds that historic elements that contribute to the integrity of a historic structure and district should remain in place. If the sign is to be removed for maintenance or repair, it should be reinstalled in a timely manner. Staff does not find the potential removal for up to ten years to be appropriate.

RECOMMENDATION:

Staff does not recommend approval based on findings a through d. Staff recommends that the sign be maintained in place rather than be removed and placed in off-site storage.

City of San Antonio One Stop




January 29, 2021

 1:1,000

 0
 0.0075
 0.015
 0.03 mi

 ├
 ·
 ·
 ·
 ·
 ·

 0
 0.0125
 0.025
 0.05 km



January 15, 2020

933 North Flores Street, Suite B San Antonio, Texas 78212

Ms. Shanon Miller, AICP Director of the Office of Historic Preservation Development and Business Services Center 1901 South Alamo Street San Antonio, Texas 78204

RE: 1829 N. New Braunfels Ave., Weilbacher Building Rehabilitation, Request for Sign Removal (SGD Project No. 1622)

Dear Ms. Miller, OHP Staff Members and HDRC Commissioners,

As you are aware, the owners of 1829 North New Braunfels Avenue (Emil Weilbacher Building), Government Hill Square Properties, recently concluded a significant rehabilitation of the historic property that at one point was placed by the OHP on the Vacant Buildings Program List. The property has been transformed into an attractive and economically functioning contributor to the Government Hill Historic Neighborhood District. The property owners and design team wish to thank OHP and HDRC for their role in this transformation.

The historic property's rehabilitation came at great financial cost to the property owners, and the available funding for the project has been expended in the effort. Not all elements in need of repairs and refurbishment could be included in the project's budget and scope of work, with some being postponed for future phases. The project's rehabilitation proposal, which received a Certificate of Appropriateness, called for the retention of the building's existing blade sign, but not its rehabilitation due to budgetary limitations. It is the property owners' full intention to eventually restore the sign by refacing it, re-wiring its electrical components, and re-installing it on the building's façade with new structure to replace the deteriorated existing structure. However, the owner and project team became aware during the rehabilitation project that retaining the sign *in situ* given its significant physical deterioration is an untenable proposition with potential risks to public safety and continued deterioration to this character-defining element. The property owners respectfully request permission to remove the blade sign and place it in storage for future rehabilitation.

The following provides additional details to inform your evaluation of this request:

A. Current Condition of Sign

While assumed not original to the Weilbacher Building (built 1921), the existing metal blade sign appears to date from the mid-20th century and may be considered a character-defining feature of the primary façade of the building. As a result, the original scope of permitted work for the building included rehabilitation of the sign (see attached architectural drawing sheets and photographic documentation). Years of exposure and lack of maintenance, preceding the current property owner, has deteriorated the paint finish and exposing the metal case of the sign. Most of the original neon lighting tubes are broken or missing. And the structural armature suspending the sign from the building's parapet and façade is requiring substantial repairs or wholesale replacement to secure the sign properly and safely.

B. Reason for Temporary Removal and Storage of Blade Sign

A qualified sign contractor provided the property owners with a cost estimate of \$25,0000 to rehabilitate the sign. This exceeds the available contingency funding for the current phase of rehabilitation of the property. This COA request proposes to temporarily remove the sign for safekeeping for rehabilitation during a future phase of the project. Acknowledging the iconic potential for the sign, it is the owners' intention to collaborate with community organizations (e.g., SAGE, Conservation Society of San Antonio, Government Hill neighborhood associations, etc.) to find funding to have the sign possibly restored as a Government Hill District gateway marker.

C. Terms and Stipulations for Permission for Temporary Removal and Storage of Blade Sign

If the City of San Antonio issues a Certificate of Appropriateness required for removal to remove of the existing blade sign located at 1829 N. New Braunfels Ave., Government Hill Properties will store it until funds are raised to rehabilitate and reinstall the sign. Government Hill Properties will commit to completion of the rehabilitation and reinstallation of the sign within 10 years. The sign will be kept in storage at location(s) known to OHP at all times. Community and District fundraising for the sign's restoration will be pursued to have the sign rehabilitated and reinstalled as soon as possible. In fact, once \$20,000 is raised, work would be authorized by Government Hill Properties to begin the sign's rehabilitation. During the fundraising period, Government Hill Properties will commit and set aside \$2500 annually to go towards the sign's eventual restoration and reinstallation. In other words, without any outside fundraising, Government Hill will set aside \$25,000 during the next ten years and contribute any additional funds needed in the tenth year to have the sign rehabilitated and reinstalled. Government Hill Properties further requests that the City of San Antonio also agrees that Government Hill Properties will retain all rights and the full authority to determine the content and the layout of the original sign faces, subject only to the normal regulations of the UDC's Signage Ordinance.

Please feel free to contact me should you have any questions regarding this CoA application or if you need additional supporting material. As always, thank you for your assistance and expertise.

Best regards,

with Mm. argunt

Scott Wm. Carpenter, RA, LEED AP Principal, Seventh Generation Design, Inc.

CC: Government Hill Properties, PJC

Attachments:

- Selective drawing sheets from Construction Documents, dated 11/12/2018
- Photographs of Existing Conditions

EMIL WEILBACHER BUILDING REHABILITATION Government Hill Square Properties, LP.

1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208



EXISTING BUILDING TO BE REHABILITATED

ISSUED FOR PERMIT SET

11/13/2018

SEVENTH GENERATION DESIGN ARCHITECTURE | SUSTAINABILITY | PRESERVATION 118 Broadway, Suite 519 San Antonio, Texas 78205 TEL (210) 262-6161 TEL (210) 241-7490 OWNER: Government Hill Square Properties, LP. 209 East Riverside Drive Austin, Texas 78704 TEL (210) 227-2724

CIVIL ENGINEER:

SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808

STRUCTURAL ENGINEER:

Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203 San Antonio, Texas 78230 TEL (210) 227-3647

MEP ENGINEER:

CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841

EMIL WEILBACHER BUILDING REHABILITATION

1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208

No.	Date	Description
1	08-22-2017	95% Construction Set
2	05-01-2018	Draft Permit Set
3	11-13-2018	Permit Set
6	08-13-2019	Addendum 4 Construction Set



ELEVATION GENERAL NOTES:

- 1. SCRAPE, SAND AND REMOVE RUST, DIRT AND PAINT BUILD UP FROM ALL EXISTING SCUPPERS, DOWNSPOUTS AND MISCELLANEOUS METAL FASTENERS AND STRUCTURAL SUPPORTS SCHEDULED FOR REUSE. TYPICAL - ALL LOCATIONS AND MATERIALS
- 2. PRIME ALL SCUPPERS, DOWNSPOUTS AND MISCELLANEOUS METAL COMPONENTS WITH RUST INHIBITING PRIMER, PREP AND PRIME FOR PAINTING AS RECOMMENDED BY PAINT MANUFACTURER.

THE BUILT-UP ROOF OVER THE EXISTING BUILDING IS NEW. PROTECT IT DURING THE INSTALLATION OF NEW MECHANICAL EQUIPMENT

> CLEAN, REPAIR, AND REPOINT HISTORIC CAST STONE & BRICK MASONRY.

REPAIR LEADER HEADS AND DOWNSPOUTS AS REQUIRED, PAINT- TYP.

NEW ALUMINUM STOREFRONT SYSTEM AT TRANSOMS


NEW FLASHING AND COUNTER FLASHING AT TRANSOM SILL. REPAIR OR REPLACE ALL DETERIORATED WOOD TRIM AND STRUCTURAL COMPONENTS BETWEEN STOREFRONT WINDOWS AND TRANSTOMS (TYP.).


NEW ALUMINUM STOREFRONT SYSTEM, FRONT GLAZED WITH DARK BRONZE ANODIZED FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE ANODIZED FINISH, TYP.


> CLEAN, REPLACE, AND REPAIR EXISTING TILE BULKHEADS, TYP.

REPLACE MISSING SILL TILES WITH SIMILAR










BEYOND.	
TING CLEAN & PROTECT HISTORIC STONE INSCRIPTION.	
REPAIR AND REASSEMBLE FRESNEL PANELS IN NEW FRAMES TO BE INSTALLED ON THE EXTERIOR OF THE NEW ALUMINUM STOREFRONT TRANSOMS.	ARC
EXTERIOR CANOPY TO BE SIMILAR TO 1901 N. NEW BRAUNFELS CANOPY ACROSS THE STREET. REUSE SALVAGED ORIGINAL CANOPY COMPONENTS WHEN POSSIBLE. PREP & PAINT ALL EXPOSED ANCHOR ELEMENTS & RODS.	G
	STRUC
8'-8" NEW LIGHT FIXTURE TO BE INSTALLED - TYPICAL	106
NEW WOOD TRIM ABOVE STORE FRONT SYSTEM, PAINTED, TYP.	MEP Er
EXTERIOR ALUMINUM STOREFRONT DOORS TO PROVIDE ADA CONFIGURATION AT NORTHEAST CORNER ENTRANCE.	
01 FLOOR PLAN 0"	EI BI
CLEAN, REPLACE, AND REPAIR EXISTING TILE BULKHEADS, TYP.	R
	182 SA
	No. 1 2 3 6
EXISTING VENTS IN CLAY TILE WALL TO BE CLOSED & SEALED WITH PAINTED REAR MOUNTED METAL PLATE -TYP.	
 PAINTED METAL CANOPY AT DOOR OVERHANG TO MATCH MAIN CANOPY WITH GUTTER OR DIVERTER 	
LIGHT FIXTURE RE: ELECTRICAL DRAWINGS - TYPICAL	
NEW TRADITIONAL STANDING SEAM METAL ROOF WITH GALVANIZED FINISH INSTALLATION UNDER SEPARATE CONTRACT BY OTHERS.	PI E
NEW GALVANIZED GUTTER AND DOWNSPOUT BY OTHERS.	EI
ADDITION PLATE HT. 11'-5 3/4"	
3 PART STUCCO ON GALVANIZED METAL LATH	
WITH ELASTOMERIC COATING	
LIGHT FIXTURE RE: ELECTRICAL DRAWINGS - TYPICAL	
0" NEW STEEL FLUSH PANEL DOOR AND FRAME, PAINTED, WITH GLAZED TRANSOM ABOVE.	Pro Dat Dra
*	Che

TEL (210) 227-2724 CIVIL ENGINEER: SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808 STRUCTURAL ENGINEER: Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203 San Antonio, Texas 78230
TEL (210) 227-3647 MEP ENGINEER: CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841
EMIL WEILBACHER BUILDING BUILDING BUILDING HABILITATION 1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208 No. Date Description 1 08-22-2017 95% Construction Set 2 05-01-2018 Draft Permit Set 3 11-13-2018 Permit Set 6 08-13-2019 Addendum 4 Construction Set
PROPOSED EXTERIOR ELEVATIONS
Project number 1622 Date 11/13/2018
Date 11/13/2018 Drawn by Checked by A3.01 Scale 1/4" = 1'-0"



	NEW WINDOW SYSTEM AND FRAMING, TYPICAL	
	MAINTENANCE AND REPAIRS TO EXISTING ROOF, IN SEPARATE CONTRACT.	Seventh Generation
	CLEAN, REPAIR, AND REPOINT HISTORIC CAST STONE AND BRICK MASONRY, TYP.	DESIGN
	REPAIR LEADER HEADS TOP OF PARAPET AND DOWNSPOUTS, AS 18'-6"	118 Broadway, Suite 519 San Antonio, Texas 78205 TEL (210) 262-6161 TEL (210) 241-7490 OWNER:
	NEW ALUMINUM STOREFRONT SYSTEM AT TRANSOMS BEHIND FRESNEL PANEL, FRONT GLAZED WITH DARK BRONZE FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE FINISH TO MATCH STOREFRONT WINDOWS BELOW.	Government Hill Square Properties, LP. 209 East Riverside Drive Austin, Texas 78704 TEL (210) 227-2724
	NEW FLASHING AND COUNTER FLASHING AT TRANSOM SILL. REPAIR OR REPLACE ALL DETERIORATED WOOD TRIM AND STRUCTURAL COMPONENTS BETWEEN STOREFRONT WINDOWS AND TRANSTOMS	CIVIL ENGINEER: SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808
	(TYP.). 	STRUCTURAL ENGINEER: Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203
	NEW ALUMINUM STOREFRONT WINDOW SYSTEM, FRONT GLAZED WITH DARK BRONZE FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE FINISH.	San Antonio, Texas 78230 TEL (210) 227-3647 MEP ENGINEER:
	CLEAN AND REPAIR EXISTING TILE BULKHEADS, TYP.	CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841
	01 FLOOR PLAN 0"	EMIL WEILBACHER BUILDING
		REHABILITATION
		1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208
		No.DateDescription108-22-201795% Construction Set205-01-2018Draft Permit Set311-13-2018Permit Set608-13-2019Addendum 4 Construction Set
	V.I.F. LOCATION OF EXISTING TRAFFIC POLE IN NEW CANOPY	
	EXTERIOR CANOPY TO BE SIMILAR TO 1901 N. NEW BRAUNFELS CANOPY ACROSS THE STREET. REUSED SALVAGED ORIGINAL CANOPY COMPONENTS WHEN POSSIBLE. PREP & PAINT ALL EXPOSED ANCHOR ELEMENTS & RODS.	
	ADDITION PLATE HT. 11'-5 3/4"	PROPOSED EXTERIOR
		ELEVATIONS
	CLEAN, REPAIR, AND REPOINT HISTORIC BRICK AND STRUCTURAL CLAY TILE MASONRY WALLS (TYPICAL).	
		STERED ARCHITECT
<u>A</u>	<u>01 FLOOR PLAN</u> 0"	SA 74665 45
		Swff 11/1. Jarpent 11/13/2018
*		Project number1622Date11/13/2018Drawn by
		Checked by A3.02
		Scale 1/4" = 1'-0"



Name: Address: Description: Date: Emil Weilbacher Building Rehabilitation 1829 North New Braunfels Ave., San Antonio, Texas View looking NNW toward southeast corner of building October 7, 2016 (Prior to Rehabilitation)

Photograph No.



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking NNW toward southeast corner of buildingDate:October 7, 2016 (Prior to Rehabilitation)





Name:Emil Weilbacher Building RehabilitationPhotograph No.Address:1829 North New Braunfels Ave., San Antonio, TexasBescription:View looking west across New Braunfels Ave. at east facadeDate:October 7, 2016 (Prior to Rehabilitation)GVHL-03



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking southwest at northeast corner of buildingDate:October 7, 2016 (Prior to Rehabilitation)





Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking south across Carson St. at north facade of buildingDate:October 7, 2016 (Prior to Rehabilitation)

Photograph No.



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:Detail view of south face of blade sign on east facadeDate:October 7, 2016 (Prior to Rehabilitation)



EMIL WEILBACHER BUILDING REHABILITATION Government Hill Square Properties, LP.

1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208



EXISTING BUILDING TO BE REHABILITATED

ISSUED FOR PERMIT SET

11/13/2018

SEVENTH GENERATION DESIGN ARCHITECTURE | SUSTAINABILITY | PRESERVATION 118 Broadway, Suite 519 San Antonio, Texas 78205 TEL (210) 262-6161 TEL (210) 241-7490 OWNER: Government Hill Square Properties, LP. 209 East Riverside Drive Austin, Texas 78704 TEL (210) 227-2724

CIVIL ENGINEER:

SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808

STRUCTURAL ENGINEER:

Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203 San Antonio, Texas 78230 TEL (210) 227-3647

MEP ENGINEER:

CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841

EMIL WEILBACHER BUILDING REHABILITATION

1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208

No.	Date	Description
1	08-22-2017	95% Construction Set
2	05-01-2018	Draft Permit Set
3	11-13-2018	Permit Set
6	08-13-2019	Addendum 4 Construction Set





Name: Address: Description: Date: Emil Weilbacher Building Rehabilitation 1829 North New Braunfels Ave., San Antonio, Texas View looking NNW toward southeast corner of building October 7, 2016 (Prior to Rehabilitation)

Photograph No.



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking NNW toward southeast corner of buildingDate:October 7, 2016 (Prior to Rehabilitation)





Name:Emil Weilbacher Building RehabilitationPhotograph No.Address:1829 North New Braunfels Ave., San Antonio, TexasBescription:View looking west across New Braunfels Ave. at east facadeDate:October 7, 2016 (Prior to Rehabilitation)GVHL-03



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking southwest at northeast corner of buildingDate:October 7, 2016 (Prior to Rehabilitation)





Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:View looking south across Carson St. at north facade of buildingDate:October 7, 2016 (Prior to Rehabilitation)

Photograph No.



Name:Emil Weilbacher Building RehabilitationAddress:1829 North New Braunfels Ave., San Antonio, TexasDescription:Detail view of south face of blade sign on east facadeDate:October 7, 2016 (Prior to Rehabilitation)



ELEVATION GENERAL NOTES:

- 1. SCRAPE, SAND AND REMOVE RUST, DIRT AND PAINT BUILD UP FROM ALL EXISTING SCUPPERS, DOWNSPOUTS AND MISCELLANEOUS METAL FASTENERS AND STRUCTURAL SUPPORTS SCHEDULED FOR REUSE. TYPICAL - ALL LOCATIONS AND MATERIALS
- 2. PRIME ALL SCUPPERS, DOWNSPOUTS AND MISCELLANEOUS METAL COMPONENTS WITH RUST INHIBITING PRIMER, PREP AND PRIME FOR PAINTING AS RECOMMENDED BY PAINT MANUFACTURER.

THE BUILT-UP ROOF OVER THE EXISTING BUILDING IS NEW. PROTECT IT DURING THE INSTALLATION OF NEW MECHANICAL EQUIPMENT

> CLEAN, REPAIR, AND REPOINT HISTORIC CAST STONE & BRICK MASONRY.

REPAIR LEADER HEADS AND DOWNSPOUTS AS REQUIRED, PAINT- TYP.

NEW ALUMINUM STOREFRONT SYSTEM AT TRANSOMS


NEW FLASHING AND COUNTER FLASHING AT TRANSOM SILL. REPAIR OR REPLACE ALL DETERIORATED WOOD TRIM AND STRUCTURAL COMPONENTS BETWEEN STOREFRONT WINDOWS AND TRANSTOMS (TYP.).


NEW ALUMINUM STOREFRONT SYSTEM, FRONT GLAZED WITH DARK BRONZE ANODIZED FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE ANODIZED FINISH, TYP.


> CLEAN, REPLACE, AND REPAIR EXISTING TILE BULKHEADS, TYP.

REPLACE MISSING SILL TILES WITH SIMILAR










BEYOND.	
TING CLEAN & PROTECT HISTORIC STONE INSCRIPTION.	
REPAIR AND REASSEMBLE FRESNEL PANELS IN NEW FRAMES TO BE INSTALLED ON THE EXTERIOR OF THE NEW ALUMINUM STOREFRONT TRANSOMS.	ARC
EXTERIOR CANOPY TO BE SIMILAR TO 1901 N. NEW BRAUNFELS CANOPY ACROSS THE STREET. REUSE SALVAGED ORIGINAL CANOPY COMPONENTS WHEN POSSIBLE. PREP & PAINT ALL EXPOSED ANCHOR ELEMENTS & RODS.	G
	STRUC
8'-8" NEW LIGHT FIXTURE TO BE INSTALLED - TYPICAL	106
NEW WOOD TRIM ABOVE STORE FRONT SYSTEM, PAINTED, TYP.	MEP Er
EXTERIOR ALUMINUM STOREFRONT DOORS TO PROVIDE ADA CONFIGURATION AT NORTHEAST CORNER ENTRANCE.	
01 FLOOR PLAN 0"	EI BI
CLEAN, REPLACE, AND REPAIR EXISTING TILE BULKHEADS, TYP.	R
	182 SA
	No. 1 2 3 6
EXISTING VENTS IN CLAY TILE WALL TO BE CLOSED & SEALED WITH PAINTED REAR MOUNTED METAL PLATE -TYP.	
 PAINTED METAL CANOPY AT DOOR OVERHANG TO MATCH MAIN CANOPY WITH GUTTER OR DIVERTER 	
LIGHT FIXTURE RE: ELECTRICAL DRAWINGS - TYPICAL	
NEW TRADITIONAL STANDING SEAM METAL ROOF WITH GALVANIZED FINISH INSTALLATION UNDER SEPARATE CONTRACT BY OTHERS.	PI E
NEW GALVANIZED GUTTER AND DOWNSPOUT BY OTHERS.	EI
ADDITION PLATE HT. 11'-5 3/4"	
3 PART STUCCO ON GALVANIZED METAL LATH	
WITH ELASTOMERIC COATING	
LIGHT FIXTURE RE: ELECTRICAL DRAWINGS - TYPICAL	
0" NEW STEEL FLUSH PANEL DOOR AND FRAME, PAINTED, WITH GLAZED TRANSOM ABOVE.	Pro Dat Dra
*	Che

TEL (210) 227-2724 CIVIL ENGINEER: SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808 STRUCTURAL ENGINEER: Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203 San Antonio, Texas 78230
TEL (210) 227-3647 MEP ENGINEER: CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841
EMIL WEILBACHER BUILDING BUILDING BUILDING HABILITATION 1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208 No. Date Description 1 08-22-2017 95% Construction Set 2 05-01-2018 Draft Permit Set 3 11-13-2018 Permit Set 6 08-13-2019 Addendum 4 Construction Set
PROPOSED EXTERIOR ELEVATIONS
Project number 1622 Date 11/13/2018
Date 11/13/2018 Drawn by Checked by A3.01 Scale 1/4" = 1'-0"



	NEW WINDOW SYSTEM AND FRAMING, TYPICAL	
	MAINTENANCE AND REPAIRS TO EXISTING ROOF, IN SEPARATE CONTRACT.	Seventh Generation
	CLEAN, REPAIR, AND REPOINT HISTORIC CAST STONE AND BRICK MASONRY, TYP.	DESIGN
	REPAIR LEADER HEADS TOP OF PARAPET AND DOWNSPOUTS, AS 18'-6"	118 Broadway, Suite 519 San Antonio, Texas 78205 TEL (210) 262-6161 TEL (210) 241-7490 OWNER:
	NEW ALUMINUM STOREFRONT SYSTEM AT TRANSOMS BEHIND FRESNEL PANEL, FRONT GLAZED WITH DARK BRONZE FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE FINISH TO MATCH STOREFRONT WINDOWS BELOW.	Government Hill Square Properties, LP. 209 East Riverside Drive Austin, Texas 78704 TEL (210) 227-2724
	NEW FLASHING AND COUNTER FLASHING AT TRANSOM SILL. REPAIR OR REPLACE ALL DETERIORATED WOOD TRIM AND STRUCTURAL COMPONENTS BETWEEN STOREFRONT WINDOWS AND TRANSTOMS	CIVIL ENGINEER: SA Engineering Co. 12703 Spectrum Drive, Suite 101 San Antonio, Texas 78249 TEL (210) 561-0808
	(TYP.). 	STRUCTURAL ENGINEER: Alpha Consulting Engineers 10609 W. Interstate Highway 10, Suite 203
	NEW ALUMINUM STOREFRONT WINDOW SYSTEM, FRONT GLAZED WITH DARK BRONZE FINISH AND ADDED EXTRUDED ALUMINUM PROFILED TRIM WITH DARK BRONZE FINISH.	San Antonio, Texas 78230 TEL (210) 227-3647 MEP ENGINEER:
	CLEAN AND REPAIR EXISTING TILE BULKHEADS, TYP.	CNG Engineering, PLLC 1917 N. New Braunfels Ave. Suite 201 San Antonio, Texas 78208 TEL (210) 224-8841
	01 FLOOR PLAN 0"	EMIL WEILBACHER BUILDING
		REHABILITATION
		1829 N. NEW BRAUNFELS ST. SAN ANTONIO, TX 78208
		No.DateDescription108-22-201795% Construction Set205-01-2018Draft Permit Set311-13-2018Permit Set608-13-2019Addendum 4 Construction Set
	V.I.F. LOCATION OF EXISTING TRAFFIC POLE IN NEW CANOPY	
	EXTERIOR CANOPY TO BE SIMILAR TO 1901 N. NEW BRAUNFELS CANOPY ACROSS THE STREET. REUSED SALVAGED ORIGINAL CANOPY COMPONENTS WHEN POSSIBLE. PREP & PAINT ALL EXPOSED ANCHOR ELEMENTS & RODS.	
	ADDITION PLATE HT. 11'-5 3/4"	PROPOSED EXTERIOR
		ELEVATIONS
	CLEAN, REPAIR, AND REPOINT HISTORIC BRICK AND STRUCTURAL CLAY TILE MASONRY WALLS (TYPICAL).	
		STERED ARCHITECT
<u>A</u>	<u>01 FLOOR PLAN</u> 0"	SA 74665 45
		Swff 11/1. Jarpent 11/13/2018
*		Project number1622Date11/13/2018Drawn by
		Checked by A3.02
		Scale 1/4" = 1'-0"









