HISTORIC AND DESIGN REVIEW COMMISSION March 17, 2021

HDRC CASE NO: 2021-061

ADDRESS: 1940 W MULBERRY AVE **LEGAL DESCRIPTION:** NCB 1951 BLK 19 RED 16

ZONING: R-6, H CITY COUNCIL DIST.: 7

DISTRICT: Monticello Park Historic District

APPLICANT: Tatiana Shear/ROOF FIX

OWNER: John Shear/SHEAR JOHN H & ROSEMARY L

TYPE OF WORK: Re-roof, shingle to metal **APPLICATION RECEIVED:** February 01, 2021

60-DAY REVIEW: Not applicable due to City Council Emergency Orders

CASE MANAGER: Huy Pham

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to replace the existing composition shingle roof with a standing seam metal roof.

APPLICABLE CITATIONS:

- 2. Guidelines for Exterior Maintenance and Alterations
- 3. Materials: Roofs
- A. MAINTENANCE (PRESERVATION)
- i. Regular maintenance and cleaning—Avoid the build-up of accumulated dirt and retained moisture. This can lead to the growth of moss and other vegetation, which can lead to roof damage. Check roof surface for breaks or holes and flashing for open seams and repair as needed.
- B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)
- i. *Roof replacement*—Consider roof replacement when more than 25-30 percent of the roof area is damaged or 25-30 percent of the roof tiles (slate, clay tile, or cement) or shingles are missing or damaged.
- ii. Roof form—Preserve the original shape, line, pitch, and overhang of historic roofs when replacement is necessary. iii. Roof features—Preserve and repair distinctive roof features such as cornices, parapets, dormers, open eaves with exposed rafters and decorative or plain rafter tails, flared eaves or decorative purlins, and brackets with shaped ends. iv. Materials: sloped roofs—Replace roofing materials in-kind whenever possible when the roof must be replaced. Retain and re-use historic materials when large-scale replacement of roof materials other than asphalt shingles is required (e.g., slate or clay tiles). Salvaged materials should be re-used on roof forms that are most visible from the public right-of-way.
- Match new roofing materials to the original materials in terms of their scale, color, texture, profile, and style, or select materials consistent with the building style, when in-kind replacement is not possible.
- v. *Materials: flat roofs*—Allow use of contemporary roofing materials on flat or gently sloping roofs not visible from the public right-of-way.
- vi. *Materials: metal roofs*—Use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Refer to Checklist for Metal Roofs on page 10 for desired metal roof specifications when considering a new metal roof. New metal roofs that adhere to these guidelines can be approved administratively as long as documentation can be provided that shows that the home has historically had a metal roof. vii. *Roof vents*—Maintain existing historic roof vents. When deteriorated beyond repair, replace roof vents in-kind or with one similar in design and material to those historically used when in-kind replacement is not possible.

FINDINGS:

- a. The primary historic structure at 1940 W Mulberry was constructed circa 1925 in the Craftsman style, first appears on the 1951 Sanborn map, and contributes to the Monticello Park Historic District.
- b. HISTORIC CONTEXT OF METAL ROOFS Site-formed metal and metal panels were a widely used roofing material in San Antonio in the late 19th century following the arrival of the railroad. Desired for its low maintenance and durability, it was often applied directly over cedar shake or other existing roofing materials. It continued to be a common roofing material for homes through the early part of the 20th century until factory-produced asphalt shingle products became widely available. By the 1920's, asphalt shingles were a popular roofing material due to its fire resistance, ability to be customized in regard to color and shape, and relatively low

- costs of manufacturing and transportation.
- c. ROOFING The applicant has proposed to replace the existing composition shingle roof with a standing seam metal roof. The structure features a combustible shake shingle roof on the 1951 Sanborn map. Per the Guidelines for Exterior Alterations and Maintenance 3.B.vi. use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Staff finds that standing seam metal roofs are within the period of significance per finding b and an appropriate material upgrade for Craftsman style houses throughout San Antonio, not excluding Monticello Park which features a number of metal roofs on similar style structures.

RECOMMENDATION:


Staff recommends approval based on finding b and c with the stipulation that the installation features the standard specifications for metal roofs:


- Panels that are 18 to 21 inches in width, and <u>smooth with no striation or corrugation.</u>
- Seams are 1 to 2 inches in height
- Ridges are to feature a double-munch or crimped ridge configuration; <u>no vented ridge caps or end caps are</u> allowed.
- Roof color will feature a standard galvalume finish or match the existing historic roof.

1940 W Mulberry



March 9, 2021




















ProQuest® Digital Sanborn Maps, 1867–1970

San Antonio 1911-Mar. 1951 vol. 5, 1924-June 1950, Sheet 503



NON-COMMERCIAL USE ONLY

Digital Sanborn Maps are not suitable for legal or regulatory purposes. Digital Sanborn Maps may not be downloaded, clipped, printed, resold, retained or used for commercial or business research purposes, including but not limited to environmental, property or other land use evaluations. Digital Sanborn Maps are reproduced and distributed under license from Environmental Data Resources, Inc. For information on how to obtain maps for commercial and business research purposes, go to www.edrnet.com/sanborn.

All copyright in the Sanborn Maps are held by Environmental Data Resources, Inc. or its affiliates. Sanborn Map

Company logo used with permission.

Database and software copyright © 2001–2021 ProQuest, LLC. All rights reserved.