# HISTORIC AND DESIGN REVIEW COMMISSION

October 21, 2015 Agenda Item No: 29

HDRC CASE NO:	2015-422
ADDRESS:	247 E KINGS HWY
LEGAL DESCRIPTION:	NCB 6327 BLK 2 LOT 41, E 3 FT OF 40 & W 2 FT OF 42
ZONING:	R5 H
CITY COUNCIL DIST.:	1
DISTRICT:	Monte Vista Historic District
<b>APPLICANT:</b>	Macario Rosas/VR Construction
OWNER:	Mike Hollaway/Mike Hollaway Custom Homes
TYPE OF WORK:	Amend COA to Account for Tree Preservation and New Driveway

### **REQUEST:**

The applicant is requesting to amend a Certificate of Appropriateness issued on June 18th, 2014, to change the location and width of the driveway, approach and sidewalk.

# **APPLICABLE CITATIONS:**

Historic Design Guidelines, Chapter 5, Guidelines for Site Elements

3. Landscape Design

#### A. PLANTINGS

i. Historic Gardens- Maintain front yard gardens when appropriate within a specific historic district.

ii. *Historic Lawns*—Do not fully remove and replace traditional lawn areas with impervious hardscape. Limit the removal of lawn areas to mulched planting beds or pervious hardscapes in locations where they would historically be found, such as along fences, walkways, or drives. Low-growing plantings should be used in historic lawn areas; invasive or large-scale species should be avoided. Historic lawn areas should never be reduced by more than 50%.

iii. *Native xeric plant materials*—Select native and/or xeric plants that thrive in local conditions and reduce watering usage. See UDC Appendix E: San Antonio Recommended Plant List—All Suited to Xeriscape Planting Methods, for a list of appropriate materials and planting methods. Select plant materials with a similar character, growth habit, and light requirements as those being replaced.

iv. *Plant palettes*—If a varied plant palette is used, incorporate species of taller heights, such informal elements should be restrained to small areas of the front yard or to the rear or side yard so as not to obstruct views of or otherwise distract from the historic structure.

v. *Maintenance*—Maintain existing landscape features. Do not introduce landscape elements that will obscure the historic structure or are located as to retain moisture on walls or foundations (e.g., dense foundation plantings or vines) or as to cause damage.

5. Sidewalks, Walkways, Driveways, and Curbing

#### **B. DRIVEWAYS**

- i. *Driveway configuration*—Retain and repair in place historic driveway configurations, such as ribbon drives. Incorporate a similar driveway configuration—materials, width, and design—to that historically found on the site. Historic driveways are typically no wider than 10 feet. Pervious paving surfaces may be considered where replacement is necessary to increase stormwater infiltration.
- ii. *Curb cuts and ramps*—Maintain the width and configuration of original curb cuts when replacing historic driveways. Avoid introducing new curb cuts where not historically found.

# **FINDINGS:**

- a. The HDRC granted approval of new construction at 247 E Kings Highway at the June 18, 2014, meeting. The approval includes a 10' driveway with a 12' curb cut along the west edge of the lot.
- b. The City Arborist has recommended that a tree in the right of way, in the location of the approved apron, should be preserved and not removed.
- c. In order to preserve the tree, the applicant has proposed to move the drive way and apron to the center of the lot and increase the width to 18' feet. The drive and approach would be in front of the main structure, which is not typical in Monte Vista. The Guidelines for Site Elements 5, B, i. state that historic driveways should be no wider than 10 feet. The proposed width for the driveway and approach are not consistent with the guidelines. Staff recommends that the driveway be no wider than 10 feet and the curb cut no wider than 12 feet
- d. The revised site plan proposed an increase to the amount of hardscaping in the front yard of the property. The Guidelines for Site Elements 3, A, ii., state that historic lawn areas should never be reduced by more than 50%. The proposed hardscaping is not consistent with the guidelines.

# **RECOMMENDATION:**

Staff does not recommend approval based on findings a through d. Staff recommends that the applicant develop a site plan that includes a linear driveway no wider than 10 feet with a curb cut no wider than 12 feet. A curved option may be appropriate to avoid the significant tree.

# **CASE MANAGER:**

Katie Totman





The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





















# 2009 IRC AND IECC GENERAL NOTES: II IS THE RESPONSIBILITY OF THE BULDERY CONTRACTOR TO HEET ALL 1869 IRC AND ECC. All STRICTURAL AND FRAMMS NEEDS TO HEET SO THAY UND CONTRAL AS HER SEC, RUOI ) AND FRAME RUOD (AL ALL TREATED BLOODS IOLDAN'S GLAB FORMATION SLL AND BLEEPERS TO HEET SEC RUTI IRC. Regular reactor will pred locator braced will preds shall be located in Accordance with part locator braced will preds shall be located in Accordance with part regular ( ), braced will preds the located in to pred the form of the one shall be pertited no more time to be the form SPICE WORLDWIGHT WORLD ATTC AC UNT-PROVIDE OVERFLOW PAR MAR PER MAIL/1000 IRC/

ENGINEERING GENERAL NOTES:

LISTINGE-CITIES CEPTOREVAL INVITES RAMDARE AD ADMONTHS IC & A PREVIOUX LILLON GENERIN IN INE SLAE OF EXAS IS KOT AND ADMONTHS IC & A PREVIOUX LILLON GENERIN IN INE SLAE OF EXAS RELEARL RIPHA HONE DISCLAG CATADUATION ALLEGEN PREVIOUX BOARTS SALOD DE COMMICTO DISCLAG CATADUATION ALLEGEN PREVIOUX BOARTS SALOTATION ALLEGIANTS DISCLAGA DISCLAGA DE RECATO SALUERAL BANDONICON RECOLUES DISCLAGA DISCLAGA DE SALORA CATADUATIONES REALIZIONICON RECOLUES DISCLAGA DISCLAGA DE SALORA CATADUATIONES DISCLAGA CATADUATIONES DISCLAGA DISCLAGA DE SALORA CATADUATIONES DISCLAGA CATADUATIONES DISCLAGA DIS WAY, MAITER OR FORM IF ANY PROBLEMS HAY ARKE.

#### COPYRIGHT 2013 ALL RIGHTS RESERVED

EXCLUSIVE PROPERTY OF F.S. ALMENDARIZ & ASSOCIATES, THESE PLANS ARE NOT TO BE USED IN UNCLE OR IN PART UTROUT DESIGNERS NATTEN PERMISSION

CONTRACTOR'S NOTES

LORONG DRAINES SHALL NOT BE SCALEDN BEFORE PROCEEDING IP DAT URK (RESENG NIESALS) NE CONJUCTOR ADDR BIL CONJUCTOR SHALL VEST AL I HEAREPOINS ON REE CONTACTOR SHALD REPORT ANT DECREPANCES AND/OR CARESCHIS FROM THE LORDNO DRAINES OR DESCRIPTIONES AND/CR OPERIGNES TROTT HE LORSEN, DAUMAG DR SPECTURIONE, FRONCING HE DRUGE & DA BERTHAN BEI SOLL JA OCE HITT HE ESSERTER SE FROLEL AN OFFITTI INFOLOMILL & BEI SUB ORANIZA (SPECIFICAL MET SE REPORTER RAN ORA, HENDELS DRUGE AND DRUMPER AND ALTER AND HE DESCRIPT ON DRUGE AND DRUMPER AND ALTER AND HE DESCRIPT ON DRUGE AND HENDELS HUNDER AND DRUMPER AND HE THE PERIOR HENDELS HUNDELS DRUGER AND DRUMPER AND HE THE DRUGE AND DRUMPER AND HENDELS IN THE HENDELS OF SUB DRUMPER AND REAL HENDELS IN THE HENDELS OF SUB DRUMPER AND REAL HENDELS IN THE HENDELS OF SUB DRUMPER AND REAL HENDELS IN THE HENDELS

	GENERAL NOTES:
l BULDE	R TO HEET ALL LRC. CODES.
2 ALLON	FOR 6" PLIMB WALL WC SIDE WHERE NECESSARY
a Allou	FOR DUAL, AC'S N ATTIC AS REQUIRED.
4 HNHL	10°-0° FLATE HEIGHT # MAN LEVEL # 9'-0° FLATE HEIGHT
+ UPPE	r level unless otherijse koted
5. LEE RO	unded sheetrook corners throughout house.
6 BLOOK	I UNE FOR CELING FANS # ALL BEDROOMS
1 ALLON	urng for security system
a verfy	PLACEMENT OF FULLDOIR STARS + JOB SITE
n verefy	PLACEMENT OF SHORE DETECTORS SHOWN ON PLANS.
io. Vento	KYTER THRU WULL
L ALLOU A	or 3 gravity roof vents allay from front
R. ALLOUP	OR COME & FLATFORME FOR WHIN GARAGE
A VERFY	FLACEHENTS OF AIC PACE SHOLK ON PLAN
ALL BE	Ordon Pluks to be arc fault circuit interrupters.
6. VERIFY	CROIN MOLLONG THPOLISHOUT HOUSE
6. ALLOU	URING FOR SPEAKERS # DINING, KITCHEN, LIBRARY,
WSTER BA	EDROCH, MASTER BATH, GREAT ROCH, STUDIO & PATIO

