### HISTORIC AND DESIGN REVIEW COMMISSION

July 06, 2016 Agenda Item No: 3

HDRC CASE NO: ADDRESS: LEGAL DESCRIPTION: ZONING: CITY COUNCIL DIST.: DISTRICT: APPLICANT: OWNER: TYPE OF WORK: 2016-232 1407 S ST MARYS NCB 2912 BLK 1 LOT 12 AND 13 C3NA H 1 King William Historic District Ryan Reed/French & Michigan Annette Rodriguez/The Children's Shelter Exterior modifications and landscaping

#### **REQUEST:**

The applicant is requesting a Certificate of Appropriateness for approval to perform exterior modifications to the structure at 1407 S St Mary's including the installation of a new storefront system, the addition of a steel canopy, landscaping and the introduction of a green wall. Neither signage nor a mural is part of this request.

#### **APPLICABLE CITATIONS:**

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

#### 10. Commercial Facades

*i. New features*—Do not introduce new facade elements that alter or destroy the historic building character, such as adding inappropriate materials; altering the size or shape of windows, doors, bulkheads, and transom openings; or altering the façade from commercial to residential. Alterations should not disrupt the rhythm of the commercial block. *ii. Historical commercial facades*—Return non-historic facades to the original design based on photographic evidence. Keep in mind that some non-original facades may have gained historic importance and should be retained. When evidence is not available, ensure the scale, design, materials, color, and texture is compatible with the historic building. Consider the features of the design holistically so as to not include elements from multiple buildings and styles.

#### FINDINGS:

- a. The structure at 1407 S St Mary's is a 1960's commercial structure featuring a façade consisting of stone veneer with little minor penetrations. The applicant has proposed to modify the east facing façade by incorporating a storefront window system and a new green wall to feature climbing vegetation. According to the Guidelines for Exterior Maintenance and Alterations, new façade elements that alter or destroy the historic character of a structure should not be introduced. Staff performed a site visit on June 22, 2016, and found that the applicant's proposed materials would not negatively impact the structure nor negatively impact the existing streetscape.
- b. The applicant has proposed to install four 6' x 5' aluminum storefront windows, a trellis constructed of 3" round steel with a corrugated steel roof, four (4) corten planters will replace two parking spaces between the front (east) façade and the public right of way and 3" x 4" steel angles and hog wire mesh to provide a climbing surface for the proposed green wall ivy. Given the existing materials in use on this structure and its location on S St Mary's in close proximity with other structures with various metal materials featured on their façade, staff finds this request appropriate. Staff finds that the applicant's proposed green wall is an appropriate solution to improving the existing façade which lacks openings and depth providing features.

#### **RECOMMENDATION:**

Staff recommends approval as submitted based on findings a and b.

#### CASE MANAGER:

Edward Hall





## **Flex Viewer**

Powered by ArcGIS Server

Printed:Jun 20, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.

San Antonio Mennonite Fellowship

Las Tapatias De Jalisco

Ø.

3.9

Marpley

W Cerolina

Q

SSt Mary's St

Imsco

10.00

1407 S St Mary's St

8310

S St Mary's St

Vale Law Firm

( Subway

MED

Mission St

Mario's Automotive Services

AAA Freight Salvage Sales



# FRENCH & MICHIGAN

#### Edward Hall

Office of Historic Preservation, City of San Antonio edward.hall@sanantonio.gov

Hi Ed,

Attached is our final proposal for The Children's Shelter Thrift Boutique located at 1407 S. St. Mary's Street. Included in the proposal are our new elevations, hand renderings, and photographs showing the existing building, and several example of similar building modifications along S. St. Mary's in the King William district.


We presented these items to the King William Association on Tuesday, May 31, 2016, and they approved the design without and changes.


If you have any questions, please call me at 210.660.8822 or email me at ryan@frenchandmichigan.com.

Thank you,


kJ







Front Elevation states and the



Right Side Elevation saturate

A000 STU MIE CARANY MARKIN TARE I SET MIE 2012 AND 20

Proposed Facade

