

HISTORIC AND DESIGN REVIEW COMMISSION

February 01, 2017

Agenda Item No: 24

HDRC CASE NO: 2017-020
ADDRESS: 115 W ASHBY PLACE
LEGAL DESCRIPTION: NCB 1885 BLK LOT 6
ZONING: RM-4, H
CITY COUNCIL DIST.: 1
DISTRICT: Monte Vista Historic District
APPLICANT: Tom Stolhandske
OWNER: Ada Yrizarry
TYPE OF WORK: Rear fence alterations
REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to place wrought iron spikes 20 inches above the top of the fence. The space between the spikes to be 6”.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 5, Guidelines for Site Elements

2. Fences and Walls

A. HISTORIC FENCES AND WALLS

- i. *Preserve*—Retain historic fences and walls.
- ii. *Repair and replacement*—Replace only deteriorated sections that are beyond repair. Match replacement materials (including mortar) to the color, texture, size, profile, and finish of the original.
- iii. *Application of paint and cementitious coatings*—Do not paint historic masonry walls or cover them with stone facing or stucco or other cementitious coatings.

B. NEW FENCES AND WALLS

- i. *Design*—New fences and walls should appear similar to those used historically within the district in terms of their scale, transparency, and character. Design of fence should respond to the design and materials of the house or main structure.
- ii. *Location*—Avoid installing a fence or wall in a location where one did not historically exist, particularly within the front yard. The appropriateness of a front yard fence or wall is dependent on conditions within a specific historic district. New front yard fences or wall should not be introduced within historic districts that have not historically had them.
- iii. *Height*—Limit the height of new fences and walls within the front yard to a maximum of four feet. The appropriateness of a front yard fence is dependent on conditions within a specific historic district. New front yard fences should not be introduced within historic districts that have not historically had them. If a taller fence or wall existed historically, additional height may be considered. The height of a new retaining wall should not exceed the height of the slope it retains.
- iv. *Prohibited materials*—Do not use exposed concrete masonry units (CMU), Keystone or similar interlocking retaining wall systems, concrete block, vinyl fencing, or chain link fencing.
- v. *Appropriate materials*—Construct new fences or walls of materials similar to fence materials historically used in the district. Select materials that are similar in scale, texture, color, and form as those historically used in the district, and that are compatible with the main structure. Screening incompatible uses—Review alternative fence heights and materials for appropriateness where residential properties are adjacent to commercial or other potentially incompatible uses.

C. PRIVACY FENCES AND WALLS

- i. *Relationship to front facade*—Set privacy fences back from the front façade of the building, rather than aligning them with the front façade of the structure to reduce their visual prominence.
- ii. *Location*—Do not use privacy fences in front yards.

FINDINGS:

- a. The main structure is a two-story Neoclassical home w, built circa 1909. It is a contributing structure in the Monte Vista Historic District, and was designated in 1975.
- b. There is an existing 6’ wrought iron rear fence. There are also 3 strands of barbed wire above the portion of the

fence that spans the rear property line, that did not receive a Certificate of Appropriateness. The proposed modification to the existing fence includes removing the barbed wire and adding 20" spikes above the existing 6' fence. The spikes are designed 6" apart. According to the Guidelines for Site Elements 2.B., new fences should appear similar to those used historically within the district in terms of scale, character, and height. Staff finds the design of the proposed spikes is not characteristic of the spires installed currently. Staff also finds that a fence that is 7'-8" is not historically found in the district

RECOMMENDATION:


Staff does not recommend approval based on findings a and b.

CASE MANAGER:

Lauren Sage

CASE COMMENTS:

- March 3, 2013 – Development Services Department (DSD) received a complaint of razor wire on the property. DSD allowed the razor due to the fact that it has been in place for over 20 years. If the property owner in the future wants to remodel or alter the existing fence, a new permit would be required.
- March 4, 2014 – DSD received another complaint of the razor wire. Further research indicated that razor wire is not allowed by code, but barbed wire is allowed by Sec. 6-2. DSD directed the property owner to convert the existing razor wire to barbed wire.
- August 18, 2014 – A citation was issued because the property owner refused to remove the razor wire and install barbed wire. A court date was set for October 28, 2014, at which the property owner did not show, and was liable, by default.
- November 11, 2014 – A variance application was submitted for the razor wire, and was denied.
- November 20, 2014 – Another citation was issued because the property owner refused to remove the razor wire and install barbed wire.
- January 7, 2015 – The citation was dismissed because the property owner agreed to remove the razor wire and install barbed wire. She had 60 days to do so.
- January 23, 2015 – A letter from DSD to the applicant references the agreement made of January 7, 2015. The letter also states that code allows barbed wire, not razor wire.
- March 25, 2015 – A citation was issued because though some razor wire was replaced with barbed wire, some razor wire remained.
- May 1, 2015 – All razor wire was removed and replaced with 3 strands of barbed wire.
- June 3, 2015 – A request was heard by the HDRC to install three strands of barbed wire at 6" apart on top of an existing wrought iron fence along the back property line. Staff did not recommend approval. The commission moved to deny the request.
- The barbed wire was not removed and the 3 strands of barbed wire persist today.
- The final construction height of an approved fence may not exceed the maximum height as approved by the HDRC at any portion of the fence. Additionally, all fences must be permitted and meet the development standards outlined in UDC Section 35-514. The applicant will need to seek a variance from the Board of Adjustment for the additional fence height.
- Any property designated historic requires a Certificate of Appropriateness from the Office of Historic Preservation prior to performing any exterior modifications.




Flex Viewer

Powered by ArcGIS Server

Printed: Jan 24, 2017

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.



An aerial photograph of a residential neighborhood. Several houses with different colored roofs (red, orange, blue, grey) are visible, interspersed with green trees. A road runs along the bottom of the frame. A small brown icon of a house with a checkmark is positioned to the right of the text.

Dr. Yrizarry's Bed
and Breakfast

An aerial photograph of a residential street. In the center is a large, two-story house with a grey roof and a white porch. To its right is a smaller, single-story building with a grey roof. The street is visible at the bottom, with a car parked on the left. The text "Dr. Ylizarry's Bed and Breakfast" is overlaid on the image, with a line pointing to the smaller building.

Dr. Ylizarry's Bed
and Breakfast



W French Pl

W French Pl

W French Pl

Casseb Clothing

N Main Ave

N Main Ave

Dr. Yrizarry's Bed
and Breakfast

Kym's Kids

115 West Ashby Place

W Ashby Pl

W Ashby Pl

W Ashby Pl

Fiesta On Main /
Alamo Fiesta.COM.

W Ashby Pl



CITY OF SAN ANTONIO
HISTORIC PRESERVATION

170315





ADA C. YRIZARRY

DENTIST

FRONT LEFT



VIEW OF BACK OF 115 W ASHBY



Oct 21, 2016, 10:43:59 AM

VIEW OF BACK OF 115 W ASHBY



Oct 21, 2016, 10:44:12 AM

EXISTING CONDITIONS - REAR FENCE

Nov 30, 2016, 4:10:11 PM

EXISTING CONDITIONS - REAR FENCE



Nov 30, 2016, 4:10:14 PM

EXISTING CONDITIONS - REAR FENCE



EXISTING CONDITIONS - REAR FENCE





2017 JAN -4 AM 11:40

Tom Stolhandske
1004 S. St. Mary's
San Antonio, Texas 78205
Email: tomstolhandske@gmail.com
stolhandskelawmessages@gmail.com

Telephone: (210) 798-1453
Facsimile: (888) 461-3796

January 3, 2017

City of San Antonio
Development Services Department
1901 S. Alamo Street
P.O. Box 839966
San Antonio, Texas 78204

Gentlemen:

In submitting the application to the Historic Design and Review Commission/City of San Antonio Office of Historic Preservation, for Lot 6, NCB 1885 (115 W. Ashby Place) for Dr. Ada Yrizarry, Dr. Yrizarry is not relinquishing the right to have 3-strand barb wire as granted by document dated January 23, 2015. This document was accepted by Dr. Yrizarry and the work was performed and completed according to the terms set out.

This letter is to protect my client's right that the document of January 23, 2015 created and established a contract and that the performance by my client according to the terms of your document have been fulfilled by Dr. Yrizarry.

If the plan submitted with the application to place stakes instead of barb wire is approved, the Applicant will abide by the terms of the new agreement.

Very truly yours,



Tom Stolhandske

TS/cja

2017 JAN -4 AM 11:40

P L A N

- ▶ Will remove barbed wire - see Picture "A"
- ▶ Will place spikes 6" apart on top of existing fence
- ▶ Spikes to be 18" - 20" tall - as per bid attached
- ▶ Time of replacement - to be started upon acceptance or approval of this request. A spike sample has been furnished.

PROPOSED

Juan S. Diaz
210-394-6809

INVOICE NO. 1041

Invoice

INVOICE DATE 11-17-'16

CUSTOMER ORDER NUMBER

SOLD TO: Dr. Ada Yrizarry
115 West Ashby Place
San Antonio, Tx 78212

SHIP TO:

SALESPERSON

SHIPPED VIA

TERMS

F.O.B.

QTY ORDERED

QTY SHIPPED


DESCRIPTION

UNIT

AMOUNT

20 whom may concern :

\$ 1,200.00



Proposal:

Remove existing barbed wire,
replaced as shown in outline
included.

Thank you,
Juan Diaz

\$ 1,200.00



PROPOSED SPIKES

Nov 28, 2016, 3:57:29 PM


A-1

Rear of 115 W Ashby Pl.



Exhibit C-1

RAZOR WIRE FENCE - NOT PERMITTED
REMOVED IN 2015



REMOVED wire AS agreed with City
Wire in back of house.

Before


Exhibit D-1

Drive to back of House.
With gate -



Exhibit C-2

EXISTING CONDITIONS



VIEW OF back fence - See Exhibit C-1
After removal and addition of Barb Wire.
Wire 3 strands - 6" apart - meets Standard
requirements
NOT ALLOWED to take picture from other side.

Exhibit C-3

REAR ACCESSORY STRUCTURE




Front view of Bread & Breakfast
See Exhibit C-2 - Fence in question
directly behind Bread & Breakfast

Exhibit D-3

LEFT SIDE of 115 W Ashby Pl
(NOWIRE) REMOVED.



PROPOSED LOCATION OF SPIKES



7

CITY CLERK

R.I.N. 95 # 09277