

Photos
Subject Property – 10327 Cone Hill Drive



Carport meets side setback



Overhang extends in the right-of-way



Streetscape



Similar carports within neighborhood

