HISTORIC AND DESIGN REVIEW COMMISSION September 19, 2018

HDRC CASE NO: ADDRESS: LEGAL DESCRIPTION: ZONING: CITY COUNCIL DIST.: DISTRICT: APPLICANT: OWNER: TYPE OF WORK: APPLICATION RECEIVED: 60-DAY REVIEW:

2018-449 613 MISSION ST NCB 2914 BLK 3 LOT 15 RM-4, H 1 King William Historic District Nick & Leigh Anne Lester Nick & Leigh Anne Lester Installation of front yard fencing August 28, 2018 October 27, 2018

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to install front yard fencing at 613 Mission.

APPLICABLE CITATIONS:

5. Guidelines for Site Elements

2. Fences and Walls

B. NEW FENCES AND WALLS

i. *Design*—New fences and walls should appear similar to those used historically within the district in terms of their scale, transparency, and character. Design of fence should respond to the design and materials of the house or main structure. ii. *Location*—Avoid installing a fence or wall in a location where one did not historically exist, particularly within the front yard. The appropriateness of a front yard fence or wall is dependent on conditions within a specific historic district. New front yard fences or wall should not be introduced within historic districts that have not historically had them. iii. *Height*—Limit the height of new fences and walls within the front yard to a maximum of four feet. The appropriateness of a front yard fence is dependent on conditions within a specific historic district. New front yard fence or wall existed historically had them. If a taller fence or wall existed historically, additional height may be considered. The height of a new retaining wall should not exceed the height of the slope it retains.

iv. *Prohibited materials*—Do not use exposed concrete masonry units (CMU), Keystone or similar interlocking retaining wall systems, concrete block, vinyl fencing, or chain link *fencing*.

v. *Appropriate materials*—Construct new fences or walls of materials similar to fence materials historically used in the district. Select materials that are similar in scale, texture, color, and form as those historically used in the district, and that are compatible with the main structure. Screening incompatible uses—Review alternative fence heights and materials for appropriateness where residential properties are adjacent to commercial or other potentially incompatible uses.

C. PRIVACY FENCES AND WALLS

i. *Relationship to front facade*—Set privacy fences back from the front façade of the building, rather than aligning them with the front façade of the structure to reduce their visual prominence.

ii. Location - Do not use privacy fences in front yards.

FINDINGS:

- a. The primary structure at 613 Mission was constructed circa 1910 in the Craftsman style and is contributing to the King William Historic District. The one-story single-family structure features a crossed-gable primary roof with a gable-covered front porch. The front yard features natural lawn flanked by a ribbon driveway leading to a wood privacy fence behind the front façade plane of the structure. The structure first appears on the 1919 Sanborn Map.
- **b.** FENCE LOCATION The applicant has proposed to install a fence to wrap around the front yard, including a gate spanning across the driveway. According to the Guidelines for Site Elements 2.B.ii, new front yard fences should not be introduced within historic districts that did not historically have them. While staff finds that a fence is not currently present on this property, fences are found on Mission and within the King William Historic

District. According to the Guidelines for Site Elements 2.C.i., privacy fences should be set back from the front façade to reduce their visual prominence. Staff finds that the fence should turn at the driveway to meet the corner of the structure, rather than spanning across the driveway as proposed. Staff finds that the driveway gate, if included, should be set back behind the front façade plane of the structure.

- c. FENCE DESIGN The applicant has proposed the new fence to feature metal-framed cattle panel at three (3) feet in height. According to the Guidelines for Site Elements 2.B.i., the design of the fence should respond to the design and materials of the primary historic structure or structures of a similar style in the neighborhood in relation to scale, transparency, and character. Staff finds that a traditional wood-framed cattle panel fence is found on a Craftsman duplex at 604 Mission while wrought iron and wood picket fences are more common to the Craftsman style, Mission St, and the King William Historic District. Staff finds that the applicant should explore wrought iron and wood picket options first, then consider the wood-framed cattle panel fence. The applicant has referenced the property at 223 Delaware located in the Lavaca Historic District as a reference to the proposed metal-framed cattle panel fence. Staff finds that the referenced fence was installed without approval in 2012 and does not relate to the King William Historic District.
- **d.** FENCE HEIGHT Per the Guidelines 2.B.iii, the height of new fences and walls within the front yard should be limited to a maximum of four feet. Staff finds that the proposed three foot tall fence is consistent with the Guidelines.

RECOMMENDATION:

Staff recommends approval of front yard fencing with the following stipulations:


- i. The fence should turn at the driveway to meet at the corner of the structure, as opposed to spanning across the driveway in the front.
- ii. The driveway gate should be located behind the front façade plane of the structure or removed from the design.
- iii. The fence should feature a traditional design including wrought iron, wood picket, or a wood-framed cattle panel as opposed the proposed metal-framed cattle panel.
- iv. That no portion of the fence exceed four feet in height.

CASE COMMENT:

The final construction height of an approved fence may not exceed the maximum height as approved by the HDRC at any portion of the fence. Additionally, all fences must be permitted and meet the development standards outlined in UDC Section 35-514.

CASE MANAGER:

Huy Pham






613 Mission

Powered by ArcGIS Server

Printed:Sep 12, 2018

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.





611 Mission St San Antonio, Texas

🦻 Google, Inc.


🕲 + Street View - Mar 2016

9:





Copyrigh San Antonio Board of Rea





FENCE @ 613 MISSION ST. GALVANIZED STEEL 3 FT HIGHT WITH GATE AND CAR GATE



