

City Of San Antonio
Bid Tabulation

NON-LOCAL

NON-LOCAL

LOCAL

Opened: July 8, 2019					
Annual Contract For Police Motorcycles Parts and Services					
6100011562					
AAS					
Item	Description	Estimated Annual Quantity			
1A	HONDA MOTORCYCLE PARTS A. Percent of discount offered OR Cost Plus Mark Up B. Product Identification (Manufacturer) C. Type of price schedule (dealer, jobber, etc.) D. Price Schedule Number E. Date of Price Schedule F. Price schedule column on which discount is based (i.e., distributor, net, wholesale, etc.) G. Warranty				
2	HONDA GOLD WING MOTORCYCLE SPECIFIED ITEMS:				
2.1	Brake Pad Sets 06435-MCA-016 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	20 EACH	No Bid	10% Honda Retail N/A June 1, 2019 Retail 6 Months	0% Honda Dealer No response 90 Days
2.2	Pad Sets 06455-MCA-016 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	20 EACH	No Bid	Honda Pad Set 06435-MCA-026 10% \$54.45 \$49.01 \$980.20	Honda 0% \$49.98 \$49.98 \$999.60
2.3	Disk Brakes 43250-MCA-013 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid	Honda Pad Set 06455-MCA-016 10% \$53.69 \$48.33 \$966.60	Honda 0% \$49.98 \$49.98 \$999.60
2.4	Valve Stems 292299 (Tucker Rocky) Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 PACKAGE (pack of 6)	No Bid	Honda Brake Disc 43250-MCA-013 10% \$621.35 \$559.22 \$2,796.10	Honda 0% \$621.36 \$621.35 \$3,106.75
2.5	Headlight Bulbs 34901-MAT-611 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	10 EACH	No Bid	Tucker Rocky Valve Stems 292306 10% \$52.80 \$47.52 \$47.52	Honda 0% \$9.29 \$9.29 \$55.74
2.6	Sensors 39411-MCA-R32 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid	Honda Headlight Bulbs 34901-MAT-611 10% \$22.96 \$20.67 \$206.70	Honda 0% \$22.96 \$22.96 \$229.60
2.7	Switch Assembly 35200-MCA-S81 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid	Honda Sensors 39411-MCA-R32 10% \$173.89 \$156.51 \$782.55	Honda 0% \$173.89 \$173.89 \$869.45
				Honda Switch Assembly 35200-MCA-S81 10% \$571.73 \$514.56 \$2,572.80	Honda 0% \$571.73 \$571.73 \$2,858.65

Opened: July 8, 2019 Annual Contract For Police Motorcycles Parts and Services 6100011562			AAS		Overseas Parts Distributing Inc., dba Alamo BMW 25600 IH -10W Boerne, TX 78006 210-289-8692	Kent Powersports, LP 15664 IH35 N Selma, TX 78154 210-655-2625	Alamo Cycle Plex 11900 IH-10 West San Antonio TX 78230
Item	Description	Estimated Annual Quantity					
2.8	Grommet Set 417410 (Tucker Rocky) Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	3 EACH	No Bid		Showchrome Grommet Set 417410 10% \$5.96 \$5.36 \$16.08	Showchrome \$17.85	
2.9	Rubber Maid Step 50661-MCA-305 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid		Honda Rubber, Maid Step 50661-MCA-305 10% \$12.04 \$10.84 \$54.20	Honda \$60.20	
2.10	Seals, Windshield 64121-MCA-000 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid		Honda Seals, Windshield 64121-MCA-000 10% \$28.53 \$25.68 \$128.40	Honda \$142.65	
2.11	Seal Set 51490-MCA-A61 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid		Honda Seal Set 51490-MCA-A61 10% \$28.02 \$25.22 \$126.10	Honda \$140.10	
2.12	Fluid 08208-0010 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	5 EACH	No Bid		Honda Fluid 08208-0010 10% \$6.40 \$5.76 \$28.80	Honda \$39.80	
3	PERIODIC MAINTENANCE COST PER SERVICE TYPE-						
3.1	Category I - Maintenance Schedule Price Each Price Total	25 EACH	No Bid		\$253.06 \$6,326.50	\$272.81 \$6,820.25	
3.2	Category II - Maintenance Schedule Price Each Price Total	20 EACH	No Bid		\$379.39 \$7,587.80	\$662.62 \$13,252.40	
3.3	Category III - Maintenance Schedule Price Each Price Total	20 EACH	No Bid		\$546.32 \$10,926.40	\$967.84 \$19,356.80	
3.4	Category IV - Maintenance Schedule Price Each Price Total	5 EACH	No Bid		\$669.78 \$3,348.90	\$1380.06 \$6,900.30	
3.5	New Front Tire (Removal-Install-Balance) Price Each Price Total	20 EACH	No Bid		\$294.30 \$5,886.00	\$363.65 \$7,273.00	
3.6	New Rear Tire (Removal-Install-Balance) Price Each Price Total	35 EACH	No Bid		\$337.88 \$11,825.80	\$457.45 \$16,010.75	
3.7	Battery Replacement (Inclusive of all fees) Price Each Price Total	10 EACH	No Bid		\$158.74 \$1,587.40	\$231.45 \$2,314.50	

Opened: July 8, 2019 Annual Contract For Police Motorcycles Parts and Services 6100011562			AAS		
Item	Description	Estimated Annual Quantity	Overseas Parts Distributing Inc., dba Alamo BMW 25600 IH -10W Boerne, TX 78006 210-289-8692	Kent Powersports, LP 15664 IH35 N Selma, TX 78154 210-655-2625	Alamo Cycle Plex 11900 IH-10 West San Antonio TX 78230
3.8	Labor Rate For Repair Service	120	No Bid		
	Price Each	HOURS		\$107.55	\$129.00
	Price Total			\$12,906.00	\$15,480.00
3.9	Initial Oil Change at 800 Miles	3	No Bid	No Bid	No Bid
	Price Each	EACH		\$0.00	\$0.00
	Price Total			\$0.00	\$0.00
	Warranty For Labor		No	3 Months	90 Days
	Warranty For Specified Parts			3 Months	90 Days
	Honda Certified Service Provider Delivery			Honda Certified 7 Days	Honda Certified 7 Days
4	BMW R1250RTs MOTORCYCLE PARTS A. Percent of discount offered OR Cost Plus Mark Up B. Product Identification (Manufacturer) C. Type of price schedule (dealer, jobber, etc.) D. Price Schedule Number E. Date of Price Schedule F. Price schedule column on which discount is based (i.e., distributor, net, wholesale, etc.) G. Warranty		30% BMW / Michelin Manufacturer N/A 7/5/2019 Dealer Cost 2 Years	No Bid	No Bid
5	BMW R1250RTs MOTORCYCLE SPECIFIED ITEMS				
5.1	Brake Pads Front (Sets) 34 18 405 104 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	2 SETS	BMW Brake Pads Front (Sets) 3418405104 Cost Plus 30% \$54.27 \$70.55 \$141.10	No Bid	No Bid
5.2	Brake Pads Rear (Sets) 34 18 562 163 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 SETS	BMW Brake Pads Sintered Metal 3418562163 Cost Plus 30% \$61.39 \$79.81 \$79.81	No Bid	No Bid
5.3	Disk Brakes front with rivet, 34 118 526 566 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	2 EACH	BMW Brake Rotor w Rivet 34 11 8 526 566 Cost Plus 30% \$238.10 \$309.53 \$619.06	No Bid	No Bid
5.4	Rubber Valve Stems– Incorporated in TPM Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 PACKAGE (pack of 6)	BMW Included in Item 5.6 \$0.00 \$-	No Bid	No Bid
5.5	Headlight Bulbs 63 217 160 780; BMW Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 EACH	BMW Bulb 63 217 160 780 Cost Plus 30% \$6.46 \$8.40 \$8.40	No Bid	No Bid
5.6	TPM Sensors with valve stem; 36 318 532 731 BMW Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 EACH	BMW Sensor with valve 36 318 532 731 Cost Plus 30% \$127.75 \$166.08 \$166.08	No Bid	No Bid

Opened: July 8, 2019 Annual Contract For Police Motorcycles Parts and Services 6100011562			AAS		Overseas Parts Distributing Inc., dba Alamo BMW 25600 IH -10W Boerne, TX 78006 210-289-8692	Kent Powersports, LP 15664 IH35 N Selma, TX 78154 210-655-2625	Alamo Cycle Plex 11900 IH-10 West San Antonio TX 78230
Item	Description	Estimated Annual Quantity					
5.7	Turn Signal Switch Assembly (Left Multifunction Switch); 61 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 EACH	BMW Combination Switch Left (Lin Bus) 61 Cost Plus 30% \$263.52 \$342.58 \$342.58				
5.8	Rubber Foot Peg; 46 718 544 486 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 EACH	BMW Footrest Rubber 46 718 544 486 Cost Plus 30% \$18.85 \$24.51 \$24.51				
5.9	Front Fork Seal Set; one per fork, 31 42 8 532 723 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	1 SET	BMW Set if Sealing Elements 31 42 8 532 723 Cost Plus 30% \$31.09 \$40.42 \$40.42				
5.10	Fork Oil 10W, 31-42 9062 158 Manufacturer Name Part Name & No. Discount % Offered or Cost Plus Price Each Price Each with Discount Price Total	2 EACH	BMW Telescopic Fork Oil Type 1 31-42 9062 Cost Plus 30% \$14.27 \$18.55 \$37.10				
6	PERIODIC MAINTENANCE COST PER SERVICE TYPE-						
6.1	Category I - Maintenance Schedule Price Each Price Total	5 EACH	\$340.23 \$1,701.15				
6.2	Category II - Maintenance Schedule Price Each Price Total	5 EACH	\$554.37 \$2,771.85				
6.3	Category III - Maintenance Schedule Price Each Price Total	5 EACH	\$230.34 \$1,151.70				
6.4	Category IV - Maintenance Schedule Price Each Price Total	5 EACH	\$578.00 \$2,890.00				
6.5	Category V - Maintenance Schedule Price Each Price Total	5 EACH	\$230.34 \$1,151.70				
6.6	Category VI - Maintenance Schedule Price Each Price Total	5 EACH	\$675.12 \$3,375.60				
6.7	New Front Tire (Removal-Install-Balance) Price Each Price Total	10 EACH	\$258.70 \$2,587.00				
6.8	New Rear Tire (Removal-Install-Balance) Price Each Price Total	15 EACH	\$318.05 \$4,770.75				
6.9	Battery Replacement (Inclusive of all fees) Price Each Price Total	5 EACH	\$188.72 \$943.60				

Opened: July 8, 2019 Annual Contract For Police Motorcycles Parts and Services 6100011562			AAS		
Item	Description	Estimated Annual Quantity	Overseas Parts Distributing Inc., dba Alamo BMW 25600 IH -10W Boerne, TX 78006 210-289-8692	Kent Powersports, LP 15664 IH35 N Selma, TX 78154 210-655-2625	Alamo Cycle Plex 11900 IH-10 West San Antonio TX 78230
7.0	Labor Rate For Repair Service	60			
	Price Each	HOURS	\$115.00	No Bid	No Bid
	Price Total		\$6,900.00		
7.1	Initial Oil Change at 600 Miles	5			
	Price Each	EACH	\$230.34	No Bid	No Bid
	Price Total		\$1,151.70		
	Warranty For Labor		2 Years		
	Warranty For Specified Parts		2 Years		
	Certified Service Provider			No	No
	Deliveries made within 7 days after receipt of order		BMW Certified 7 Days		
	Payment Terms		2%, Net 15	Net 30	Net 30
	Delivery		7 days if parts available		
	Business hours are from		Tuesday -Saturday 8:30 am to 6 pm	Tuesday -Saturday 9 am to 7 pm	Tuesday -Saturday 8 am to 5 pm
	Weekends		Tuesday -Saturday 8:30 am to 6 pm		
	Percentage between lowest responsible bid and local bidder			-28.71%	
	Price Differential			\$27,827.14	
	Estimated Annual Total:		\$30,854.11	\$69,100.85	\$96,927.99
	Estimated Annual Award:		\$30,854.11	\$69,100.85	