HISTORIC AND DESIGN REVIEW COMMISSION

October 07, 2020

HDRC CASE NO: 2020-427

ADDRESS: 333 SADIE ST

LEGAL DESCRIPTION: NCB 729 BLK 3 LOT S 98.9 FT OF 9 ARB 9B

ZONING: R-6, H CITY COUNCIL DIST.:

DISTRICT: Lavaca Historic District **TYPE OF WORK:** Historic Tax Certification **APPLICATION RECEIVED:** September 24, 2020

60-DAY REVIEW: Not applicable due to City Council Emergency Orders

CASE MANAGER: Rachel Rettaliata

REQUEST:

The applicant is requesting Historic Tax Certification for the property at 333 Sadie.

APPLICABLE CITATIONS:

UDC Section 35-618. Tax Exemption Qualification.

(d)Certification.

(1)Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's documentation for recommendation of either approval or disapproval of the application for exemption.

FINDINGS:

- a. The primary structure at 333 Sadie was constructed in the is a 2-story structure constructed circa 1910. The property first appears on the Sanborn Map in 1912 as a commercial structure. The structure features a flat roof, composition siding, one-over-one windows, and an entryway oriented to the corner of Sadie and Labor Streets. The property features a rear accessory structure that is not original to the property and does not appear on the Sanborn Map until 1951. The rear accessory structure features a flat roof, stucco cladding, and two wood-framed windows facing Labor street. The property is contributing to the Lavaca Historic District. The applicant is requesting Historic Tax Certification.
- b. The scope of work includes a comprehensive interior remodel, installation of new plumbing, new electrical, new HVAC, new sheetrock, new flooring, a kitchen, bathroom, and bedroom remodel, stairway renovation, exterior siding restoration and painting, door repair and replacement, rear accessory structure restoration, landscaping and hardscaping, and foundation repair.
- c. The applicant has met all the requirements for Historic Tax Certification outlined in UDC Section 35-618 and has provided evidence to that effect to the Historic Preservation Officer.


RECOMMENDATION:

Staff recommends approval based on findings a through c.


City of San Antonio One Stop




City of San Antonio GIS Copyright 8-7-2020




Imagery ©2020 Google, Map data ©2020 , Map data ©2020 20 ft




Imagery ©2020 Google, Map data ©2020 , Map data ©2020 20 ft 🗀




Imagery ©2020 Landsat / Copernicus, Google, Map data ©2020 , Map data ©2020



Imagery ©2020 Google, Data SIO, NOAA, U.S. Navy, NGA, GEBCO, Data LDEO-Columbia, NSF, NOAA, Landsat / Copernicus, Map data ©2020 , Map data ©2020 20 ft ∟




Imagery ©2020 Google, Map data ©2020 , Map data ©2020 20 ft L




Original located at the Dolph Briscoe Center for American History, University of Texas at Austin

333 Sadie - Sanborn Maps

1931, v.3, p. 257 – separate building for auto repair at rear of main store.



1938, v.3, p. 257 – shows a separate dry cleaners' at the rear of main store. Unclear whether auto repair







333 Sadie



333 Sadie Street

Lorem ipsum dolor sit amet

Plans for 333 Sadie Street:

- 1. Remove cement siding and restore wood siding on exterior. Caulk and repaint exterior
- 2. Repair and paint exterior wood window frames and repair glass in windows
 - 3. Repair doors or replace with like kind wood doors.
 - 4. Repair or replace flat metal roof
- 5. Restore wood siding to back property that will be converted into a 2 car garage
- 6. Add a small 3' wrought iron fence around the front on the property.
 - 7. Add some landscaping in front of store front windows
 - 8. Add a privacy fence between the main property and garage
 - 9. Add driveway to new car garage
 - 10. Repair or replace foundation

11.	Back	upper	balcony	y is just	olywood	d, that will	removed	and
resto	red							

Projected time schedule:

3 Months

Itemized work to make a multifamily property into a single family residence.

- 1. New plumbing
- 2. New Electric
- 3. New HVAC
- 4. New sheetrock, mud tape flow and paint
- 5. Redo stairway
- 6. New flooring
- 7. New kitchen, bathrooms and bedrooms

Estimated cost: