HISTORIC AND DESIGN REVIEW COMMISSION

July 07, 2021

HDRC CASE NO: 2021-306

ADDRESS: 202 MARY LOUISE LEGAL DESCRIPTION: NCB 6699 BLK 8 LOT 21

ZONING: R-6, H CITY COUNCIL DIST.: 7

DISTRICT: Monticello Park Historic District
APPLICANT: Benjamin and Jennifer Rosas
OWNER: Benjamin and Jennifer Rosas
TYPE OF WORK: Historic Tax Certification

APPLICATION RECEIVED: June 23, 2021

60-DAY REVIEW: Not applicable due to City Council Emergency Orders

CASE MANAGER: Rachel Rettaliata

REQUEST:

The applicant is requesting Historic Tax Certification for the property at 202 Mary Louise.

APPLICABLE CITATIONS:

UDC Section 35-618. Tax Exemption Qualification.

(d)Certification.

(1)Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's documentation for recommendation of either approval or disapproval of the application for exemption.


FINDINGS:

- a. The primary structure located at 202 Mary Louise is a 2-story, single-family residence constructed circa 1926 in the Spanish Eclectic style. The home features a red clay tile hip roof and a flat roof, stucco cladding, prominent front and rear chimneys, divided lite windows, arched transoms over the front façade windows, and a decorative front door surround. The property is contributing to the Monticello Park Historic District. The applicant is requesting Historic Tax Certification.
- b. The scope of work includes a comprehensive interior remodel, roof repair and replacement, landscaping modifications, fence repair, window and door repair, and upgrades to the existing plumbing, electrical, and mechanical systems. Certificates of Appropriateness are required for all exterior scopes of work.
- c. The applicant has met all the requirements for Historic Tax Certification outlined in UDC Section 35-618 and has provided evidence to that effect to the Historic Preservation Officer.

RECOMMENDATION:


Staff recommends approval based on findings a through c.


City of San Antonio One Stop




June 23, 2021

User drawn lines







Imagery ©2021 Google, Map data ©2021 , Map data ©2021 Google 20 ft L




Imagery ©2021 Google, Map data ©2021 , Map data ©2021 Google 20 ft L



Imagery ©2021 Google, Map data ©2021 , Map data ©2021 Google 20 ft 🗀



Imagery ©2021 Google, Map data ©2021 , Map data ©2021 Google 20 ft □



Imagery ©2021 Google, Map data ©2021 , Map data ©2021 Google 20 ft

202 Mary Louise Dr. | San Antonio, TX





HISTORIC REHABILITATION APPLICATION PART 1 JUNE 2021

EXISTING FLOOR PLAN

OVERVIEW

We are so excited to own this piece of San Antonio's History! My wife and I are overjoyed to have the opportunity to raise our family in this historic gem of a house.

My wife is an educator in the inner city and I am an architect working in downtown San Antonio. Our kids attend SAISD schools. We are deeply rooted in this community and have a deep appreciation and affinity for historic structures.

We believe in the power of restoration, both in structures and in people. The original deed of this house was written such that my wife and I would not be allowed to buy the house due to the color of our skin and family origin. However, we are now proud to reclaim the opportunity of ownership and to restore the piece of this homes narrative that was about love and family. We believe that every building has a story and this home is no exception.

The story of home began in 1926 when it was built for the DeLesdernier Family and featured, at the time, fine italian stone craftsmenship both inside and out. Some of these features are still intact today around the front door. Over years, the original high quality interior character has been muddied and in many ways lost by insensitive intervetions and low quality replacement of original high quality materials and craftsmanship.

Our goal is to restore the pieces of this homes character that are currently hidden under layers of poorly crafted additions. We want to reintroduce the warmth and quality of craftsmanship that once defined this prominent home. Our intention is not to overpower the histroric aspects of this house, rather compliment them with contemporary functional improvements that will last for generations to come.


We're thinking ahead. We want this to be a home that our family will grow old in and are investing in it as such. We know that the value of the improvements we are putting into the structure may not yield a return for many, many years. We are not planning to sell this home. We are building a legacy and an example for others to follow.

We want our kids to love being here. We hope to create many menories in this house with family and friends. We hope that those that enter this home will feel warmth and love - no matter where they come from or what the color of their skin is. We hope that they will see that, with care and attention, what was once old and broken can be made new again.

EXCERPT FROM ORIGNAL DEED

North Woodlewn Terrace, said lots fronting on the south side of Club Drive, eccording to plat of record in Vol.642, page 189, of the Plat Records of said County. To have and to hold the above described premises, together with all and singular the rights and appurtenances thereto in anywise belonging unto the said w.F. Delesdernier and wife, alice Delesdernier, their heire and assigns, forever subject to the following conditions and restrictions, the observance of which is a part of the consideration for said property, and which the purchaser agrees for themselves, their heirs and essigns, shell be covenants running with the land; 1. That neither they nor their heirs, executors, administrators or assigns, shell sail or lease any partion of said property to any person of negro blood, nor to any Mexican. 2. That said property shell be used for private residence purposes only, except as hereinafter set out; That no residence





NEW FLOOR PLAN

IMPROVEMENT LIST

EXTERIOR REHABILITATION

- Repair Stucco finish throughout and repaint with same white color
- Reseal Windows and Doors
- Rehabilitate Leaking Windows: Carpenter to rebuild in same historic likeness and wood construction methodology
- Repair and Restore existing Clay tile roofing
- Repair existing leaking modified bitumen roofing membrane
- Reseal flat roof joints and seams
- Repair historic iron fencing
- Landscape front yard with drought tolerant vegitation

INTERIOR REPAIR, RENOVATIONS, AND IMPROVEMENTS

Architectural:

- Repair and Restore and historic wood flooring: sand, seal, replace broken/rotting/missing boards
- Remove period inappropriate interventions and replace with contemporary complimentary interventions: remove fiberglass columns and arches and replace with simple archways. Remove dark stained particle board kitchen cabinetry and replace with solid wood kitchen cabinetry and countertops.
- Update/Renovate Main Bathroom layout, tile, electrical, and plumbing fixtures
- Paint and finish throughout

Electrical:

- Repair and update electrical system and fixtures throughout Plumbing:
- Repair and update broken plumbing fixtures throughout
- Replace leaking/corroded piping with PEX piping HVAC:
- Repair/replace old HVAC condenser and furnace

For a full breakdown of improvements and costs, see budget breakdown at the end of the document.

EXISTING KITCHEN











NEW KITCHEN PERSPECTIVE RENDERING




NEW KITCHEN PERSPECTIVE RENDERING




NEW KITCHEN PLANS




EXISTING MAIN BATHROOM






NEW MAIN BATHROOM PLANS (IN PROGRESS)








EXISTING ARCHES AND ROOF LEAK WATER DAMAGE



NEW ARCHES RENDERING



EXISTING WINDOWS TO BE RESTORED












EXISTING STUCCO TO BE RESTORED





EXISTING ROOFING TO BE RESTORED AND REPAIRED









PROJECT BUDGET AND SCHEDULE

202 Mary Louise Project Budget					
Scope	Material Unit Cost	Install Cost	Quantity		Unit
Permanent Plumbing Fixtures					
Master Bathtub				1	ea.
Master Shower Fixture Package				2	ea.
Master Tub fixtures				1	ea.
Master Toilet				1	ea.
Master Sink+Vanity				2	ea.
Master Mirrors					ea.
Total	_				
Plumbing System Updates					
Refrigerator Water				1	
Master Vanity relocation					
Master Toilet drain relocation				1	
Tub supply and drain				1	
Install shower at Casita					
Gas Line replacement at Stove				1	
-	-				
Total					
Kitchen Updates					Linear Foot
Lower Cabinets					Linear Feet
Tall Cabinet				5	
Upper Cabinets					Linear Feet
Counter tops					Square Feet
Beams				7	
Backsplash					Square Feet
Faucet					ea.
Sink					ea.
Disposal				1	ea.
Total					
Roof Repair and Restoration					
Rebuild tile roof				240	Square Feet
Repair/Replace Mod. Bit.				2000	Square Feet
Replace missing/damaged clay tile					
Trim/flashing at garage					
Repair downspouts					
Total					
Exterior Repair and Restoration					
Window Repair/Glass Replacement				2	ea.
New windows (back of house)				5	ea.
Stucco Patch/Repair				200	Square Feet
Rotted Framing Replacement				3	
Trim/Detail/Vent Repair					
Total					
Paint/Finish					
Interior Paint				1000	Square Feet
Exterior Paint					Square Feet
Total	-				
Electrical Repairs and Fixtures					
Bedroom Lights				1	ea.
Master Bedroom Light					ea.
Master bathroom sconces					ea.
Master Shower and Toilet					ea.
Master Closet					ea.
Laundry					ea.
Kitchen (can lights)					ea.
Kitchen Pendant lights					ea.
Pantry (can lights)					ea.
Dining Dining					ea.
Dining Sconce Lights					ea.
Living				2	ea.

Studio	
Garage	e light
Garage	Door Opener
Bathro	om Vanity Lights
Bathro	om Lights
	e Room Light
	r Flood Lights
Total	
HVAC	Updates
	ondenser and Furnace
Total	ondenser and i umace
TOLAI	
Door E	Postoration
	Restoration Exterior Deere
	Exterior Doors
	e patio doors
	y Camera + Keypad Lock
Total	
	eplacement
Pre-se	aled Saltillo 12x12
Thinse	t Mortar
Grout	
Tile ba	cker
Master	Bath Floor
Master	Bath Heated Floor
	Bath Shower Walls
Master	Bath Glass Doors
Total	Bath Glass Doors Floor Restoration
Total Wood Repair	Floor Restoration +Refinish
Total Wood Repair Stair tre	Floor Restoration +Refinish eads
Total Wood Repair Stair tre	Floor Restoration +Refinish eads
Wood Repair Stair tre Landin entry fo	Floor Restoration +Refinish eads 9
Wood Repair Stair tr Landin entry fo	Floor Restoration +Refinish eads g yyer and back foyer
Wood Repair Stair tre Landin entry for	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs
Wood Repair Stair tre Landin entry for	Floor Restoration +Refinish eads g yyer and back foyer
Wood Repair Stair tr Landin entry fo Tile De Total	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs
Wood Repair Stair to Landin entry fo Tile De Total Drywa Master Living/I	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs
Wood Repair Stair to Landin entry fo Tile De Total Drywa Master Living/I	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings
Wood Repair Stair to Landin entry fo Tile De Total Drywa Master Living/I	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings
Wood Repair Stair to Landin entry fo Tile De Total Drywa Master Living/I Total	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings
Wood Repair Stair tr Landin entry fo Tile De Total Drywa Master Living/I Total	Floor Restoration +Refinish eads g over and back foyer molition and Original Floor Repairs II and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings
Wood Repair Stair tr Landin entry fo Tile De Total Drywa Master Living/I Total	Floor Restoration +Refinish eads g byer and back foyer molition and Original Floor Repairs II and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings
Total Wood Repair: Stair trr Landin entry fo Tile De Total Drywa Master Living/I Total Repair	Floor Restoration +Refinish eads g byer and back foyer molition and Original Floor Repairs II and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings
Total Wood Repair Stair tr Landin Landin Entry for Total Drywa Master Living/I Total Repair Total	Floor Restoration +Refinish eads g byer and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings Epair and Restoration Fencing
Total Wood Repair Stair tr Landin Landin Entry for Total Drywa Master Living/I Total Iron Re Repair Total	Floor Restoration +Refinish eads g byer and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings Epair and Restoration Fencing
Wood Repair Stair tr Landin entry fc Total Drywa Master Living/I Total Iron Re Repair Total Lands Front L	Floor Restoration +Refinish eads g byer and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings epair and Restoration Fencing
Wood Repair Stair tr Landin entry fc Total Drywa Master Living/I Total Iron Re Repair Total Lands Front L	Floor Restoration +Refinish eads g pyer and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings epair and Restoration Fencing cape andscaping
Wood Repair to Landin entry fo Title De Total Drywa Master Living/I Total Iron R Repair Total Lands Front L Back L	Floor Restoration +Refinish eads g pyer and back foyer molition and Original Floor Repairs Il and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings epair and Restoration Fencing cape andscaping
Wood Repair to Landin entry fo Title De Total Drywa Master Living/I Total Iron R Repair Total Lands Front L Back L	Floor Restoration +Refinish eads g over and back fover molition and Original Floor Repairs Ill and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings epair and Restoration Fencing cape endscaping andscaping andscaping
Wood Repair Stair tn Landin entry fc Tile De Total Drywa Master Living/I Total Iron Re Repair Total Lands: Front L Back L Total Sub To	Floor Restoration +Refinish eads g over and back fover molition and Original Floor Repairs Ill and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings epair and Restoration Fencing cape endscaping andscaping andscaping
Wood Repair Stair tn Landin entry fc Tile De Total Drywa Master Living/I Total Iron Re Repair Total Lands: Front L Back L Total Sub To	Floor Restoration +Refinish eads g over and back fover molition and Original Floor Repairs Ill and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings Papair and Restoration Fencing cape andscaping andscaping tal ctor Fees 20%
Total Wood Repair Stair tn Landin entry fc Tile De Total Drywa Master Living/I Total Iron Re Repair Total Lands: Front L Back L Total Sub To Contra	Floor Restoration +Refinish eads g over and back fover molition and Original Floor Repairs Ill and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings Papair and Restoration Fencing cape andscaping andscaping tal ctor Fees 20%
Total Wood Repair Stair tn Landin entry fc Tile De Total Drywa Master Living/I Total Iron Re Repair Total Lands: Front L Back L Total Sub To Contra Permits Clean i	Floor Restoration +Refinish eads g over and back fover molition and Original Floor Repairs Ill and Framing Restoration Suite Walls and Ceilings Kitchen/Dining Openings Papair and Restoration Fencing cape andscaping andscaping tal ctor Fees 20%

1	ea.	
2	ea.	
2	ea.	
3	ea.	
	ea.	
	ea.	
4	ea.	
1	ea.	
6	ea.	
300	Square Feet	
7	Per bag (45SF coverage)	
3	Per bag (90SF coverage, 1/2" joint)	
	Per 3x5 Panel	
	Square Feet	
	Square Feet	
	Square Feet	
	ea.	
2215	Square Feet	
17	tread count	
1		
300		
300		
	0 5 1	
	Square Feet	
6	each	
100	Linear Foot	
250	Square Feet	
250	Square reet	

SCHEDULE

Total Construction Duration 3 Months