## City of San Antonio Bid Tabulation

Opened: For:	November 8, 2013 Refuse Trucks Collision Repair Units 4152 &		Collision Country Repair
FOI.	468313		Center
6100003646	400010	LD	4282 IH 10 East
			San Antonio,
Item	Description	Quantity	TX 78219
	·	-	210-333-1881
1A	Repair vehicle Cab and repair collision damage,	1	
	2008 American LaFrance Condor, Unit Number		
	4152, Vehicle Identification Number		
	5SXHANDR98RZ69219		
	Complete Estimated Price:		\$58,216.07
	Repairs will begin withincalendar days		45/120 days
	after receipt of Purchase Order and completed		,
	within days.		
1B	Deleted		
2A	Repair Vehicle Cab and Repair Collision Damage,	1	
	2013 Freightliner with New Way Refuse Body, Unit		
	Number 468313, vehicle identification number		
	1FVHG3DV4DDBX1426.		
	Complete Estimated Price:		\$45,485.09
	Complete Estimated Fince.		\$45,465.09
	Repairs will begin withincalendar days		45/90 Days
	after receipt of Purchase Order and completed		<b>,</b>
	within days.		
2B	Deleted		
	Payment Terms		Net 30
	aymone romio		1401 00
	Total		\$103,701.16
	Total Award		\$103,701.16