

**City of San Antonio Bid Tabulation**

Opened: July 10, 2020			<b>Local</b>	<b>Local</b>	<b>Local</b>	<b>Non-Local</b>
For: Olmos Dam Drain Repair			HJD Capital Electric, Inc.	Clearfield Construction, LLC.	International Mechanical Services, Inc.	Tony Puga Construction, LLC., dba TCP Construction
6100012599			5424 Hwy 90 West San Antonio, TX 78227 210-681-0954	108 Earl Street San Antonio, TX 78212	1914 Breeden Ave. San Antonio, TX 78212	714 FM 2537 San Antonio, TX 78221
<b>Item</b>	<b>Description</b>	<b>Quantity</b>				
1	Olmos Dam Drain Repair - Repair of water supply for Restroom & Janitor Sink (Located at Olmos Dam Gate House, 1000 E. Olmos Dr.)	1				<b>NAS</b>
	Material Cost:		\$32,017.00	\$40,327.00	\$76,503.20	\$42,072.00
	Hourly Labor Rate:		\$60.67	\$311.00	\$90.29	\$31.05
	Labor Hours:		480	80	750	360
	Labor Total Price:		\$29,121.60	\$24,880.00	\$67,717.50	\$11,178.00
	Equipment Rental:		\$11,935.00	\$7,460.00	12,000.00	4,750.00
	Payment Bond:		\$1,461.46	\$4,231.00	\$1,646.00	1,740.00
	Performance Bond:		N/A	N/A	\$1,646.00	N/A
	Extended Price :		\$74,535.06	\$76,898.00	\$159,512.70	\$59,740.00
	Start of work will be within calendar days, after receipt of purchase order		10 days	14 days	20 days	7 days
	Completion of repairs will be within calendar days		30 days	10 days	70 days	21 days
	Payment Terms		Net 30	Net 30	Net 30	2%,10
	Total:		\$74,535.06	\$76,898.00	\$159,512.70	\$59,740.00
	<b>Total Award:</b>		<b>\$74,535.06</b>			