

<p align="center">RFQ: Underground Storm Drain Video Inspection Program PublicWorks03232020JEC</p> <p align="center">Score Summary INITIAL EVALUATION Wednesday, June 9, 2020</p>		<p align="center">Gonzalez De La Garza &amp; Associates, LLC Fredericksburg Rd., Ste. 200SL San Antonio, TX 78229</p>	<p align="center">RJN Group, Inc. 200 W. Front Street Wheaton, IL 60187 USA</p>	<p align="center">Watson and Watson Development 2702 URSULA Ct Mansfield, TX 76063</p>
A. Experience, Background and Qualifications, Key Personnel, Key Sub-Consultants	35	28.60	33.20	5.00
B. Understanding of the Project and Proposed Management Plan	20	17.40	19.00	1.60
C. Team's Experience with San Antonio Region Issues and Past Experience with City of San Antonio	25	21.80	24.00	2.80
E. SBEDA	20	20.00	0.00	0.00
TOTAL SCORE	100	87.80	76.20	9.40
<b>RANK BASED ON TOTAL SCORE</b>		<b>1</b>	<b>2</b>	<b>3</b>