

## City of San Antonio Bid Tabulation

Opened: For: 6100003646	November 8, 2013 Refuse Trucks Collision Repair Units 4152 & 468313	LD	Collision Country Repair Center 4282 IH 10 East San Antonio, TX 78219 210-333-1881
Item	Description	Quantity	
1A	Repair vehicle Cab and repair collision damage, 2008 American LaFrance Condor, Unit Number 4152, Vehicle Identification Number 5SXHANDR98RZ69219  Complete Estimated Price:  Repairs will begin within _____calendar days after receipt of Purchase Order and completed within _____ days.	1	\$58,216.07  45/120 days
1B	Deleted		
2A	Repair Vehicle Cab and Repair Collision Damage, 2013 Freightliner with New Way Refuse Body, Unit Number 468313, vehicle identification number 1FVHG3DV4DDBX1426.  Complete Estimated Price:  Repairs will begin within _____calendar days after receipt of Purchase Order and completed within _____ days.	1	\$45,485.09  45/90 Days
2B	Deleted		
	Payment Terms		Net 30
	Total		\$103,701.16
	<b>Total Award</b>		<b>\$103,701.16</b>