




STATE OF TEXAS
COUNTY OF BEXAR

I HEREBY CERTIFY THAT THE ABOVE PLAT CONFORMS TO THE MINIMUM STANDARDS SET
FORTH BY THE TEXAS BOARD OF PROFESSIONAL LAND SURVEYING ACCORDING TO AN
ACTUAL SURVEY MADE ON THE GROUND BY: PAPE-DAWSON ENGINEERS, INC.



REGISTERED PROFESSIONAL LAND SURVEYOR

1 1



BY: APX CHAIRMAN

CURVE	RADIUS	DELTA	CHORD BEARING	CHORD	LENGTH
C1	27.00'	31°46'22"	N45°21'57"E	14.78'	14.97'
C2	59.00'	115°40'19"	S89°41'04"E	99.89'	119.11'
C3	59.00'	118°07'50"	S39°53'45"E	101.21'	121.64'
C4	27.00'	35°30'58"	S81°12'12"E	16.47'	16.74'
C5	59.00'	111°40'45"	N25°00'32"W	12.01'	12.03'
C6	59.00'	245°28'54"	S23°46'47"E	99.25'	252.78'
C7	1853.00'	Q049°24'E	S45°17'23"W	21.48'	213.46'

