#### HISTORIC AND DESIGN REVIEW COMMISSION

September 21, 2016 Agenda Item No: 6

**HDRC CASE NO:** 2016-374

**ADDRESS:** 927 E CROCKETT ST

**LEGAL DESCRIPTION:** NCB 576 (923 CROCKETT), BLOCK 15B LOT 15

**ZONING:** RM4 H CITY COUNCIL DIST.: 2

**DISTRICT:** Dignowity Hill Historic District

APPLICANT: Susan Todd
OWNER: Susan Todd

**TYPE OF WORK:** Historic Tax Certification

**REQUEST:** 

The applicant is requesting Historic Tax Certification for the property at 927 E Crockett St.

### **APPLICABLE CITATIONS:**

UDC Section 35-618. Tax Exemption Qualifications:

- (a) Assessed Valuation. In accordance with the provisions of this article, a building, site, or structure which meets the definition of a historically significant site in need of tax relief to encourage preservation and which is substantially rehabilitated and/or restored as certified by the historic and design review commission and approved by the city tax assessor-collector, shall have an assessed value for ad valorem taxation as follows regardless of ownership during the granted time period:
- (1) A residential property shall have the assessed value for ad valorem taxation for a period of ten (10) tax years equal to the assessed value prior to preservation.
- (b) Applicability. This exemption shall begin on the first day of the first tax year after verification of completion of the preservation required for certification; provided the building shall comply with the applicable zoning regulations for its use and location.
- (c) Application. Application for a historic structure preservation tax exemption pursuant to this division is to be filed with the office of historic preservation. The historic preservation officer shall be the agent of the city for the purposes of administering this division provided that the historic preservation officer request a recommendation from the historic and design review commission. Each application shall be signed and sworn to by the owner of the property and shall:
  - (1) State the legal description of the property proposed for certification;
  - (2) Include an affidavit by the owner describing the historic significance of the structure in need of tax relief;
  - (3) Include a final complete set of plans for the historic structure's restoration or rehabilitation;
  - (4) Include a statement of costs for the restoration or rehabilitation work;
  - (5) Include a projection of the estimated construction, time and predicted completion date of the historic restoration or rehabilitation:
  - (6) Authorize the members of the historic and design review commission, the city tax assessor-collector and city officials to visit and inspect the property proposed for certification and the records and books of the owners as necessary to certify that the property in question is in substantial need of restoration or rehabilitation;
  - (7) Include a detailed statement of the proposed use for the property; and
  - (8) Provide any additional information to the historic and design review commission which the owner deems relevant or useful such as the history of the structure or access to the structure by the public.

Each application shall contain sufficient documentation confirming or supporting the information submitted therein.

- (d) Certification.
  - (1) Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's documentation for recommendation of either approval or disapproval of the application for exemption.

(2) Tax Assessor-Collector Approval. Upon receipt of the certified application for tax exemption as well as the recommendation of the historic and design review commission, the city's tax assessor-collector shall within thirty (30) days approve or disapprove eligibility of the property for tax relief pursuant to this division. In determining eligibility, the tax assessor-collector shall first determine that all the requirements of this division have been complied with and that only the historic structure and the land reasonably necessary for access and use thereof is to be provided favorable tax relief.

### (g) Eligibility.

(1) The tax exemption options outlined in subsection (f), above, will remain in effect unless terminated by designation status being removed pursuant to subsection 35-606(g) of this article.

### **FINDINGS:**

- a. The applicant is requesting Historic Tax Certification for the property located at 927 E Crockett. The scope of work consists of various items including repairs to the electrical, plumbing, HVAC, windows, doors, hardwood floors, and siding, new roof, painting exterior, insulation, dry-wall, and leveling foundation. The exterior work requests have been submitted to staff for administrative approval.
- b. The requirements for Historic Tax Certification outlined in UDC Section 35-618 have been met and the applicant has provided evidence to that effect to the Historic Preservation Officer including photographs and an itemized list of costs.
- c. Staff visited the site September 9, 2016.

### **RECOMMENDATION:**

Staff recommends approval as submitted based on findings a through c.

#### **CASE MANAGER:**

Lauren Sage





## **Flex Viewer**

**Powered by ArcGIS Server** 

Printed:Sep 14, 2016

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.



#### 927 East Crockett

This home was an vacant and ill kept property. There were few unbroken windows or functioning doors. It was literally just a shell, with partial missing floors. You can see from the photos that it was boarded up and abandoned.

The scope of work entailed refurbishing and creating a small but historic home. Everything from repairing and replacing walls and floors, adding modern appliances, including reestablishing the gas line so that the kitchen can have a gas stove.

The previous owner failed to separate the sewer and water systems from the house next door, so instead of arguing, I have paid the impact fees and am awaiting a contractor to run new water and sewer lines to this home. This correction alone is costing over \$12,000.00 to rectify.

The home is scheduled to be completed late fall of 2016.

Here is a partial list of the work to be completed:

All new appliances

All new kitchen cabinets

Repair/Replace weighted windows as necessary. Antique weights will be used to replace missing ones.

Wooden sashes repaired or rebuilt by local Dignowity artisans.

Custom made closet doors crafted by a local Dignowity carpenter

Maximize storage with a sophisticated appearance

Movable kitchen island with custom top for efficient work space, storage, and can be moved to the side to allow for entertaining

Custom made screen with reclaimed lumber

Removable exterior siding panels to allow for easy maintenance, painting, and access to under home.

Complete clean out of trash from under home

Plugs throughout with USB capability

Walls, ceilings and floors have been insulated.

Complete new HVAC system

Tankless water heater

Complete new electrical wiring, panel boxes

LED recessed lights for cooling and less expensive lighting

Exposed wood ceilings and walls where appropriate

All exterior walls sheet rocked for extra insulation and noise reduction

Original hardwood floors repaired, sand and stain

The overall cost of this project is indicated on the attached analysis.







































































# **BEXAR APPRAISAL DISTRICT**

06/30/16

**#BWNCTVY** 

**TODD SUSAN** 24165 IH 10 W # 217-419 SAN ANTONIO TX 78257

RE:

ACCOUNT NUMBER: 00576-152-0150

PID#: 1248916

LEGAL DISCRIPTION: NCB 576 (923 CROCKETT), BLOCK 15B LOT 15

PARCEL ADDRESS: CROCKETT TX - 927

Dear Property Owner:

Bexar Appraisal District is pleased to inform you that:

The property owner on the account referenced above is shown as TODD SUSAN.

If you need additional information contact the Customer Information and Assistance Department at (210) 242-2432.

Sincerely, Bexar Appraisal District

## **REPAIR COST ESTIMATE**

## 927 East Crockett St

EXT. DOORS & WINDOWS

SAT 78202

Input a brief description of the repairs required to the property.

Total Repair Estimate  GENERAL CONDITIONS					Breakdov	n by Scope	of Work		,	
			\$2,010	\$2.010 EXT. DOORS & WIN		\$6,700	HARDWOOD FLOO	RING	\$2,385	
				\$270	GARAGE DOORS		\$0	TILING		\$1,525
563,935 STRUCTURAL CONCRE			STRUCTURAL CONCRETE	\$1,050	LANDSCAPING		\$500	PAINTING		\$7,000
			CONCRETE & FLATWORK	\$800	\$800 MISC. EXT. IMPROVEN		\$540	APPLIANCES		\$900
MASONRY				\$0	\$0 FRAMING & DRYWA		\$5,110	PLUMBING		\$7,475
Breakdown by Work Type			SIDING	\$2,885	CABINETS & COU	NTERTOPS	\$5,784	HVAC		\$5,000
LAB/EQUIP MAT'L SUB			DECKING AND PATIOS	\$1,675	DOORS & TRIM		\$4,330	ELECTRICAL		\$7,451
\$19,148	\$19,437	\$25,350	ROOFING	\$350	CARPET & RESILIE	INT	\$0	MISCELLANEOUS		\$195
							Totals			
Description of Work				QTY	Unit	Lab	Mat'l	Sub	Total	Cost
GENERAL (	CONDITIONS									
Dumpster	r rental-40 yard			1	ea	\$0	\$400	\$0	\$40	00
Construct	tion Permits < \$1	Ok	¥	1	job	\$0	\$325	\$0	\$325	
Chemical	Toilet			2	то	\$0	\$170	\$0	\$1	70
Misc. Too	ols & Materials			2	ls	\$0	\$500	\$0	\$50	00
Rekey/loc	k box			2		\$90	\$100	\$0	\$19	90
Turn on u				1		\$0	\$125	\$0	\$12	
Architect	ural Fees		·		hrs	\$0	\$0	\$300	\$30	
WHICH SHEET SHEET		Park Park Mary Mary	42 1000	GENERAL CONDI	TIONS TOTAL	\$90	\$1,620	\$300	\$2,0	10
DEMOLITIC	ON									
Demolition work per hour			18	hrs	\$270	\$0	\$0	\$270		
				DEMOL	JTION TOTAL	\$270	\$0	\$0	\$2	70
14.			V = 4				MARINE SQUARES SHOP IN			
STRUCTUR	AL CONCRETE									
Ероху ста	ick injection			15	lf	\$0	\$0	\$1,050	\$1,0	150
	a con remainder to the first	MATERIAL SECTION		STRUCTURAL CON	CRETE TOTAL	\$0	\$0	\$1,050	\$1,0	50
CONCRETE	& FLATWORK									
Brick pav	ers, sand base			80	sf	\$520	\$280	\$0	\$80	00
38 1 73		8 850		CONCRETE & FLAT		\$520	\$280	\$0	\$8	00
						-		2017 1011		N 21 2186
SIDING					1 -	4	4	1 4- 1	4-	
Plywood panel, douglas fir				300	+	\$345	\$375	\$0	\$720	
Trim, 1"x				100	-	\$125	\$40	\$0	\$165	
Repair siding to match house					ls	\$0	\$0	\$2,000	\$2,0	
			The state of the s	S	SIDING TOTAL	\$470	\$415	\$2,000	\$2,8	85
DECKING A	AND PATIOS									
New deck, columns, joists, railing-treated lumber					sf	\$500	\$250	\$0	\$7:	
New deck, columns, joists, railing-cedar				20	sf	\$200	\$180	\$0	\$3	
Existing deck, replace decking				35	sf	\$175	\$70	\$0	\$24	<b>4</b> 5
Install rai	iling w/ wood ba	lusters only		10	lf .	\$150	\$150	\$0	\$3(	00
				DECKING AND F	ATIOS TOTAL	\$1,025	\$650	\$0	\$1,6	75
ROOFING										
Roof repo	air/patch, asphal	t		1	ea	\$250	\$100	\$0	\$3:	50
11				RO	OFING TOTAL	\$250	\$100	\$0	\$3.	50
	THE RESERVE OF THE PERSON NAMED IN	THE RESERVE AND DESCRIPTION OF THE PERSON NAMED IN				-	MARKET MARKET STREET	THE RESERVE THE PERSON NAMED IN	MATERIAL PLANS SHAPE MADE	

				Totals		Total Cost	
Description of Work	QTY	Unit	Lab	Mat'l	Sub		
French patio door, pair	2	ea	\$600	\$1,000	\$0	\$1,600	
Exterior door hardware w/ dead bolt	2	еа	\$50	\$50	\$0	\$100	
Repair historically accurate windows	5	0	\$0	\$0	\$5,000	\$5,000	
	EXT. DOORS & WINL	DOWS TOTAL	\$650	\$1,050	\$5,000	\$6,700	
LANDCCADINC						*****	
LANDSCAPING  Landscaping bid/allowance, trees, bushes, flowers				1 40	Aron	Arno	
tunascuping via/anowance, trees, busines, flowers		ls	\$0	\$0	\$500	\$500	
	LANDSC	APING TOTAL	<i>\$</i> 0	\$0	\$500	\$500	
MISC. EXT. IMPROVEMENTS							
New mailbox	1	ea	\$50	\$100	\$0	\$150	
Shutters	6	ea	\$150	\$240	\$0	\$390	
	MISC. EXT. IMPROVEM	IENTS TOTAL	\$200	\$340	\$0	\$540	
			117	441	-1 Y	17 70	
FRAMING & DRYWALL							
Subflooring, 3/4" plywood	250	·	\$250	\$213	\$0	\$463	
Interior wall framing	250	sf	\$250	\$438	\$0	\$688	
Wall insulation	250	sf	\$125	\$125	\$0	\$250	
Attic insulation, blown-in	700	,	\$350	\$210	\$0	\$560	
Drywall wallboard, 1/2" thick, finish one side  Drywall ceilings, 1/2" thick	500	-	\$750	\$500	\$0	\$1,250	
Drywuii teiinigs, 1/2 trick	400		\$1,600	\$300	\$0	\$1,900	
	FRAMING & DRY	WALL TOTAL	\$3,325	\$1,785	\$0	\$5,110	
CABINETS & COUNTERTOPS							
Cabinet Material bid/allowance	1	ls	\$0	\$0	\$3,500	\$3,500	
Countertop bid/allowance	1	Is	\$0	\$0	\$1,500	\$1,500	
New cabinet door pulls	12	ea	\$48	\$36	\$0	\$84	
Kitchen sink bowl, stainless steel, undermount	1	ea	\$100	\$250	\$0	\$350	
Vanity cabinet	1	ea	\$150	\$200	\$0	\$350	
	CABINETS & COUNTER	TOPS TOTAL	\$298	\$486	\$5,000	\$5,784	
DOORS & TRIM					To the latest to		
	1 2		ćane.	danc.	40	A450	
		ea	\$225 \$150	\$225 \$170	\$0 \$0	\$450 \$320	
Interior door, prehung, hallow-core door				2170	20		
Interior mirrored, sliding, closet doors	2	ea		¢165	¢n.		
Interior mirrored, sliding, closet doors Door casings	2	ea ea	\$150	\$165	\$0	\$315	
Interior mirrored, sliding, closet doors	2 3 6	ea ea	\$150 \$300	\$270	\$0	\$315 \$570	
Interior mirrored, sliding, closet doors Door casings Window casings	2 3 6 150	ea ea ea	\$150 \$300 \$263	\$270 \$150	\$0 \$0	\$315 \$570 \$413	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base	2 3 6 150 350	ea ea ea If	\$150 \$300	\$270 \$150 \$613	\$0 \$0 \$0	\$315 \$570 \$413 \$1,313	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding	2 3 6 150 350 2	ea ea lf. lf lf	\$150 \$300 \$263 \$700 \$250	\$270 \$150 \$613 \$700	\$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long	2 3 6 150 350 2	ea ea ea If	\$150 \$300 \$263 \$700	\$270 \$150 \$613	\$0 \$0 \$0	\$315 \$570 \$413 \$1,313	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long	2 3 6 150 350 2	ea ea lf. lf lf	\$150 \$300 \$263 \$700 \$250	\$270 \$150 \$613 \$700	\$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950 \$4,330	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade	2 3 6 150 350 2 DOORS &	ea ea ea lf lf lf sf TRIM TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b>	\$270 \$150 \$613 \$700	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950 \$4,330	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing	2 3 6 150 350 2 DOORS &	ea ea ea lf lf lf sf rrim TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade	2 3 6 150 350 2 DOORS &	ea ea ea lf lf lf sf rrim TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b>	\$270 \$150 \$613 \$700 <b>\$2,293</b>	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950 \$4,330	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing	2 3 6 150 350 2 DOORS &	ea ea lf lf lf sf sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings	2 3 6 150 350 2 DOORS &	ea ea lf lf lf sf sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings	2 3 6 150 350 2 DOORS &	ea ea ea lf lf lf sf sf sf lf RING TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b>	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b>	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile	2 3 6 150 350 2 DOORS &  100 550 200 HARDWOOD FLOO	ea ea ea  ff  if  if  if  sf  sf  RING TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b>	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b>	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile  Shower tile, standard	2 3 3 6 150 350 2 2 DOORS & 200 HARDWOOD FLOO	ea ea ea lf lf lf sf sf sring TOTAL  sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b>	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b>	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile	2 3 6 150 350 2 DOORS &  100 550 200 HARDWOOD FLOO  25 75 30	ea ea ea lf lf lf lf sf sf sf sf sf sf sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b> \$250 \$375 \$150	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b> \$300 \$300 \$150	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675 \$300	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile  Shower tile, standard	2 3 6 150 350 2 DOORS &  100 550 200 HARDWOOD FLOO  25 75 30	ea ea ea lf lf lf sf sf sring TOTAL  sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b>	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b>	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile  Shower tile, standard  Floor tile, bathrooms	2 3 6 150 350 2 DOORS &  100 550 200 HARDWOOD FLOO  25 75 30	ea ea ea lf lf lf lf sf sf sf sf sf sf sf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b> \$250 \$375 \$150	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b> \$300 \$300 \$150	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675 \$300	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, masaic tile  Shower tile, standard	2 3 6 150 350 2 DOORS &  100 550 200 HARDWOOD FLOO  25 75 30	ea ea ea lf lf lf lf sf sf sf sf sf lf lRING TOTAL	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b> \$250 \$375 \$150	\$270 \$150 \$613 \$700 <b>\$2,293</b> \$400 \$138 \$160 <b>\$698</b> \$300 \$300 \$150	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675 \$300	
Interior mirrored, sliding, closet doors  Door casings  Window casings  Wood base  Crown molding  Closet kit, 8ft long  HARDWOOD FLOORING  Hardwood flooring, average grade  Floor refinishing  Shoe moldings  TILING  Kitchen backsplash, mosaic tile  Shower tile, standard  Floor tile, bathrooms	2 3 3 6 150 350 2 DOORS & 2 DOORS & 2 200 HARDWOOD FLOO	ea ea ea lf lf lf lf sf	\$150 \$300 \$263 \$700 \$250 <b>\$2,038</b> \$300 \$1,238 \$150 <b>\$1,688</b> \$250 \$375 \$150 <b>\$775</b>	\$270 \$150 \$613 \$700 \$2,293 \$400 \$138 \$160 \$698 \$300 \$150 \$750	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$315 \$570 \$413 \$1,313 \$950 \$4,330 \$700 \$1,375 \$310 \$2,385 \$550 \$675 \$300 \$1,525	

Description of Work	QTY	Unit	Lab	Mat'l	Sub	Total Cost	
Range, average	1	ea	\$0	\$650	\$0	\$650	
Microwave, built-in	1	ea	\$0	\$250	\$0	\$250	
	APPLU	ANCES TOTAL	\$0	\$900	\$0	\$900	
PLUMBING							
Plumbing, bid/allowance	1	Is	\$0	\$6,500	\$0	\$6,500	
Garbage disposal	1	ea	\$50	\$100	50	\$150	
Bathroom faucet fixture	1	ea	\$75	\$125	50	\$200	
Showerhead/tub kit	1	ea	\$75	\$150	\$0	\$225	
Toilets	1	ea	\$75	\$125	\$0	\$200	
vanity sink with top	1	ea	\$200	\$0	\$0	\$200	
	PLUN	ABING TOTAL	\$475	\$7,000	\$0	\$7,475	
					an to Far		
HVAC							
HVAC, bid/allowance	1	ls	\$0	\$0	\$5,000	\$5,000	
		HVAC TOTAL	\$0	\$0	\$5,000	\$5,000	
PI POTALIA I						MIT AND A SECOND	
ELECTRICAL		1					
Electrical, bid/allowance		İs	\$0	\$0	\$5,500	\$5,500	
Track/Pendent light	1		\$0	\$100	\$50	\$150	
Chandelier light fixture	1	ea	\$0	\$150	\$50	\$200	
Ceiling dome light	1		\$0	\$35	\$25	\$60	
Ceiling fan fixture	3	ea	\$0	\$345	\$225	\$570	
Bathroom vanity light		ea	\$0	\$85	\$50	\$135	
Can lighting	4	ea	\$0	\$86	\$500	\$586	
Exterior light fixture	2	ea	\$0	\$150	\$100	\$250	
	ELECT	RICAL TOTAL	\$0	\$951	\$6,500	\$7,451	
AMPORTANION			-			-	
MISCELLANEOUS							
Bath accessories, towel bar, toilet disp, ea bathroom		ea	\$50	\$50	\$0	\$100	
Bathroom mirrors	1	ea	\$25	\$70	\$0	\$95	
	MISCELLAN	IEOUS TOTAL	\$75	\$120	\$0	\$195	
	TOTAL REPA	UR ESTIMATE	\$19,148	\$19,437	\$25,350	\$63,935	

Total towards 30%

\$46,660

Agent Code:

Mapsco:

Map ID:

## **Bexar CAD**

### Property Search Results > 105933 EVEREST & TERRA ALTA LLC for Year 2016

### **Property**

	Α	C	C	O	u	n	t
--	---	---	---	---	---	---	---

Property ID: 105933

Geographic ID: 00576-152-0110

Type: Real Property Use Code: 001

Property Use Description: Single Family

Location

Address: 923 E CROCKETT ST

SAN ANTONIO, TX 78202

Neighborhood: DIGNOWITY HILL HIST DIST

Neighborhood CD: 57069

**Owner** 

Name: EVEREST & TERRA ALTA LLC

Mailing Address: 13750 SAN PEDRO AVE STE B10

SAN ANTONIO, TX 78232-4463

LTA LLC Owner ID:

vner ID: 2895807

% Ownership: 100.000000000%

Legal Description: NCB 576 BLK 15B LOT 11

617B5

Exemptions:

### **Values**

(+) Improvement Homesite Value: + \$28,760

(+) Improvement Non-Homesite Value: + \$0

(+) Land Homesite Value: + \$41,860

(+) Land Non-Homesite Value: + \$0 Ag / Timber Use Value (+) Agricultural Market Valuation: + \$0 \$0

(+) Timber Market Valuation: + \$0 \$0

\_\_\_\_\_\_

(=) Market Value: = \$70,620

(–) Ag or Timber Use Value Reduction: – \$0

(=) Appraised Value: = \$70,620

(–) HS Cap: – \$0

(=) Assessed Value: = \$70,620

### **Taxing Jurisdiction**

### Improvement / Building

Improvement Residential State Code: A1 Living Area: 818.0 sqft Value: \$17,480 #1:

	Туре	Type Description		Clas	Class CD Exterior Wall		or Wall	Year Built	SQFT	
	LA Living Area OP Attached Open Porch		A - \	A - WS WS		1910	818.0			
			A - NO		1910	132.0				
	PAC	Terrace with cover		A - NO			1910	60.0		
Improve #2:	ment	Residential State Code:		A1 Living		<b>g Area:</b> 598.0 sqf		ft Value:	\$11,280	
	Туре	Description Living Area Attached Open Porch		Clas	ss CD	Exterio	or Wall	Year Built	SQFT	
	LA			F - V	VS	WS		1910	598.0	
	OP			F - N	F - NO			1910	48.0	

Land

**Roll Value History** 

**Deed History - (Last 3 Deed Transactions)** 

2017 data current as of Sep 12 2016 12:30AM.
2016 and prior year data current as of Aug 5 2016 8:08AM
For property information, contact (210) 242-2432 or (210) 224-8511 or email.
For website information, contact (210) 242-2500.

Website version: 1.2.2.7

Database last updated on: 9/12/2016 12:30 AM

© N. Harris Computer Corporation