HISTORIC AND DESIGN REVIEW COMMISSION

January 18, 2017 Agenda Item No: 01

HDRC CASE NO:	2017-018
ADDRESS:	221 CLAUDIA ST
LEGAL DESCRIPTION:	NCB 2876 BLK 1 LOT 5
ZONING:	RM-4,H,HL
CITY COUNCIL DIST.:	1
DISTRICT:	King William Historic District
LANDMARK:	House
APPLICANT:	Jud Janak
OWNER:	Name Janak, Megan Janak
TYPE OF WORK:	Historic Tax Certification and Verification

REQUEST:

The applicant is requesting Historic Tax Certification and Verification for the property at 221 Claudia.

APPLICABLE CITATIONS:

UDC Section 35-618. Tax Exemption Qualifications:

(a) Assessed Valuation. In accordance with the provisions of this article, a building, site, or structure which meets the definition of a historically significant site in need of tax relief to encourage preservation and which is substantially rehabilitated and/or restored as certified by the historic and design review commission and approved by the city tax assessor-collector, shall have an assessed value for ad valorem taxation as follows regardless of ownership during the granted time period:

- (1) A residential property shall have the assessed value for ad valorem taxation for a period of ten (10) tax years equal to the assessed value prior to preservation.
- (b) Applicability. This exemption shall begin on the first day of the first tax year after verification of completion of the preservation required for certification; provided the building shall comply with the applicable zoning regulations for its use and location.
- (c) Application. Application for a historic structure preservation tax exemption pursuant to this division is to be filed with the office of historic preservation. The historic preservation officer shall be the agent of the city for the purposes of administering this division provided that the historic preservation officer request a recommendation from the historic and design review commission. Each application shall be signed and sworn to by the owner of the property and shall:
 - (1) State the legal description of the property proposed for certification;
 - (2) Include an affidavit by the owner describing the historic significance of the structure in need of tax relief;
 - (3) Include a final complete set of plans for the historic structure's restoration or rehabilitation;
 - (4) Include a statement of costs for the restoration or rehabilitation work;
 - (5) Include a projection of the estimated construction, time and predicted completion date of the historic restoration or rehabilitation;
 - (6) Authorize the members of the historic and design review commission, the city tax assessor-collector and city officials to visit and inspect the property proposed for certification and the records and books of the owners as necessary to certify that the property in question is in substantial need of restoration or rehabilitation;
 - (7) Include a detailed statement of the proposed use for the property; and
 - (8) Provide any additional information to the historic and design review commission which the owner deems relevant or useful such as the history of the structure or access to the structure by the public.

Each application shall contain sufficient documentation confirming or supporting the information submitted therein.

- (d) Certification.
 - (1) Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's

documentation for recommendation of either approval or disapproval of the application for exemption.

- (2) Tax Assessor-Collector Approval. Upon receipt of the certified application for tax exemption as well as the recommendation of the historic and design review commission, the city's tax assessor-collector shall within thirty (30) days approve or disapprove eligibility of the property for tax relief pursuant to this division. In determining eligibility, the tax assessor-collector shall first determine that all the requirements of this division have been complied with and that only the historic structure and the land reasonably necessary for access and use thereof is to be provided favorable tax relief.
- (e) Verification of Completion. Upon completion of the restoration and rehabilitation, together with a fee as specified in Appendix "C" of this chapter, the owner, who may not be the same as at the time of application, shall submit a sworn statement of completion acknowledging that the historically significant site in need of tax relief to encourage preservation has been substantially rehabilitated or restored as certified by the historic and design review commission. The historic and design review commission, upon receipt of the sworn statement of completion, but no later than thirty (30) days thereafter, shall make an investigation of the property and shall recommend either approval or disapproval of the fact that the property has been substantially completed as required for certification. If the historic and design review commission recommends that it has not been substantially completed as so required, then the certified applicant may be required by the historic preservation officer to complete the restoration or rehabilitation in order to secure the tax exemption provided herein. If the verification of completion is favorable, the historic and design review commission shall recommend approval and the historic preservation officer may notify the tax assessor-collector in writing of compliance. Thereafter, the tax assessor-collector shall provide the property with the historic tax exemption.
- (f) Historic Preservation Tax Exemptions.
 - (1) Historic Preservation Tax Exemption for Residences in Need of Substantial Repair. In accordance with the provisions of this chapter, a historically significant residential building, which meets both the definitions of a historically significant site in need of tax relief to encourage preservation and of a residential property in Appendix "A" of this chapter, and is either individually designated or is located within the boundaries of a locally designated historic district which is substantially rehabilitated and is approved by the chief appraiser of the Bexar County Appraisal District, shall have an assessed value for ad valorem taxation as follows:
 - A. A residential property shall have no assessed value for ad valorem taxation for a period of five (5) tax years after verification, as defined in Appendix "A" to this chapter. Thereafter, the exempt property shall be reappraised at current market value and assessed at a fifty (50) percent rate for an additional consecutive five-year period.
 - B. This exemption shall begin on the first day of the first tax year after verification of completion of the substantial rehabilitation by the historic and design review commission, provided compliance with subsection (b) of this section.
- (g) Eligibility.
 - (1) The tax exemption options outlined in subsection (f), above, will remain in effect unless terminated by designation status being removed pursuant to subsection 35-606(g) of this article.

FINDINGS:

- a. The applicant is requesting Historic Tax Certification and Tax Verification for the property located at 221 Claudia.
- b. The purpose of the Substantial Rehabilitation Tax Exemption program is to encourage repair and reuse of historic properties; encourage preservation of historic character and original material; assist property owners with the cost of associated with repair and maintenance.
- c. The scope of work consists of wood floor repair, window repair, electrical repair, roof and foundation repair. Foundation, window and roof repair were approved administratively. Staff finds the work is eligible for the program and all work was approved.
- d. The requirements for Historic Tax Certification and Verification outlined in UDC Section 35-618 have been met.
- e. Staff visited the site January 11, 2017.
- f. The approval of tax verification by the HDRC in 2017 means that the property owner will be eligible for the Substantial Rehabilitation Tax incentive beginning in 2018.

RECOMMENDATION:

Staff recommends approval as submitted based on findings a through f.

CASE MANAGER:

Lauren Sage



N

Flex Viewer

Powered by ArcGIS Server

Printed:Jan 09, 2017

The City of San Antonio does not guarantee the accuracy, adequacy, completeness or usefulness of any information. The City does not warrant the completeness, timeliness, or positional, thematic, and attribute accuracy of the GIS data. The GIS data, cartographic products, and associated applications are not legal representations of the depicted data. Information shown on these maps is derived from public records that are constantly undergoing revision. Under no circumstances should GIS-derived products be used for final design purposes. The City provides this information on an "as is" basis without warranty of any kind, express or implied, including but not limited to warranties of merchantability or fitness for a particular purpose, and assumes no responsibility for anyone's use of the information.




















































Rehab Item	Rehab Cost	Approximate Start	Approximate End
		Date	Date
1) Foundation	\$10,350.00	09/21/2015	09/28/2015
2) Electric	\$5,386.47	09/30/2015	11/04/2015
3) Roof & Gutters	\$19,000.00	11/9/2015	11/26/2015
4) Hard Wood Floors	\$1,520.00	12/7/2015	12/11/2015
5) Windows	\$4,750.00	10/01/2016	10/31/2016
6) Paint & Gutter Repair	\$11,463.00	11/01/2016	11/18/2016
Total	52,469.47		

The property at 221 Claudia has 2 residential structures. The first structure is the original historic home built in 1900 and the second structure is a guest house built in the 21st century by the previous owners. All of the improvements listed were performed on the original historic home.

The last complete tax year before my wife and I bought the house in September of 2015 was for 2014. Per a search performed on the Bexar CAD website in 2014, the original historic structure appraised for \$122,990. A thirty percent reinvestment would be \$36,897. As of November 18, 2016 we have invested \$52,469.67 in completed projects.

- 1) We have included the initial agreement, final paid invoice, and foundation repair certification report from a registered professional engineer.
- 2) We have included the initial invoice and final paid invoice for updating the electrical. We have also included pictures of the new outside and inside electrical panels.
- 3) We have included the initial estimate as well as the final invoice for the metal roof and gutters. We have also included before and after pictures.
- 4) The final invoice to refinish the original long-leaf pine hardwood floors is included. We also included before and after pictures.
- 5) We have included the original invoice for the estimate to replace the single pane double hung windows. After the initial estimate, Mr. Elizondo agreed to a final price of \$475 per window (total of 10 windows) if I helped him remove and install the windows. The original windows were removed and the original glass was saved. Then the original glass was installed in Mr. Elizondo's period appropriate double hung single pane wood windows. Finally the windows were installed. We have attached before and after pictures. We also have the certificate of appropriateness.
- 6) The original invoice for new exterior paint and gutter repair is attached. We also have the final invoice attached as well as before and after pictures. We also have the certificate of appropriateness.

Bexar CAD

Property Search Results > 136491 JANAK JUDSON CLARKE & MEGAN ELIZABETH for Year 2016

Property

Account					
Property ID:	136491			Legal Description:	NCB 2876 BLK 1 LOT 5
Geographic ID:	02876-001-0050	0		Agent Code:	
Туре:	Real				
Property Use Code:	001				
Property Use Description:	Single Family				
Location					
Address:	221 CLAUDIA ST SAN ANTONIO, 1			Mapsco:	616F7
Neighborhood:	ACEQUIA MADR	RE NAT/LOC HI	IST (SA)	Map ID:	
Neighborhood CD:	57300				
Owner					
Name:	JANAK JUDSON	CLARKE & ME	GAN ELIZABETH	Owner ID:	2971878
Mailing Address:	221 CLAUDIA ST SAN ANTONIO, 1		8	% Ownership:	100.000000000%
				Exemptions:	HS
alues					
(+) Improvement Homes	site Value:	+	\$297,570		
(+) Improvement Non-H	omesite Value:	+	\$0		
(+) Land Homesite Value	e:	+	\$81,140		
(+) Land Non-Homesite	Value:	+	\$0	Ag / Timber Use Va	alue
(+) Agricultural Market \	/aluation:	+	\$0		\$0
(+) Timber Market Valua	ation:	+	\$0		\$0
(=) Market Value:		=	\$378,710		
(–) Ag or Timber Use Va	lue Reduction:	-	\$0		
(=) Appraised Value:		=	\$378,710		
(–) HS Cap:		-	\$0		
(=) Assessed Value:		=	\$378,710		
xing Jurisdiction					
Owner: JANAK J	UDSON CLARKE	& MEGAN E	LIZABETH		
% Ownership: 100.000 Total Value: \$378,71	000000%				

17			Bexar CAD - Property I	Jetans	
Entity	Description	Tax Rate	Appraised Value	Taxable Value	Estimated Tax
06	BEXAR CO RD & FLOOD	0.015700	\$378,710	\$375,710	\$58.99
08	SA RIVER AUTH	0.017290	\$378,710	\$373,710	\$64.61
09	ALAMO COM COLLEGE	0.149150	\$378,710	\$378,710	\$564.85
10	UNIV HEALTH SYSTEM	0.276235	\$378,710	\$378,710	\$1,046.13
11	BEXAR COUNTY	0.293250	\$378,710	\$378,710	\$1,110.57
21	CITY OF SAN ANTONIO	0.558270	\$378,710	\$378,710	\$2,114.22
57	SAN ANTONIO ISD	1.512600	\$378,710	\$353,710	\$5,350.22
CAD	BEXAR APPRAISAL DISTRICT	0.000000	\$378,710	\$378,710	\$0.00
	Total Tax Rate:	2.822495			
				Taxes w/Current Exemptions:	\$10,309.59
				Taxes w/o Exemptions:	\$10,689.07

mprovement #1:	Residential State Code:	A1 Livii Area	•	sqft V	alue: \$162,120
Туре	Description	Class CD	Exterior Wall	Year Built	SQFT
LA	Living Area	A - WS		1900	1124.0
OP	Attached Open Porch	A - NO		1900	88.0
LA1	Additional Living Area	A - WS		0	181.0
Improvement #2:	Residential State Code:	A1 Livii Area	•	sqft V	alue: \$135,450
Туре	Description	Class CD	Exterior Wall	Year Built	SQFT
LA	Living Area	A - WS		1900	1209.0
СР	Att Carport	A - NO		1980	546.0
PAC	Terrace with cover	A - NO		1980	126.0

Land

#	Туре	Description	Acres	Sqft	Eff Front	Eff Depth	Market Value	Prod. Value
1	RES	R/1 Family not Farm Single	0.1687	7350.00	50.00	147.00	\$81,140	\$0

Roll Value History

Year	Improvements	Land Market	Ag Valuation	Appraised	HS Cap	Assessed
2017	N/A	N/A	N/A	N/A	N/A	N/A
2016	\$297,570	\$81,140	0	378,710	\$0	\$378,710
2015	\$275,030	\$81,130	0	356,160	\$0	\$356,160
2014	\$214,190	\$81,130	0	295,320	\$0	\$295,320
2013	\$198,550	\$81,130	0	279,680	\$0	\$279,680
2012	\$204,040	\$50,100	0	254,140	\$0	\$254,140

Deed History - (Last 3 Deed Transactions)

#	Deed Date	Туре	Description	Grantor	Grantee	Volume	Page	Deed Number	

1/11/2017 Bexar CAD - Prope				operty Details					
-	1	9/17/2015	GWD	General Warranty Deed	HEMPHILL KELLY P & CHARLES K	JANAK JUDSON CLARKE & MEGAN ELIZABETH	17464	0410	20150179260
	2	5/14/2009	GWD	General Warranty Deed	AMARO FRANCISCO M	HEMPHILL KELLY P & CHARLES K	13985	1134	20090088379
	3		Deed	Deed		AMARO, FRANCISCO M	7169	0972	0

2017 data current as of Jan 9 2017 12:29AM.

2016 and prior year data current as of Dec 9 2016 7:56AM

For property information, contact (210) 242-2432 or (210) 224-8511 or email.

For website information, contact (210) 242-2500.

Website version: 1.2.2.11

Database last updated on: 1/9/2017 12:29 AM

© N. Harris Computer Corporation

Davila Electric Co., Inc.

1842 Bandera Rd. San Antonio, TX 78228-3801 TexasElectricalContractorLicense #17069

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	·
VALL.	

1	Ir	V	0	ic	e
		. Los			

Date Invoice # 9/7/2015 34875

Judson Janek 221 Claudia San Antonio, Texas 78210

Jobsite	Information
---------	-------------

Re: 221 Claudia San Antonio, Texas

Г														
1	Phone # 210.436.1		551	Fax # 210.4	35.9800	E	E-mail:davilaeleo	ctric@s	bcglo	bal.net	ana ana ina ma			
	CUST P.O. No.			Terms	Due Upon Rec't		Tech	Job#		Requested By				
ľ			Du	ie on receipt	9/7/2015 SG		SG	50902		Juds	on			
	Date	ltem			Des	cription				Svc Units	Rate	Amount		
9/3/2	9/3/2015 Bid Bid work per contract agreement as follows: -Inspected all electrical points -Made lights and submitted a proposal on repairs Subtotal										358.50	358.50T 358.50		
Tha	Thank you for your business!								Su	btotal	<u> </u>	\$358.50		
Plea	Please pay by this invoice- no statement will be sent. A \$35.00 fee is charged for a returned check. Any invoice aged over 30 days may be handled for collection at \$50.00 per							per	Sa	es Tax (8	8.25%)	\$29.58		
month until paid in full. 30-day labor warranty. Faulty materials & fixtures will defer to the mfg. warranty. Customer supplied items are not warrantied.								To	\$388.08					
Any dispute with this bill must be submitted in writing within ten (10) days of the billing date; otherwise it is deemed correct, with no further recourse. Thank you - we appreciate your business!							e	Payments/Credits \$0.0			\$0.00			
Regulated by The Texas Dept of Licensing & Regulation, PO Box 12157, Austin, TX 78711, 1.800.803.9202, Website:www.state.tx.us								Ba	alance I	Due	\$388.08			

Davila Electric Co., Inc.

1842 Bandera Rd. San Antonio, TX 78228-3801 TexasElectricalContractorLicense #17069

PAL THIS INV: NO STATEMENT WILL BE SENT

THANK YOU!

Invoice

 Date
 Invoice #

 11/4/2015
 50920

Bill To

Judson Janak 221 Claudia San Antonio, Texas 78210 Jobsite Information Re: 221 Claudia San Antonio, Texas judjanak@gmail.com

Phone	e # 210.436 .1	1551 Fax # 210.4	35.9800		E-mail:davilaele	ctric@sb	global.net			
CUST	P.O. No.	Terms	Due Upon Rec't		Tech		Job#	Requested By		
		Due on receipt	Due on receipt 11/4/2015 SG				51170	Judson		
Date	ltem	Description Svc Units						Rate	Amoun	
11/4/2015	Bid	Bid work Scope I- Main House Svc Onits Front bedroom 1)Properly install foyer hanging fixture and wire for and install switch for permanent power Kitchen 2)Install GFCI left of sink 3)Install GFCI protection on two (2) additional plugs Laundry room 4)Replace light fixture provided by customer Miscellaneous 5)Lower 7 ea. plugs to new location along baseboard. Blank over old outlet box. Guest House 6) Install GE arc fault combination breaker for smoke detectors								
Contractor	r your busines	Bid work Scope II s!						2,165.63	2,165.6	
						S	ubtotal			
Please pay by this invoice- no statement will be sent. A \$35.00 fee is charged for a returned check. Any invoice aged over 30 days may be handled for collection at \$50.00 per merch will will be full.							Sales Tax (8.25%)			
month until paid in full. 30-day labor warranty. Faulty materials & fixtures will defer to the mfg. warranty. Customer supplied items are not warrantied. Any dispute with this bill must be submitted in writing within ten (10) days of the billing date; otherwise it is deemed correct, with no further recourse. Thank you - we appreciate						Т	Total			
							Payments/Credits			
Regulated by The Texas Dept of Licensing & Regulation, PO Box 12157, Austin, TX							Balance Due See pg. 3			

78711, 1.800.803.9202, Website:www.state.tx.us

Davila Electric Co., Inc.

1842 Bandera Rd. San Antonio, TX 78228-3801 TexasElectricalContractorLicense #17069

Invoice

 Date
 Invoice #

 11/4/2015
 50920

Bill To	
Judson Janak 221 Claudia San Antonio, Texas 78210	

Jobsite Information Re: 221 Claudia

San Antonio, Texas judjanak@gmail.com

F	Phone # 210.4	136.1551	Fax # 210.4	35.9800		E-mail:davilaele	ctric@sbcg	@sbcglobal.net				
	CUST P.O. No.		Terms	Due Upon Rec't		Tech	J	lob#	Requested By			
		D	Due on receipt 11/4/2015 SG			5	51170		on			
Dat	te Item	1		Desc	cription)	Svc Units			Amount		
11/4/20	15 Bid	Main •Repl. follow oOne oTwo oOne oTwo oSix (oLabe •Bono •Insta Bid w	de as		1,543.19	1,543.19						
Thank y	ou for your bu	siness!		Su	btotal							
returned	Please pay by this invoice- no statement will be sent. A \$35.00 fee is charged for a returned check. Any invoice aged over 30 days may be handled for collection at \$50.00 per						per Sa	Sales Tax (8.25%)				
month until paid in full. 30-day labor warranty. Faulty materials & fixtures will defer to the mfg. warranty. Customer supplied items are not warrantied.								Total				
Any dispute with this bill must be submitted in writing within ten (10) days of the billing date; otherwise it is deemed correct, with no further recourse. Thank you - we appreciate your business!								Payments/Credits				
Regulated by The Texas Dept of Licensing & Regulation, PO Box 12157, Austin, TX 78711, 1.800.803.9202, Website:www.state.tx.us						Ba	Balance Due See Pg. 3					

Davila Electric Co., Inc.

1842 Bandera Rd. San Antonio, TX 78228-3801 TexasElectricalContractorLicense #17069

Inv	oice
Date In	voice #

11/4/2015	
-----------	--

50920

Jobsite Information
Re: 221 Claudia San Antonio, Texas judjanak@gmail.com

Phone	# 210.436.1	551	Fax # 210.4	35.9800	E	E-mail:davilaelee	ctric@	sbcglo	bal.net			
CUST	P.O. No.		Terms	Due Upon	Rec't	Tech		Job#		Requested By		
		Du	ie on receipt	11/4/20)15	SG		51	170	Judson		
Date	Item			Des	cription	1			Svc Units	Rate	Amount	
		•Run r •Inside oOne oTwer	e panel will be u (1) 24-circuit pa nty (20) 20-amp el and test upon c	r from main pgraded as fo nel breakers	panel, u	under house to ins o accommodate 4	ide par -wire s	nel ystem			4,998.3	
'hank you fo	r your busine	ss!						Su	ototal		\$4,998.39	
eturned chec	k. Any invoi	no state ce aged	ement will be ser over 30 days ma	nt. A \$35.00 by be handled) fee is c d for co	charged for a llection at \$50.00	per	Sal	es Tax (8	.25%)	\$0.00	
	warranty. Fa		terials & fixtures varrantied.	will defer to	the mf	g. warranty.		Total			\$4,998.3	
Customer supplied items are not warrantied. Any dispute with this bill must be submitted in writing within ten (10) days of the billing date; otherwise it is deemed correct, with no further recourse. Thank you - we appreciate					Pay	yments/Cr	edits	\$0.0				

Regulated by The Texas Dept of Licensing & Regulation, PO Box 12157, Austin, TX 78711, 1.800.803.9202, Website:www.state.tx.us

your business!

Balance Due

\$4,998.39



341 University Ave San Antonio, TX 78201, 210-316-6595, MROD@IRONCLADROOF.COM

ROOF INSPECTION REPORT

Address: 221 Claudia San Antonio Texas 78210

Roof Type: Metal standing seam 24 gauge double lock.

Estimate age of roof : Approximately 60-80 years

Roof condition:

Main House:

Roof has sustained hail damage from multiple storms.

Valleys are rusting and have penetrations. Turn back flashing in valleys are compromised by rust and debris.

Double munch hip and ridges are bent over and are not vertical, leaving them prone to rust and water damage.

Coating on roof is pealing and bubbling from rust and corrosion. Asphalt has been applied to valleys and ridges where rust has penetrated metal.

There is no decking, metal roof is layered over wood shake shingles.

			IN	VOICE
Customer		Misc	,	
Name Address City Phone	Judd Janak 221 Claudia San Antonio State Tx ZIP	Date Order No. Rep FOB	11/2 mr	26/2015
Qty	Description	Unit Price		TOTAL
1	remove and replace galvanized roofing standing seam 26 gauge install gutters to entire house		\$	21,000.00
	down payment		\$	(10,500.00)
	down payment credit		\$	
				(10,500.00) (2,000.00) (8,500.00)
	credit final payment	SubTotal Shipping	\$	(2,000.00)
Payment	credit final payment	SubTotal Shipping	\$	(2,000.00)




.




Invoice

AU	VANCED						
woo	DD FLOORS			Date Invoice # 12/11/2015 116754			Invoice #
Bill To		Ship To			110/34		
Jud Janak 221 Claudia San Antonio, 7	ΓX		221 Clau		210		
S.O. No.	Ref #	Terms	Due	Due Date Rep Proje			Project
110735		Due on receipt	12/1	1/2015	JEI	3	221 Claudia
Item	Des	cription		Invoiced Rate			Amount
Residential Residential	of sealer and two coats Re coat back bedroom one coat of finish. Change to scope of wo	and front bedroon	n using		1	410.0 -546.0	
We Apprecia	te Your Business. Final	Bill		Subtot			\$1,520.00
				Sales T Total	\$0.00 \$1,520.00		
					nts/Crea	dits	\$0.00
				Balar	ice Di	10	\$1,520.00

- 202 W. Nakoma San Antonio, TX 78216 - Ph: 210-341-5241 - Fx: 210-308-5536 - AdvancedWoodFloors.com -







My Three Sons Luis Elizondo 310 Shannon Lee San Antonio, Texas 78216 (210) 777-5934 mythreesons@grandecom.net ElN: 65-1261952

4/17/16

TOTAL EACH

Specializing in Doors and Windows Architectural Restoration and Renovation

Bill To: Jud Janak judjanak@gmail.com RE: 221 Claudia

ESTIMATE

DESCRIPTION

		-	
•	Build new sash to match originals		\$160.00
•	Prime sash		\$30.00
•	Paint sash (two-tone) (two coat)		\$75.00
•	Remove old sash		\$25.00
•	Install new sash		\$40.00
		_	
		TOTAL EACH	\$330.00
NOTE:	Glass and glazing not included.	=	

To be provided by other.

NOTE: Estimates good for 30 days for quantities ≥10 Invoices Due Upon Receipt Foundation Repair

Agreement

Date: 8/27/2015

Owner: Jud Janek

Project Address: 221 Claudia, San Antonio, TX 78210

Mailing Address:

Office Tele No.: Cell No.: 210.400.6488 Fax No.:

Provisions:

Concrete Job Pour Supports: 32

Beam: 28'

Joist: 8'

Other:

Description of Work:

- Install (32) Concrete Job Pour Supports / Differentials will remain
- Install (28') Treated Beam
- Install (28') Joist Support under bathroom
- · Lift and adjust structure to tolerance of existing wood joists, beams and/or supports
- 3rd Party Engineer Certification
- Note: HVAC Ducts, Plumbing pipes and/or gas may require to be cut / repairs not included
- Note: Water migration within understructure should be amended
- Note: Recommend a hydrostatic plumbing test on rear guest house
- Ten Year New Concrete Warranty / One Year Re-Shim Warranty

Cash Payment Terms:

Total Amount: \$ 10,200.00

Down Payment: \$ 5,100.00

First Draw Due Upon Completion of Piers: \$4,100.00

Balance Due Upon Removal of Temp Supports: \$ 1,000.00

The total amount due does not reflect or include any plumbing, electrical, cosmetic repairs, skirting repairs or framing adjustments that may be required for the exterior or interior of the structure unless specifically indicated above. All excess, native soil will remain on property unless specifically indicated above. If the balance is not submitted within the payment terms described above any fees incurred to file applicable lien(s) will be of the owners expense. It is expressly agreed that payment delinquency on this agreement will not be charged in excess of 5% or the highest legal rate specified by the laws of the State of Texas and that future adjustments will be made to avoid the payment of interest in excess of such limits. This agreement supersedes any verbal or written agreement(s) between company, owner and any financier. Any alteration to the above described work involving additional material and/or costs will be submitted in writing and approved prior to implementation. The above described work will be performed in accordance with the drawings and specifications submitted for this agreement and completed in a substantial workmanlike manner. NOTE: This contract may be withdrawn by Vantage Foundation Repair, Inc., if not accepted in 15 days.

The above listed price, payment terms and conditions under this contract are satisfactory and accepted. I hereby authorize Vantage Foundation Repair, Inc., to start and complete the specified work above.

Date: 09/09/2015

Print Name: Jud Janak Signature: Just Janah



Agreement (Conditions)

The foundation will be elevated until, in the opinion of the company, any additional, upward movement or pressure induced to the foundation will generate undesirable results or damage to the foundation and/or super structure. The result of underpinning can amend the damage previously done to the foundation or super structure and/or create additional damage by the underpinning process. It is expressly agreed the company is not liable to replace or repair any damage that may occur to the foundation, super structure, driveway, plumbing systems, gas systems, electrical systems, AC systems, sprinkler systems, vegetation, landscaping, interior and exterior wall finishes, flooring or personal property whether buried, exposed or concealed. It is recommended all cosmetic work completed on the interior or exterior of the structure, be completed at a minimum of 90 days from the completion of the underpinning process.

During the underpinning process if the foundation is determined to be of substandard material or demonstrates deficiencies, inhibiting the company to properly lift and/or stabilize the foundation, or any unforeseen wood members or supports are required to properly support the foundation, amendments to the contract price, terms and/or warranty may occur. If the foundation incorporates builder piers, drilled piers or spread footings an additional fee of \$150 per location, per pier or \$200 per linear-horizontal ft., will be incurred to sever said piers or footings from the foundation to properly transfer the load. If the perimeter and/or interior grade beam is found to be greater than, a 3' depth, additional fees at the current rate set forth by company to access the beam for proper support will occur. Utilities will be required during the underpinning or repair process, all utilities to be of owners and/or managers expense.

The warranty under this contract implies to the intention of the company to nullify post underpinning settlement within one and one half parts in two hundred-forty parts (1.5" in a 20' horizontal span) for portions under this contract. Partial underpinning a structure may cause additional movement in portions of the structure not included in a partial underpinning process. The owner further understands and agrees the warranty under this contract applies to only those portions, provisions and conditions of this contract. All conditions under this agreement apply to warranty adjustments and/or repairs. If at not fault to the company, additional repairs or services are required under this warranty additional fees at the current rate set forth by the company may apply.

Initial A.J.

The warranty under this contract will be null and void if: payment is not submitted as per the terms of this contract; if the structure does not pass a static plumbing test within 30 days of completing the work performed under this contract; if vertical or horizontal structural additions (Room additions) are made to the structure without written notice to the company; if the foundation is undermined by pool leaks, pond leaks, plumbing leaks, septic system leaks, natural springs, sprinkler leaks, soil slumping, excavations, negative drainage or erosion; if acts of God undermine the foundation (floods, earthquakes, etc.) or the property undergoes foreclosure.

In accordance with the company warranty transfer policy the owner of the warranty under this contract shall send a written request to the company to include the new owner/owners name, address and two hundred dollars. The owner of the warranty further understands and agrees if the company does not obtain a written request to transfer the warranty within 20 days after transfer of title the WARRANTY IS NULL & VOID.

Initial

In the event that the owner and company cannot agree that the settlement in the foundation has been controlled for those portions of this contract and settlement is within the tolerance specified above, it is specifically agreed by acceptance of the warranty that the matter shall be determined by binding arbitration. Arbitration shall be conducted in accordance with the rules prevailing of the American Arbitration Association or any successor thereto. The company may terminate this warranty at any time by paying the current owner an amount equal to the total payments made under the original contract.

Direct all notices to Vantage Foundation Repair, Inc., 11844 Bandera Rd. #477, Helotes, TX 78023 · Tele 210.338.5678 · Fax 210.568.4877

Any changes to this document will not be valid unless approved in writing by both parties

Date: 09/09/2015

Jud Janak Print Name: Signature:

VANTAGE Repair 1184	tage Foundation Repair				nvoid	
	4 Bandera Road #477			Date	Invoice	
Helo	tes, TX 78023	5 98 8.		9/28/2015	1928	
Billing Address		Project Address	······	2		
Jud Janek 221 Claudia	1012912	Jud Janek 221 Claudia				
San Antonio, TX 78210		San Antonio, TX 78	210			
		Project No.		Terms	Due Date	
		221-1509	0	n Completion	9/28/2015	
	Description			Amount		
air and replace Pier & Be	am Understructure	······································			10,200.0	
			-			
	1 SILL)					
	Thankyou?					
	J J					
			Tota	al	\$10,350.	
			Pay	ments/Credits	-\$10,350.0	
				lance Due	\$0.0	
				ance Due		



5934 S Staples Suite 227 -Corpus Christi, Texas 78413-Office /Fax 361 808 9705 Firm -4053 6800 Park Ten Blvd Suite 212-N San Antonio, Texas 78413-Office/Fax 210 732 9705 Firm 4053

> FOUDATION REPAIR CERTIFICAION REPORT October 29,2015

Vantage Foundation Repair, Texas 11844 Bandera Rd #477 Helotes, Texas 78023

REF: 221 Claudia ,San Antonio, Texas 78210

At the request of Vantage Foundation Repair, We performed the assessment of the foundation repair at 221 Claudia ,San Antonio, Texas 78210. The scope of the assessments includes, the site inspection and verification of the repair work performed as shown on the repair plan drawing in order to certify the repair. Any other repair work performed by others is not part of this survey and therefore, is not verified by this report

The structure is a single-family Two-story dwelling supported by pier and beam foundation that has experienced foundation movement Vantage Foundation Repair has installed the 35 (thirty five) concrete pour supports as shown on the foundation repair plan drawings.

Qualified Individual from this office visited the site to check the construction stated above off for the general conformance with the design construction documents OR engineer guidance and the 2012 edition of the International Residential Code for residential sites.


In my opinion, based on our experience, knowledge, information and belief, the stated construction that we observed is in general conformance with our design/construction documents OR engineer guidance and the 2012 edition of the international Residential Code for residential sites. <u>All perimeter</u> drainage, ventilation, and skirting meet IRC requirements and there scuttle hole.

As denoted by the engineer seal on my construction documents and on the letter ,we have full filed our obligation as an engineer under the Texas Engineering practice act pursuant to its requirements to protect the public health,safety and welfare in the practice of engineering. We further believe we met these requirements insofar as our responsibility for periodic observation of the work for conformance is concerned. No responsibility is assumption the vents that occur after the inspection and submission. No warranty, either expressed or implicit, is made

F-4053



Austin, Corpus Christi, Dallas, Galveston, Houston, San Antonio, New Bruanfels



a'.



CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION

ADMINISTRATIVE CERTIFICATE OF APPROPRIATENESS

September 9, 2016

ADDRESS:	221 CLAUDIA ST
LEGAL DESCRIPTION:	NCB 2876 BLK 1 LOT 5
HISTORIC DISTRICT:	King William
PUBLIC PROPERTY:	Νο
LANDMARK:	House
RIVER IMPROVEMENT OVERLAY:	No
APPLICANT:	Jud and Megan Janak - 221 Claudia
OWNER:	Jud and Megan Janak - 221 Claudia
TYPE OF WORK:	Repair and Maintenance, Painting

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to restore existing wood windows throughout the house and paint the exterior.

CITY OF SAN ANTONIO OFFICE OF HISTORIC PRESERVATION DATE: 9/9/2016 12:16:47 PM ADMINISTRATIVE APPROVAL TO: 1. rd

ADMINISTRATIVE APPROVAL TO: 1. restore nine (9) wood windows with in-kind materials; replace any damaged sashes with new, custom wood sashes to match existing. Existing window openings should not be altered in any way. New glass may be installed, and the clarity of the glass must match what is existing. Glazing and general repairs are approved.


2. re-paint the house; body will be green (dark sage); windows will be burnt orange; trim will be mustard yellow; columns and trim will be white/cream.

APPROVED BY: Katie Totman

Shanon Shea Miller Historic Preservation Officer A.H.C Gutters, LLC 307 Hompipe Hills San Antonio, TX 78260

(210) 665-5500 Info@AmericanHillCountryGutters.com www.AmericanHillCountryGutters.com





Address Jud Yonick 221 Claudia Street San Antonio, TX 78210

 Painting: 9,435.00 *Sand and scrap exterior surface of home *Replace and repair all needed exterior siding, trim, soffit and fascia *Caulk and seal 100% exterior surface *Power wash and clean around exterior surface Apply Sherwin Williams Pro Industrial Universal Acrylic Primer to exterior surface (Due to the age of some exterior wood, we will apply as many coats as needed to achieve smooth uniform finish) *No charge if you should choose to paint front door* *Painting of the front Patio floor and detached garage is not included in price* "Our finest paint with best-in-class overall performance. "Teatures an exclusive cross-linking 100% acrylic technology for exceptional durability and hide. "Extreme resistance to blistering, peeling, fading and dirt pickup. "Self-priming with a smooth, uniform appearance. "Provides a mildew-resistant coating. "Low temperature application down to 35°F. "Contains VinylSafe® Technology allowing you to paint darker colors on vinyl siding without worrying about warping or buckling. "AttC Gutters & Painting 2 year craftsmanship warranty 	Activity	Amount
	 Painting: Sand and scrap exterior surface of home Replace and repair all needed exterior siding, trim, soffit and fascia Caulk and seal 100% exterior surface Power wash and clean around exterior surface Apply Sherwin Williams Pro Industrial Universal Acrylic Primer to exterior surface Apply Sherwin Williams Emerald Exterior Latex Satin in 5 colors to exterior surface Due to the age of some exterior wood, we will apply as many coats as needed to achieve smooth uniform finish) No charge if you should choose to paint front door* Painting of the front Patio floor and detached garage is not included in price* Our finest paint with best-in-class overall performance. Features an exclusive cross-linking 100% acrylic technology for exceptional durability and hide. Extreme resistance to blistering, peeling, fading and dirt pickup. Self-priming with a smooth, uniform appearance. Provides a mildew-resistant coating. Meets the most stringent VOC regulations. Low temperature application down to 35°F. Contains VinylSafe® Technology allowing you to paint darker colors on vinyl siding without worrying bout warping or buckling. Available in all Sherwin-Williams colors and custom tints in flat, satin and gloss. 	
	18 Month 0% Financing Available*** Total	\$9,435.0

Accepted By

Accepted Date

Synchrony Bank	Sales Slip - B
48531 Payment Processe	
Synchrony Bank	
2,3,0,2,4,9,5,1,2,6,2,	5 3 4 8 1 2 1 7 3 0 6 7 3 7 6 9 MERCHANT NUMBER
JUD & MEGAN JANAK	AMERICAN HILL CNTRY GUT 307 HORNPIPE HILLS
BUYER NAME Promotional Offers - See reverse side for additional details	MERCHANT NAME / MERCHANT ADDRESS
600 Reduced 9.99% APR and fixed monthly payments equa	
604 Reduced 7.99% APR and fixed monthly payments equa	al to 2.00% of promo purchase amount - Until Paid in Full
602 Reduced 5.99% APR and fixed monthly payments equa	al to 3.00% of promo purchase amount - Until Paid in Full
period. If the promo purchase balance is not paid in full by the end of the date of purchase at the APR inserted immediately above. Fixed is of the highest balance applicable to this promo purchase, rounded to	nonthiv payments are required equal to 2.30%
DESCRI	
	O PLUMBING O SPA
O BATH REFACE/WALK IN TUBS O HVAC O ELECTRIC O INSULATION	O ROOFING O WINDOWS/DOORS
O GENERATOR O KITCHEN REFAC	
GUTTER SYSTEM O PAVERS/LANDSO	SALE PRICE
Brand / Description	
Brand / Description / / / / / / / / / / / / / / / / / / /	
This form is for final payment and cannot be processed until the	
contract between the Buyer and Merchant has been completed	TOTAL PRICE 1, 1, 4, 6, 3, 0,0
0 1 7 5 4 8	TOTAL PAYMENTS
AUTH. CODE	AMOUNT 1, 1, 4, 6, 3, 0,0

1,0,/,1,7,/2,0,1,6 DATE OF SALE

I acknowledge receipt of a completed copy of this Sales Slip and have reviewed and understand the promotional terms that will apply to this purchase. I authorize the amount shown to be charged to my credit card account shown above and agree that the purchase will be governed by the terms of the Synchrony Bank Credit Card Agreement.

If this was an in-home sales transaction, I acknowledge that I have been provided by the Merchant with both the oral and written notice of my right, as a Buyer, to cancel this transaction (if applicable).

Synchrony Bank assesses a one-time \$29 Activation Fee under the Credit Card Agreement at the time the first purchase posts to the account. Any additional surcharges or fees charged by the merchant in connection with applying for or using the Credit Card are prohibited.

SIGNATURE) (BUYER

X Megal Jane (BUYÉR SIGNATURE) 202-343-00 (04/2016) HI-B 19672

49715 COMPLETION CERTIFICATE
SYNCHRONY BANK
23024951262 Account #
Customer 1- First Name M.I. Last Name
MEGAN Customer 2- First Name M.I. Last Name
NOTICE TO CUSTOMER
DO NOT SIGN THIS CERTIFICATE UNTIL ALL SERVICES HAVE BEEN SATISFACTORILY PERFORMED
I (We) certify that:
 Any money advanced has been sent in accordance with the terms contained in the sales slip or contract; The property improvements are completed to my (our) satisfaction; and I (We) understand that the selection of the merchant and acceptance of the materials used and the work performed is my (our) responsibility.
Customer Signature Month Day Year
Million Janah Customer Signature Month Day Year
The undersigned certifies that:
 (1) The property improvements are completed to the satisfaction of the customer(s); and (2) The customer(s) signed this certificate after completion of the property improvements, and all signatures on this certificate are genuine; and (3) All debts for labor, material, license fees, permits, inspection fees and other bills, pertaining to the customer's contract have been paid in full and there will be no mechanic's, materialman's or other lien(s) on customer's residence as a consequence of said installation.
AIMIEITIICIAINIHIILICINITIYIGUTI Merchant Name
Merchant Signature Title Month Day Year
5 3 4 8 1 2 1 1 3 0 6 7 3 7 6 9 49715 Merchant Number 202-097-00 (08/2014) HI 0212123 10 10 10 12 10 10