HISTORIC AND DESIGN REVIEW COMMISSION February 05, 2020

HDRC CASE NO: 2020-040 2011 W MAGNOLIA AVE **ADDRESS: LEGAL DESCRIPTION:** NCB 1953 BLK LOT W 45.5 FT OF 3 R-6.H **ZONING:** 7 **CITY COUNCIL DIST.:** Monticello Park Historic District **DISTRICT: APPLICANT: Dorothy Choice** Dorothy Choice **OWNER:** Historic Tax Verification **TYPE OF WORK:** January 07, 2020 **APPLICATION RECEIVED:** March 07, 2020 **60-DAY REVIEW: Stephanie Phillips CASE MANAGER:**

REQUEST:

The applicant is requesting Historic Tax Verification for the property at 2011 W Magnolia Ave.

APPLICABLE CITATIONS:

UDC Section 35-618 Tax Exemption Qualifications:

(e) Verification of Completion. Upon completion of the restoration and rehabilitation, together with a fee as specified in Appendix "C" of this chapter, the owner, who may not be the same as at the time of application, shall submit a sworn statement of completion acknowledging that the historically significant site in need of tax relief to encourage preservation has been substantially rehabilitated or restored as certified by the historic and design review commission. The historic and design review commission, upon receipt of the sworn statement of completion, but no later than thirty (30) days thereafter, shall make an investigation of the property and shall recommend either approval or disapproval of the fact that the property has been substantially completed as required for certification. If the historic and design review commission recommends that it has not been substantially completed as so required, then the certified applicant may be required by the historic preservation officer to complete the restoration or rehabilitation in order to secure the tax exemption provided herein. If the verification of completion is favorable, the historic and design review commission shall recommend approval and the historic preservation office may notify the tax assessor-collector in writing of compliance. Thereafter, the tax assessor-collector shall provide the property with the historic tax exemption.


FINDINGS:

- a. The primary structure located at 2011 W Magnolia Ave is a 1-story single family home constructed circa 1930 in the Tudor Revival style. The home features an arched entryway, prominent brick chimney, and an asymmetrical side porch. The structure is contributing to the Monticello Park Historic District. The applicant is requesting Historic Tax Verification. The applicant received Historic Tax Certification on September 18, 2019.
- b. The scope of work includes siding repair, wood window repair, foundation repair, painting, and a comprehensive interior remodel.
- c. Staff conducted a site visit on January 24, 2020, to examine the exterior conditions of the property. The work has been completed.
- d. The applicant has met all requirements of the City's tax verification process as described in Section 35-618 of the UDC and has furnished evidence to that effect to the Historic Preservation Officer, including the submission of an itemized list of costs that meets the threshold to be eligible for the Substantial Rehabilitation Tax Incentive.
- e. Approval of Tax Verification by the HDRC on February 5, 2020, means that the property owners will be eligible for the Substantial Rehabilitation Tax Incentive beginning in 2020. The Substantial Rehabilitation Tax Incentive applies to the City of San Antonio tax entity line only.

RECOMMENDATION:


Staff recommends approval based on findings a through e.

City of San Antonio One Stop



September 13, 2019

User drawn lines



City of San Antonio GIS Copyright 9-13-2019

Copyright 2013 San Antonio Board of Realtors®




Copyright 2019 San Antonio Board of Realtors®





City of San Antonio – Residential Combination Inspections A/P Number 2554374 Address 2011 M Model inspection # Your inspection was: Approved Partial Passed Conditional Approval (see comments summarization below) The following inspections were performed: Mechanical Rough-in Final Reconnect (TML) (CEE) Rough in Top out (IRR) Waterpipe in Slab Underground Waterline Reconnect Top out (IRR) Waterpipe in Slab	City of San Antonio – Residential Combination Inspections A/P Number 25:4/374 Address 2011 M Monoduce Average and the second	City of San Antonio – Residential Combination Inspections A/P Number 2554374 Address 2011 W Moond in Africa Address 2011 W	ARREDONDO ENGINEERING		Inspection of ledger attachment and flashing and joist for a new 11' x 13' 143 SQ.FT uncovered deck, with handrails and stairs, attached to rear of existing residence on new concrete post foundation with new footings Located at 2011 W Magnolia, San Antonio, TX 78201	NCB 1953 BLK LOT W 45.5 FT OF 3	2554376	coar Juan. Ou constructed your residential renovation referenced above using standard construction and engineering techniques and using comments and onidance memored by Arredondo Engineering 1 LC. Onalified individuals from this office visited the site to	here the construction stated above for general conformance with our construction documents and guidance and. In my opinion, ased on our experience, knowledge, information and belief, the stated construction that we observed is in general conformance it our construction documents and the 2018 International Residential Code.	d are covered under this letter:	 Plumbing Electrical Electrical Mechanical Mechanical Interflective roof, and fenestration) Interflective roof, and fenestration 	s denoted by the engineering seal on the construction documents and on this letter, we believe we have fulfilled our obligations as an engineer under the Texas Engineering Practice Act pursuant to its requirements to protect the public health, safety, and elfare in the practice of engineering/architecture. We further believe we have met those requirements insofar as our esponsibility for periodic observation of the work for conformance is concerned. FJ8378 tyou have any questions, please call. F_{-18378} the practice of engineering/architecture. We further believe we have met those requirements insofar as our esponsibility for periodic observation of the work for conformance is concerned. F_{-18378} the any questions, please call. F_{-18378} the arry questions, please call. F_{-18378} the formation of the work for conformance is concerned. F_{-18378} the formation of the wor
A/P Number 2554374 Address 201 W Magnal (Address Magna (Address Magnal (Address Magnal (Address Ma	A/P Number 25544374 Address 201 Mode Mode Address Mode Address Conditional Approval (see comments summarization below) Your inspection was: Approved Partial Passed Conditional Approval (see comments summarization below) The following inspections were performed: Mechanical Electrical Notestand Okay to insulate? Y / N Mechanical Electrical Plumbing Building Dublication Frame UDFrame Final Reconnect Meterpipe in Slab Underground Waterline Final UDFinal Gas Sewer Final Sewer Final Flatwork	A/P Number 25544374 Address 201 Mage Mage Mage Mage Mage Mage Mage Mage	January 13, 2020	Juan Antonio Santana J.A.S Builders	Project:	Property Legal Description:	A/P Number: Dear Juan:	You constructed your residential renov documents and ouidance menared by A	check the construction stated above for based on our experience, knowledge, ir with our construction documents and th	The following items were inspected an	 [X] A. Foundation [X] B. Framing [] C. Wall Bracing [] D. Energy Conservation (insulation, [] E. Fire Blocking/Draft Stopping, No 	As denoted by the engineering seal on as an engineer under the Texas Engine welfare in the practice of engineering/a responsibility for periodic observation If you have any questions, please call. Respectfully, Respectfully, Ermie G. Arredondo, P. E. SIGNED AND SEALED ELECTRONIC 2011 W Magnolia Deck doct
A/P Number_2554/374_Address_201 Address_201 Mage Address_201	A/P Number 255547374 Address 201 M Magnetic	A/P Number 255 4/37 L Address 201 M Magne Ma	January 13, 2020	Juan Antonio Santana J.A.S Builders	Project:	Property Legal Description:	A/P Number: Dear Juan:	You constructed your res documents and ouidance	check the construction str based on our experience, with our construction doc	The following items were	 [X] A. Foundation [X] B. Framing [] C. Wall Bracing [] D. Energy Conservatio [] E. Fire Blocking/Draft 	As denoted by the engineer under the welfare in the practice of responsibility for periodi. If you have any question: Respectfully, Respectfully, Emie G. Arredondo, P. ESIGNED AND SEALED.
Okay to insulate? Y / N Mechanical Electrical Plumbing Building Rough-in Rough-in (TOPS) Rough-in Top out (IRR) Foundation Frame UDFrame Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork	Okay to insulate? Y / N Mechanical Electrical Plumbing Building Rough-in Rough-in (TOPS) Rough-in Top out (IRR) Foundation Frame UDFrame Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork	Okay to insulate? Y / N Mechanical Electrical Plumbing Building Rough-in Rough-in (TOPS) Rough-in Top out (IRR) Foundation Frame UDFrame Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork				554	376	Address	201	11	N Magr	ACCREDITED Suiture Provenuer
Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork	Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork Gas Sewer Final	Final Final Reconnect Waterpipe in Slab Insulation Final UDFinal (TML) (CEE) Underground Waterline Tree Final Flatwork Gas Sewer Final		Mechani	ical	Electr	performed: rical		<u>P</u>	lumbi	ing	Okay to insulate? Y / N Building
					Fin	nal	Reconnect		Wat Underg	terpip round	e in Slab d Waterline	Insulation Final UDFinal



The summary above contains highlights of the official inspection record filed by the inspector. The official inspection record may be obtained by scanning the image on the right and entering your A/P Number or by contacting the Development Services Department at (210) 207-1111. *Partnering with our community to build and maintain a safer San Antonio* Rev. Oct 2018