HISTORIC AND DESIGN REVIEW COMMISSION

November 04, 2020

HDRC CASE NO: 2020-476

ADDRESS: 307 DELAWARE

LEGAL DESCRIPTION: NCB 3005 BLK 3 LOT S 125.69 FT OF 2

ZONING: R-6, H CITY COUNCIL DIST.:

DISTRICT: Lavaca Historic District **TYPE OF WORK:** Historic Tax Certification

APPLICATION RECEIVED: October 23, 2020

60-DAY REVIEW: Not applicable due to City Council Emergency Orders

CASE MANAGER: Rachel Rettaliata

REQUEST:

The applicant is requesting Historic Tax Certification for the property at 307 Delaware.

APPLICABLE CITATIONS:

UDC Section 35-618. Tax Exemption Qualification.

(d)Certification.

(1)Historic and Design Review Commission Certification. Upon receipt of the owner's sworn application the historic and design review commission shall make an investigation of the property and shall certify the facts to the city tax assessor-collector within thirty (30) days along with the historic and design review commission's documentation for recommendation of either approval or disapproval of the application for exemption.


FINDINGS:

- a. The primary structure located at 307 Delaware is a 1-story single family structure constructed in approximately 1920 in the Craftsman style. The home features a standing seam metal roof with a front jerkinhead detail, woodlap siding, original one-over-one wood windows, and an asymmetrical front porch. The home is contributing to the Lavaca Historic District. The applicant is requesting Historic Tax Certification.
- b. The scope of work includes foundation repairs, the construction of a rear addition, fence installation, new HVAC installation, plumbing repairs, bathroom repairs, and interior and exterior painting.
- c. The applicant has met all the requirements for Historic Tax Certification outlined in UDC Section 35-618 and has provided evidence to that effect to the Historic Preservation Officer.


RECOMMENDATION:

Staff recommends approval based on findings a through c.

City of San Antonio One Stop




User drawn lines



Imagery ©2020 Google, Imagery ©2020 CNES / Airbus, Maxar Technologies, Map data ©2020 100 ft L




Imagery ©2020 Google, Map data ©2020 , Map data ©2020 20 ft




Imagery ©2020 Google, Map data ©2020 , Map data ©2020

20 ft ∟



Imagery ©2020 Google, Map data ©2020 , Map data ©2020



Imagery ©2020 Google, Map data ©2020 , Map data ©2020

20 ft ∟

307 Delaware Itemized Cost for Rehabilitation and New Addition

Building Framing –
Building Insulation –
Building Sheetrock and Demo – \$
Building Plumbing, Hardware and Repairs
Building Electrical – (
Finish Carpentry –
Building Roofing –
Building Bathrooms and Repairs –
Building Foundation and Repairs – §
HVAC –
Prep and Paint Exterior –
Prep and Paint Interior –
Dumpster Legal Dump -
New Fence -

Plan Reviews/Permits/Inspections For An Address

Permits for address 307 DELAWARE

House Number:	307					
Street:	DELAWARE	Bldg/Suite:				Example: 2 or BLDG:2 or SUITE:201
	List Plan Reviews/Permits/Inspections For An Address				Reset	

Permit Number	Address	Contractor/Contacts	Completion Date	Status	Туре	Inspections	Reviews
2401575	307 DELAWARE	JOE WILBUR SA STRUCTURAL REPAIR SOLUTIONS ROBERT ARTHUR DESHAZER	09/20/2018	CLOSED	MISC NO REVIEW	Inspections	Reviews
2408943	307 DELAWARE	HLR RESTORATION RAFAEL L HINOJOSA	10/30/2019	CLOSED	MISC NO REVIEW	Inspections	Reviews
2408948	307 DELAWARE	HLR RESTORATION RAFAEL L HINOJOSA	11/12/2019	CLOSED	MISC NO REVIEW	Inspections	Reviews
2419744	307 DELAWARE	METRO ELECTRIC (ASK FOR PIN) METRO ELECTRIC JESSE PAEZ		OPEN	GENERL	Inspections	Reviews
<u>2464631</u>	307 DELAWARE	HLR RESTORATION RAFAEL L HINOJOSA	06/14/2019	CLOSED	RESIDENTIAL BLDG APPLICATION	Inspections	Reviews
<u>2500658</u>	307 DELAWARE	ISLAS HEATING & A/C ISLAS BROS MECHANICAL CIRILO V ISLAS	11/13/2019	CLOSED	MECHANICAL PERMIT APPLICATION	<u>Inspections</u>	Reviews
2510609	307 DELAWARE	ROBERT V ELIZARDO III	07/19/2019	CLOSED	MISC NO REVIEW	<u>Inspections</u>	Reviews
<u>2513660</u>	307 DELAWARE	ONE STAR ELECTRIC MARIO A GONZALEZ	08/01/2019	CLOSED	GENERL	Inspections	Reviews
<u>2526849</u>	307 DELAWARE	D. BALLEW DUSTIN A BALLEW	11/26/2019	CLOSED	RESIDENTIAL BLDG APPLICATION	Inspections	Reviews
2542118	307 DELAWARE	BATRES PLUMBING GERARDO PEREZ BATRES	12/06/2019	CLOSED	GENERALPLUMB	Inspections	Reviews

City of San Antonio

Development Services Department



Plan Reviews/Permits/Inspections For An Address Permits for address 307 DELAWARE

Permits for address 307 DELAWARI
House Number: 307


Street: DELAWARE Bldg/Suite: Example: 2 or BLDG:2 or SUITE:201


List Plan Reviews/Permits/Inspections For An Address Reset

Permit Number	Address	Contractor/Contacts	Completion Date	Status	Туре	Inspections	Reviews		
<u>2543465</u>	307 DELAWARE	ALL N 1 ELECTRIC MARCUS HINTON		OPEN	GENERL	Inspections	Reviews		
<u>1</u> 2									


Back Main Menu Dynamic Portal

SERVICES | BUSINESS IN SA | GOVERNMENT | VISITING SA COMMUNITY PORTAL HOME | CITY DISCLAIMER CONTACT CUSTOMER SERVICE






REMODEL PIER FOUNDATION PLAN




REMODEL ROOF PLAN





REMODEL FRONT ELEVATION

SCALE: 1/4" = 1'0"




SCALE 1/8" = 1'-0"






REMODEL LEFT-SIDE ELEVATION



REMODEL FLOOR PLAN



ROOM ADDITION AT 307 DELAWARE STREET SAN ANTONIO, TEXAS 78210

PARTIAL FLOOR PLAN

SCALE: 1/4" = 1'-0"









