



Houston 9191 Winkler Dr. Ste. A Houston, TX 77017 713.947.2422 (o) 713.947.0667 (f)

**Dallas / Ft. Worth** 214.484.9850

**San Antonio** 210.650.3951

*Corpus Christi* 361.929.6147

*Tyler* 903.426.3846

*Lubbock* 806.786.4603

*Tulsa* 918.622.2902

#### **Project Proposal**

To: Mack McKenzie

From: Seth Ortiz

**Date:** Sunday, February 21, 2021 Cost JOC # 2019-02-21-0134

Mr. McKenzie,

LMC Corporation respectfully submits our base proposal for the listed project. This proposal includes all labor, material, and equipment to perform the work described in this proposal and the following scope of work.

Preliminary Proposal Summary:

The estimated base proposal amount for this project is \$191,148.03

Breakdown of Project Costs:

 Construction Cost
 \$183,798.67

 Bonds
 \$ 7,349.37

 Total Project Cost
 \$191,148.03


Project location: Bob Ross Wellness

2219 Babcock Rd, 78229

Prepared by: Seth Ortiz Reviewed by: Zring Kareem

Seth Ortiz
Project Manager
(210) 818-8305
Seth.Ortiz@LMC-Corporation.com

Scope of work on the following pages





#### **Scope of Work**

# Demo Scope ~

- Demo & dispose of all 4,500 Sq Ft of Drywall
- Demo & dispose of 7,600 Sq Ft of LVT Tiles
- Demo & dispose Ceiling tiles in Billiards Room and Office that Shares walls.
- Demo & dispose 320 Sq Ft of Carpet Tiles

# Temporary Storage ~

• Provide Storage for Items that will need to be moved during duration of Mitigation.

# Specialties~

• Provide Dehumidifiers to extract all moisture out of the air in the building.

#### Paint Scope~

- Install 4,500 sq feet of Drywall and insulation.
- Paint to match existing walls. Prime and paint 11,000 Sq Feet of wall surface

# Flooring Scope~

- Provide and install matching existing LVT tiles 7,600 Sq Ft of LVT Tiles
- Provide and install floor prep and glue for LVT
- Provide & install new Cove Base

#### **Exclusions:**

- Sales Tax.
- Overtime/Afterhours/Weekend work.
- Any section or part thereof not specifically listed above.
- Any delays caused by unforeseen conditions.
- Furniture Replacement
- Further damage that was not visible during the walk.
- Any and all plumbing repairs
- Pool Table replacement